August 18, 2023

Pavement Photo Inspection Report

Town of China Grove

2023 Pavement Photo Inspection Report

KISINGER CAMPO & ASSOCIATES

Kisinger Campo & Associates, Corp.
305 S. Main Street
Kannapolis, NC 28081

Roger D. Jones, PE
rjones2@kcaeng.com
C: 336.240.1952

Town of China Grove - 2023 Pavement Photo Inspection Report

August 18, 2023

Prepared For:

Town of China Grove
333 N Main Street
China Grove, NC 28203

China Grove Manager: **Franklin D. Gover III**
China Grove GIS Planner: **Alana Sweatt**

China Grove Town Council:

Charles Seaford, Mayor
Arthur Heggins, Mayor Pro Tem
Don Bringle
Rodney Phillip
Cheryl Sheets
Steve Stroud

Prepared By:

Kisinger Campo & Associates, Corp.
305 S Main Street
Kannapolis, NC 28081

KCA Project Number: 005-202318.00

Engineer of Record: **Roger D. Jones, PE**
Database Management: **David Hubert**
Pavement Inspection: **Roger Jones, PE**
Cody Harward, EI
Cody Funderburk

NORTH CAROLINA PROFESSIONAL SEAL 032092 ENGINEER ROGER D. JONES

8/18/2023

Roger D. Jones, PE
North Carolina Registration 032092

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	1 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	1ST AV	1ST AV	2	626	15

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WALNUT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,500	7a869c0c8c654402bb0b25d83bedc5e6	CENTRAL AV	SECT PCI 49.2	SECT SCI 78.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 47	SAMP SCI 57

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	110	SQFT
3	BLOCK CR	L	192	SQFT
7	EDGE CR	L	46	FT
9	LANE SH DROP	L	24	FT
10	L & T CR	L	21	FT
19	RAVELING	M	92	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	2 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	1ST AV	1ST AV	2	626	15

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WALNUT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,500	7a869c0c8c654402bb0b25d83bedc5e6	CENTRAL AV	SECT PCI 49.2	SECT SCI 78.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 51	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	195	SQFT
10	L & T CR	L	46	FT
11	PATCH/UT CUT	L	336	SQFT
19	RAVELING	H	74	SQFT
19	RAVELING	M	24	SQFT
20	WEATHERING	M	1,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	3 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	1ST AV	1ST AV	2	1,088	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	CENTRAL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	ac21ded4b741479db5a665d03cc80a02	WALNUT ST	SECT PCI 36	SECT SCI 49

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 32	SAMP SCI 42

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	135	SQFT
3	BLOCK CR	L	121	SQFT
4	BUMPS/SAGS	M	5	FT
10	L & T CR	L	127	FT
12	POLISHED AG		1,000	SQFT
18	SWELL	L	400	SQFT
19	RAVELING	H	69	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	4 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	1ST AV	1ST AV	2	1,088	18
	SECTION ID: 020	BRANCH FROM: CENTRAL AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,800	SUNIQUEID: ac21ded4b741479db5a665d03cc80a02	BRANCH TO: WALNUT ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 36		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 49

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 40

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 56

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	84	SQFT
10	L & T CR	L	116	FT
11	PATCH/UT CUT	L	270	SQFT
15	RUTTING	M	180	SQFT
19	RAVELING	M	259	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	5 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	2ND AV	2ND AV	2	973	16

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S US 29 HWY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,600	7091b928ce9a4461b778359520df5321	WALNUT ST	SECT PCI 38.3	SECT SCI 83.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 28	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	H	416	SQFT
3	BLOCK CR	L	600	SQFT
3	BLOCK CR	M	520	SQFT
7	EDGE CR	M	60	FT
9	LANE SH DROP	H	19	FT
19	RAVELING	H	72	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	6 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	2ND AV	2ND AV	2	973	16

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S US 29 HWY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,600	7091b928ce9a4461b778359520df5321	WALNUT ST	SECT PCI 38.3	SECT SCI 83.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 48	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	104	SQFT
3	BLOCK CR	L	112	SQFT
6	DEPRESSION	L	48	SQFT
10	L & T CR	L	103	FT
13	POTHOLE	L	1	COUNT
19	RAVELING	H	59	SQFT
19	RAVELING	M	24	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	7 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	2ND AV	2ND AV	2	964	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	ELM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	f18a77e04fae4bb2b96c8ae636d47f2f	WALNUT ST	SECT PCI 15.9	SECT SCI 29.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 5	SAMP SCI 13

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	292	SQFT
10	L & T CR	L	140	FT
11	PATCH/UT CUT	L	9	SQFT
13	POTHOLE	L	3	COUNT
15	RUTTING	M	400	SQFT
19	RAVELING	H	51	SQFT
20	WEATHERING	H	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	8 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	2ND AV	2ND AV	2	964	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	ELM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	f18a77e04fae4bb2b96c8ae636d47f2f	WALNUT ST	SECT PCI 15.9	SECT SCI 29.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 27	SAMP SCI 46

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	264	SQFT
3	BLOCK CR	L	185	SQFT
10	L & T CR	L	38	FT
11	PATCH/UT CUT	L	104	SQFT
13	POTHOLE	L	2	COUNT
19	RAVELING	M	120	SQFT
20	WEATHERING	H	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	9 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	3RD AV	3RD AV	2	470	16

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	BOSTIAN RD/ELM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,600	1695f7e83fe840bf9164d165c5874bf6	POPLAR ST	SECT PCI 48.1	SECT SCI 65

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 48	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	60	SQFT
3	BLOCK CR	L	338	SQFT
7	EDGE CR	M	27	FT
10	L & T CR	L	101	FT
19	RAVELING	H	31	SQFT
20	WEATHERING	M	1,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	10 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	3RD AV	3RD AV	2	322	16
	SECTION ID: 020	BRANCH FROM: POPLAR ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,600	SUNIQUEID: d94e32eedb5747ec8f849a054bc629eb	BRANCH TO: WALNUT ST/WALNUT ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 38.6	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 64.5	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 39	SAMP SCI 64

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	6	SQFT
1	ALLIGATOR CR	M	34	SQFT
3	BLOCK CR	L	120	SQFT
7	EDGE CR	M	118	FT
10	L & T CR	L	123	FT
19	RAVELING	H	78	SQFT
20	WEATHERING	L	1,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	11 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	3RD AV	3RD AV	2	337	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	ROBERTS ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	54366c2a3a7d45609845a21a25c03610	COLUMBUS ST	SECT PCI 66.1	SECT SCI 76.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 76

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	20	SQFT
10	L & T CR	L	134	FT
10	L & T CR	M	22	FT
11	PATCH/UT CUT	L	17	SQFT
13	POTHOLE	L	2	COUNT
20	WEATHERING	L	1,700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	12 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	3RD AV	3RD AV	2	584	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	WALNUT ST/WALNUT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	8efc8a8bab424f84a9a073aa36841ce3	ROBERTS ST	SECT PCI 53.9	SECT SCI 87

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 54	SAMP SCI 87

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	140	SQFT
6	DEPRESSION	L	112	SQFT
7	EDGE CR	M	53	FT
10	L & T CR	L	100	FT
19	RAVELING	H	102	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	13 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	AMHERST CT	AMHERST CT	2	535	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DOTS CIR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	8bcf20af7bc24d9fb4e86d7411682fd7	CUL-DE-SAC	SECT PCI 74.2	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 74	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	577	SQFT
10	L & T CR	L	212	FT
20	WEATHERING	M	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	14 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ARBOR DR	ARBOR DR	2	955	27
	SECTION ID: 010	BRANCH FROM: W HILLSIDE DR	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,700	SUNIQUEID: 2b047e2dfd5b476db91d4a25453ad40f	BRANCH TO: SHUE RD	SECTION PAVEMENT CONDITION INDEX: SECT PCI 56.9		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 63.2

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 65

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 72

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	M	31	SQFT
6	DEPRESSION	M	12	SQFT
10	L & T CR	L	223	FT
11	PATCH/UT CUT	H	63	SQFT
11	PATCH/UT CUT	L	72	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	15 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	ARBOR DR	ARBOR DR	2	955	27

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	W HILLSIDE DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,700	2b047e2dfd5b476db91d4a25453ad40f	SHUE RD	SECT PCI 56.9	SECT SCI 63.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 48	SAMP SCI 54

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	798	SQFT
7	EDGE CR	L	18	FT
10	L & T CR	L	27	FT
19	RAVELING	H	2	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	16 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	AZALEA LN	AZALEA LN	2	401	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	ELIZABETH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	a651a2090c234782be8be9b71322c381	DOTS CIR	SECT PCI 15.4	SECT SCI 32.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 15	SAMP SCI 32

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	400	SQFT
3	BLOCK CR	H	1,200	SQFT
3	BLOCK CR	M	400	SQFT
10	L & T CR	L	20	FT
10	L & T CR	M	70	FT
11	PATCH/UT CUT	H	12	SQFT
20	WEATHERING	M	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	17 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	AZALEA LN	AZALEA LN	2	304	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	DOTS CIR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	e0ad2eb492e24fd58b47f99686e633c2	CUL-DE-SAC	SECT PCI 41.9	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 42	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	1,018	SQFT
10	L & T CR	M	193	FT
20	WEATHERING	H	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	18 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	BARCLAY CT	BARCLAY CT	2	295	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DOTS CIR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	2a39f580247a400c9cbb7bd734727a8a	CUL-DE-SAC	SECT PCI 77.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	95	SQFT
10	L & T CR	L	171	FT
11	PATCH/UT CUT	L	50	SQFT
20	WEATHERING	M	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	19 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	BARE ST	BARE ST	2	199	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N US 29 HWY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	a74b022ea7dc4c9d8d93a8fd6523fd78	DEAD END	SECT PCI 70.3	SECT SCI 81.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 82

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	188	FT
13	POTHOLE	L	2	COUNT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	20 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	BRRYBETHCR	BERRYBETH CIR	2	681	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GOOSEBERRY TR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	654533ce0a594e62b7eaa3798ecfa9d1	DAMSENBERRY WAY	SECT PCI 93.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 98	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
19	RAVELING	L	25	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	21 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	BRRYBETHCR	BERRYBETH CIR	2	681	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GOOSEBERRY TR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	654533ce0a594e62b7eaa3798ecfa9d1	DAMSENBERRY WAY	SECT PCI 93.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 89	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
19	RAVELING	L	888	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	22 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	BRRYBETHCR	BERRYBETH CIR	2	898	24
	SECTION ID: 030	BRANCH FROM: DAMSENBERRY WAY	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,400	SUNIQUEID: a78966ee597c47d9bde2b02914489fb4	BRANCH TO: GOOSEBERRY TR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 98.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 99

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
11	PATCH/UT CUT	L	15	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	23 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	BRRYBETHCR	BERRYBETH CIR	2	898	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	DAMSENBERRY WAY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	a78966ee597c47d9bde2b02914489fb4	GOOSEBERRY TR	SECT PCI 98.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 99	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
11	PATCH/UT CUT	L	11	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	24 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	BIRCH CT	BIRCH CT	2	191	23
	SECTION ID: 010	BRANCH FROM: WALNUT ST EX	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 0a24377ea0704dc58b402bfb07ae1808	BRANCH TO: CUL-DE-SAC	SECTION PAVEMENT CONDITION INDEX: SECT PCI 77.5	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 78	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	275	SQFT
10	L & T CR	L	146	FT
20	WEATHERING	M	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	25 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	BLKWLDERST	BLACKWELDER ST	2	959	26
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	010	CUL-DE-SAC			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,600	152d190b6ca2444598ef618dc15992b6	S BOSTIAN ST	SECT PCI 53.6	SECT SCI 58.9	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 80	SAMP SCI 90

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	21	SQFT
3	BLOCK CR	L	307	SQFT
10	L & T CR	L	144	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	26 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	BLKWLDERST	BLACKWELDER ST	2	959	26
	SECTION ID: 010	BRANCH FROM: CUL-DE-SAC	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 152d190b6ca2444598ef618dc15992b6	BRANCH TO: S BOSTIAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 53.6	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 58.9	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 27	SAMP SCI 28

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	500	SQFT
6	DEPRESSION	L	77	SQFT
10	L & T CR	L	184	FT
15	RUTTING	H	125	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	27 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	CEDAR ST	CEDAR ST	2	444	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	PATTERSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8016d4e0080c40a3b917bd977418e344	W FIRST ST	SECT PCI 73.7	SECT SCI 85.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 74	SAMP SCI 85

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	520	SQFT
10	L & T CR	L	85	FT
11	PATCH/UT CUT	L	138	SQFT
11	PATCH/UT CUT	M	56	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	28 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	CEDAR ST	CEDAR ST	2	434	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W FIRST ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	a0a601a450e1433abbfd28113e8c2db2	STEVENS ST	SECT PCI 48.4	SECT SCI 66.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	100	FT
10	L & T CR	L	191	FT
20	WEATHERING	L	1,800	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	29 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	CEDAR ST	CEDAR ST	2	434	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W FIRST ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	a0a601a450e1433abbfd28113e8c2db2	STEVENS ST	SECT PCI 48.4	SECT SCI 66.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 18	SAMP SCI 34

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	180	SQFT
3	BLOCK CR	M	1,600	SQFT
15	RUTTING	H	88	SQFT
19	RAVELING	H	15	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	30 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CEDAR ST	CEDAR ST	2	216	26
	SECTION ID: 030	BRANCH FROM: STEVENS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 4f4d3dc1ec5249c2a596e8f6de0f31a8	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 25.4		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 41.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 25	SAMP SCI 42

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	240	SQFT
3	BLOCK CR	M	2,360	SQFT
6	DEPRESSION	H	24	SQFT
11	PATCH/UT CUT	M	18	SQFT
15	RUTTING	M	72	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	31 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CENTRAL AV	CENTRAL AV	2	254	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CHERRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	3a394645f18b4948bfdc654b9516e91c	1ST AV	SECT PCI 92.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	29	FT
20	WEATHERING	L	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	32 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	CENTRAL AV	CENTRAL AV	2	391	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	1ST AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	86a4ca9eb1de478fba13246941394d07	WALNUT ST	SECT PCI 84.6	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 85	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	6	FT
10	L & T CR	L	109	FT
20	WEATHERING	L	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	33 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CENTRAL AV	CENTRAL AV	2	340	21

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	WALNUT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,100	143f5fb72bd347189ff2288a2fe015e2	FRONT ST	SECT PCI 93.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	19	FT
20	WEATHERING	L	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	34 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	CENTRAL AV	CENTRAL AV	2	971	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	FRONT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	4b1915c7566f47f3851944deabe5400a	1ST AV	SECT PCI 92.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 85	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	M	126	FT
10	L & T CR	L	36	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	35 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	CENTRAL AV	CENTRAL AV	2	971	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	FRONT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	4b1915c7566f47f3851944deabe5400a	1ST AV	SECT PCI 92.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 100	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	4	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	36 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	CENTRAL AV	CENTRAL AV	2	138	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	1ST AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	fdc0da576f9849eeb3fc82ec23ce0d16	ELM ST	SECT PCI 90.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 91	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	65	FT
20	WEATHERING	L	2,000	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	37 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CHAPEL ST	CHAPEL ST	2	898	26
	SECTION ID: 010	BRANCH FROM: CUL-DE-SAC	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 846d47a0711c467f92a35cf8a3255c98	BRANCH TO: S BOSTIAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 17.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 21

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 8

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 10

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	300	SQFT
3	BLOCK CR	M	517	SQFT
6	DEPRESSION	M	148	SQFT
11	PATCH/UT CUT	H	156	SQFT
11	PATCH/UT CUT	M	2,217	SQFT
19	RAVELING	H	100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	38 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	CHAPEL ST	CHAPEL ST	2	898	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CUL-DE-SAC	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	846d47a0711c467f92a35cf8a3255c98	S BOSTIAN ST	SECT PCI 17.8	SECT SCI 21

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 28	SAMP SCI 32

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	590	SQFT
3	BLOCK CR	M	287	SQFT
4	BUMPS/SAGS	M	9	FT
6	DEPRESSION	M	161	SQFT
10	L & T CR	L	159	FT
11	PATCH/UT CUT	M	238	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	39 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	CHERRY ST	CHERRY ST	2	526	16

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E THOM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,600	c37068c5c9d34a56a0bca23893f1d8fe	ROSE AV	SECT PCI 36.2	SECT SCI 61.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 36	SAMP SCI 61

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	82	SQFT
3	BLOCK CR	L	125	SQFT
7	EDGE CR	L	85	FT
10	L & T CR	L	102	FT
10	L & T CR	M	13	FT
19	RAVELING	M	269	SQFT
20	WEATHERING	H	800	SQFT
20	WEATHERING	M	800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	40 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CHERRY ST	CHERRY ST	2	394	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	ROSE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	fabc938028d846e3849c6a2415082018	CENTRAL AV	SECT PCI 92.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	57	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	41 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CHNABERYDR	CHINABERRY DR	2	794	22
	SECTION ID: 010	BRANCH FROM: CUL-DE-SAC	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,200	SUNIQUEID: 07a3522e60a94e8b918dc324324a67f9	BRANCH TO: S BOSTIAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 42.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 53.3

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 33

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 46

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	1,800	SQFT
20	WEATHERING	L	2,200	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	42 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	CHNABERYDR	CHINABERRY DR	2	794	22

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CUL-DE-SAC	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,200	07a3522e60a94e8b918dc324324a67f9	S BOSTIAN ST	SECT PCI 42.1	SECT SCI 53.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 52	SAMP SCI 61

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	400	SQFT
3	BLOCK CR	L	1,202	SQFT
20	WEATHERING	M	2,200	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	43 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	CHNABERYLN	CHINABERRY LN	2	376	26
	SECTION ID: 010	BRANCH FROM: PATTERSON ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 1063a2fbd35c4c68b4de55727b1150ed	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 40.8	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 91.7	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 41

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 92

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	2,300	SQFT
11	PATCH/UT CUT	L	130	SQFT
11	PATCH/UT CUT	M	20	SQFT
20	WEATHERING	H	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	44 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	COLUMBUSST	COLUMBUS ST	2	372	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S US 29 HWY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	16bcd81ea4ed4104aa2f3ff91cb6602e	3RD AV	SECT PCI 55.2	SECT SCI 61.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 62

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	75	SQFT
3	BLOCK CR	M	93	SQFT
10	L & T CR	L	34	FT
13	POTHOLE	L	1	COUNT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	45 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	COLUMBUSST	COLUMBUS ST	2	480	15

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	3RD AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,500	c8da09f5ff514e44881aae77131a2bab	DEAD END	SECT PCI 16.1	SECT SCI 22.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 16	SAMP SCI 22

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	219	SQFT
3	BLOCK CR	L	44	SQFT
7	EDGE CR	L	11	FT
15	RUTTING	H	148	SQFT
15	RUTTING	L	50	SQFT
19	RAVELING	M	308	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	46 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	COVE LN	COVE LN	2	859	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	MITCHELL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	bf202ebd9adc46e88f4d28420cb9d322	CUL-DE-SAC	SECT PCI 71.4	SECT SCI 75.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 72	SAMP SCI 76

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	137	SQFT
3	BLOCK CR	L	433	SQFT
10	L & T CR	L	99	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	47 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	COVE LN	COVE LN	2	859	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	MITCHELL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
8	bf202ebd9adc46e88f4d28420cb9d322	CUL-DE-SAC	SECT PCI 71.4	SECT SCI 75.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 25	SAMP SCI 39

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	667	SQFT
7	EDGE CR	L	88	FT
10	L & T CR	L	152	FT
10	L & T CR	M	28	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	48 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	DMSNBERYW	DAMSENBERRY WAY	2	556	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GOOSEBERRY TR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	f2160a58b08342a286e517cab05609c5	BERRYBETH CIR	SECT PCI 98.6	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 99	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	19	SQFT
19	RAVELING	L	15	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	49 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	DOTS CIR	DOTS CIR	2	394	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	AZALEA LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	cc787aa126644f37a1e92da21b8404ec	BARCLAY CT	SECT PCI 54.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	2,553	SQFT
10	L & T CR	L	91	FT
20	WEATHERING	M	2,900	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	50 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	DOTS CIR	DOTS CIR	2	406	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	BARCLAY CT	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	acc3691bacab4ca2a081fa136eabc35e	AMHERST CT	SECT PCI 55.1	SECT SCI 71.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 72

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	1,300	SQFT
10	L & T CR	L	70	FT
11	PATCH/UT CUT	H	51	SQFT
11	PATCH/UT CUT	M	68	SQFT
18	SWELL	M	28	SQFT
20	WEATHERING	M	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	51 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	DOTS CIR	DOTS CIR	2	238	27

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	AMHERST CT	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,700	5c18348fc9ea40a5adb4de755ac1a994	PARK ST	SECT PCI 52	SECT SCI 66.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 52	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	300	SQFT
3	BLOCK CR	L	1,719	SQFT
10	L & T CR	L	92	FT
11	PATCH/UT CUT	L	34	SQFT
20	WEATHERING	M	2,700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	52 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	DOTS CIR	DOTS CIR	2	623	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	PARK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	ad10624886ed4a6484be424d6b832c34	W KETCHIE ST	SECT PCI 82.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 81	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	12	FT
10	L & T CR	L	42	FT
20	WEATHERING	M	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	53 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	DOTS CIR	DOTS CIR	2	623	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	PARK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	ad10624886ed4a6484be424d6b832c34	W KETCHIE ST	SECT PCI 82.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 83	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	70	FT
20	WEATHERING	M	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	54 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ECENTRVWST	E CENTERVIEW ST	2	615	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST/S MAIN ST/W	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	280be62e3abf4a25a8b9eff19bbe9267	N BOSTIAN ST/S BOSTIA	SECT PCI 87.5	SECT SCI 99.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 84	SAMP SCI 97

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	138	FT
17	SLIPPAGE CR	L	12	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	55 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	ECENTRVWST	E CENTERVIEW ST	2	615	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST/S MAIN ST/W	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	280be62e3abf4a25a8b9eff19bbe9267	N BOSTIAN ST/S BOSTIA	SECT PCI 87.5	SECT SCI 99.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 86	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	115	FT
10	L & T CR	M	5	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	56 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
11	ECENTRVWST	E CENTERVIEW ST	2	615	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST/S MAIN ST/W	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	280be62e3abf4a25a8b9eff19bbe9267	N BOSTIAN ST/S BOSTIA	SECT PCI 87.5	SECT SCI 99.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	6	SQFT
10	L & T CR	L	17	FT
20	WEATHERING	L	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	57 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ECENTRVWST	E CENTERVIEW ST	2	427	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	N BOSTIAN ST/S BOSTIA	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	21ec9edb762a408d931a72d2b19d240f	BROOKWOOD CIR	SECT PCI 87.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 87	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	24	FT
20	WEATHERING	M	1,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	58 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ECENTRVWST	E CENTERVIEW ST	2	895	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	BROOKWOOD CIR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	97adbd28e7d44ccaab563dbc7d59983e	N US 29 HWY/S US 29 H	SECT PCI 91.6	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 86	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	185	FT
11	PATCH/UT CUT	L	70	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	59 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	ECENTRVWST	E CENTERVIEW ST	2	895	31
	SECTION ID: 030	BRANCH FROM: BROOKWOOD CIR	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,100	SUNIQUEID: 97adbd28e7d44ccaab563dbc7d59983e	BRANCH TO: N US 29 HWY/S US 29 H	SECTION PAVEMENT CONDITION INDEX: SECT PCI 91.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 97	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	41	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	60 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	EKETCHIEST	E KETCHIE ST	2	369	26
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	010	N HARRIS ST			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,600	222bc3500606430984831c7e47b1b78f	N BOSTIAN ST	SECT PCI 18.5	SECT SCI 21.7	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 19	SAMP SCI 22

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	557	SQFT
6	DEPRESSION	M	8	SQFT
7	EDGE CR	M	67	FT
10	L & T CR	L	112	FT
10	L & T CR	M	45	FT
15	RUTTING	H	243	SQFT
19	RAVELING	H	40	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	61 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	EKETCHIEST	E KETCHIE ST	2	1,321	22
	SECTION ID: 020	BRANCH FROM: N BOSTIAN ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,200	SUNIQUEID: 620ab4bd76814277a3feb569cc3cd920	BRANCH TO: N US 29 HWY	SECTION PAVEMENT CONDITION INDEX: SECT PCI 27.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 35.5

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 25

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
4	BUMPS/SAGS	M	15	FT
10	L & T CR	L	120	FT
11	PATCH/UT CUT	H	280	SQFT
11	PATCH/UT CUT	M	84	SQFT
20	WEATHERING	H	2,200	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	62 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	EKETCHIEST	E KETCHIE ST	2	1,321	22
	SECTION ID: 020	BRANCH FROM: N BOSTIAN ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,200	SUNIQUEID: 620ab4bd76814277a3feb569cc3cd920	BRANCH TO: N US 29 HWY	SECTION PAVEMENT CONDITION INDEX: SECT PCI 27.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 35.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 23	SAMP SCI 24

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	400	SQFT
3	BLOCK CR	L	180	SQFT
10	L & T CR	L	110	FT
13	POTHOLE	L	1	COUNT
15	RUTTING	M	162	SQFT
20	WEATHERING	M	2,200	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	63 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
10	EKETCHIEST	E KETCHIE ST	2	1,321	22
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	020	N BOSTIAN ST			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,200	620ab4bd76814277a3feb569cc3cd920	N US 29 HWY	SECT PCI 27.6	SECT SCI 35.5	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	1,176	SQFT
11	PATCH/UT CUT	L	294	SQFT
15	RUTTING	H	208	SQFT
19	RAVELING	M	20	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	64 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIBERTYST	E LIBERTY ST	2	352	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST/W LIBERTY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	1f88e1b0653a437abf533d52598e4a85	KLONDALE ST	SECT PCI 30.9	SECT SCI 40.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 31	SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	44	SQFT
1	ALLIGATOR CR	M	231	SQFT
3	BLOCK CR	M	500	SQFT
10	L & T CR	L	235	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	65 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIBERTYST	E LIBERTY ST	2	359	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	KLONDALE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	9ca37b40022f43128e9c388bcca8636e	SALISBURY ST	SECT PCI 63.3	SECT SCI 81.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 63	SAMP SCI 82

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	65	SQFT
3	BLOCK CR	L	70	SQFT
10	L & T CR	L	440	FT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	66 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIBERTYST	E LIBERTY ST	2	237	26
	SECTION ID: 030	BRANCH FROM: N HARRIS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 714150d08d7848199ae70b8344d73541	BRANCH TO: RAILROAD AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 87.4	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 87

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	168	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	67 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	ELIBERTYST	E LIBERTY ST	2	196	26
	SECTION ID: 040	BRANCH FROM: RAILROAD AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 71957654b7c84038b3a1d9d05bed2503	BRANCH TO: N BOSTIAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 87.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 88

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	164	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	68 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIBERTYST	E LIBERTY ST	2	302	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	N BOSTIAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	2762e648e2c14751820233f4d88bb47e	N US 29 HWY	SECT PCI 66.8	SECT SCI 70.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 67	SAMP SCI 71

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	113	FT
11	PATCH/UT CUT	L	50	SQFT
15	RUTTING	M	79	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	69 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	ELIBERTYST	E LIBERTY ST	2	89	32

SECTION ID	BRANCH FROM	SECTION COMMENTS
070	N US 29 HWY	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,848	0d6b012ed464425eadd30220c6f9e184	POWER ST	SECT PCI 24.3	SECT SCI 38.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 24	SAMP SCI 39

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	80	SQFT
1	ALLIGATOR CR	M	156	SQFT
3	BLOCK CR	H	840	SQFT
17	SLIPPAGE CR	M	35	SQFT
20	WEATHERING	L	2,840	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	70 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	E VANCE ST	E VANCE ST	2	468	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST/W VANCE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	17126334964d4d3db15bfe053f919b87	SALISBURY ST	SECT PCI 58.4	SECT SCI 81.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 81

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	20	SQFT
10	L & T CR	L	400	FT
11	PATCH/UT CUT	L	370	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	71 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	ELIZBETHST	ELIZABETH ST	2	596	26
	SECTION ID: 010	BRANCH FROM: PATTERSON ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 7a8e461d144f46dbb708d0a10f54f01f	BRANCH TO: AZALEA LN	SECTION PAVEMENT CONDITION INDEX: SECT PCI 60.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 74

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 60

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 74

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	148	SQFT
10	L & T CR	L	175	FT
10	L & T CR	M	125	FT
19	RAVELING	L	10	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	72 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIZBETHST	ELIZABETH ST	2	917	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	AZALEA LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	7c2bf50aca674b5aae9c1a9f8a364fcc	PARK ST	SECT PCI 37.6	SECT SCI 84.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 36	SAMP SCI 74

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	40	SQFT
3	BLOCK CR	M	1,528	SQFT
10	L & T CR	M	63	FT
13	POTHOLE	L	1	COUNT
20	WEATHERING	H	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	73 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	ELIZBETHST	ELIZABETH ST	2	917	29

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	AZALEA LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,900	7c2bf50aca674b5aae9c1a9f8a364fcc	PARK ST	SECT PCI 37.6	SECT SCI 84.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 39	SAMP SCI 95

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	1,200	SQFT
10	L & T CR	L	50	FT
10	L & T CR	M	170	FT
11	PATCH/UT CUT	M	7	SQFT
20	WEATHERING	H	2,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	74 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELIZBETHST	ELIZABETH ST	2	608	18
	SECTION ID: 030	BRANCH FROM: PARK ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,800	SUNIQUEID: 907983a4b2144d1787d95d3c6393f37a	BRANCH TO: W KETCHIE ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 75.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 78

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	131	FT
19	RAVELING	L	87	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	75 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	ELIZBETHST	ELIZABETH ST	2	608	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	PARK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	907983a4b2144d1787d95d3c6393f37a	W KETCHIE ST	SECT PCI 75.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 73	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	61	SQFT
10	L & T CR	L	236	FT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	76 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ELM ST	ELM ST	2	363	16
	SECTION ID: 010	BRANCH FROM: CENTRAL AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 1,600	SUNIQUEID: d479a89d062b4c5ebb7c7bf9a2ea5088	BRANCH TO: 2ND AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 28.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 29

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
4	BUMPS/SAGS	M	110	FT
7	EDGE CR	M	170	FT
9	LANE SH DROP	L	30	FT
10	L & T CR	L	104	FT
11	PATCH/UT CUT	L	66	SQFT
20	WEATHERING	H	30	SQFT
20	WEATHERING	M	1,570	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	77 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ELM ST	ELM ST	2	331	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	2ND AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	6025fe6de86345b5a5329e3288d3a18b	3RD AV/BOSTIAN RD	SECT PCI 35.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 36	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
4	BUMPS/SAGS	L	60	FT
7	EDGE CR	H	100	FT
10	L & T CR	L	115	FT
12	POLISHED AG		1,700	SQFT
19	RAVELING	H	144	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	78 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	FRONT ST	FRONT ST	2	371	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CENTRAL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	c1d1d092a0984cbda6b54511eae2df7c	PARKING LOT	SECT PCI 2.6	SECT SCI 8.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 3	SAMP SCI 9

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	931	SQFT
3	BLOCK CR	M	328	SQFT
4	BUMPS/SAGS	M	15	FT
15	RUTTING	H	372	SQFT
19	RAVELING	H	135	SQFT
20	WEATHERING	H	2,400	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	79 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	GROVE ST	GROVE ST	2	645	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	POWER ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	219cd164607d43df9edee7136a3d02c9	HEGLAR ST	SECT PCI 73.3	SECT SCI 81.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 86

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	35	SQFT
3	BLOCK CR	L	24	SQFT
10	L & T CR	L	292	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	80 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	GROVE ST	GROVE ST	2	645	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	POWER ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	219cd164607d43df9edee7136a3d02c9	HEGLAR ST	SECT PCI 73.3	SECT SCI 81.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 76

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	84	SQFT
3	BLOCK CR	L	35	SQFT
10	L & T CR	L	148	FT
10	L & T CR	M	21	FT
11	PATCH/UT CUT	M	40	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	81 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HANEY ST	HANEY ST	2	713	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	6e223b2200494cfe833419bb0c2c5ce5	LILLIAN ST	SECT PCI 36.7	SECT SCI 46.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 45

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	122	SQFT
3	BLOCK CR	L	96	SQFT
10	L & T CR	L	180	FT
11	PATCH/UT CUT	M	22	SQFT
15	RUTTING	H	60	SQFT
19	RAVELING	H	47	SQFT
20	WEATHERING	M	400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	82 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	HANEY ST	HANEY ST	2	713	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	6e223b2200494cfe833419bb0c2c5ce5	LILLIAN ST	SECT PCI 36.7	SECT SCI 46.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 38	SAMP SCI 48

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	132	SQFT
3	BLOCK CR	L	2,300	SQFT
11	PATCH/UT CUT	H	40	SQFT
15	RUTTING	H	52	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	83 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HANEY ST	HANEY ST	2	439	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	LILLIAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	a541e4858bc24527ab01475d81f8bebd	S BOSTIAN ST	SECT PCI 45.2	SECT SCI 65.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 45	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	18	SQFT
3	BLOCK CR	L	128	SQFT
10	L & T CR	L	269	FT
10	L & T CR	M	132	FT
11	PATCH/UT CUT	H	99	SQFT
20	WEATHERING	H	500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	84 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	HARRY ST	HARRY ST	2	474	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	WESTSIDE CIR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	6e1bf22b791a48dabd587a6ef006def0	CORRELL ST	SECT PCI 34.5	SECT SCI 56.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 56

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	984	SQFT
6	DEPRESSION	L	267	SQFT
9	LANE SH DROP	L	68	FT
10	L & T CR	L	30	FT
11	PATCH/UT CUT	H	80	SQFT
11	PATCH/UT CUT	L	36	SQFT
11	PATCH/UT CUT	M	12	SQFT
20	WEATHERING	M	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	85 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HARRY ST	HARRY ST	2	473	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	CORRELL ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	a205e4a23ec34d2e938c59fdd2f2bcc0	KIRK ST	SECT PCI 55.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	1,502	SQFT
10	L & T CR	L	22	FT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	86 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HCKRYGRVLN	HICKORY GROVE LN	2	243	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	b666dfba6ae94086b1b0b67cb6fc999f	W HILLSIDE DR	SECT PCI 58.1	SECT SCI 62.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 62

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	324	SQFT
3	BLOCK CR	L	236	SQFT
10	L & T CR	L	81	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	87 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	HCKRYGRVLN	HICKORY GROVE LN	2	945	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W HILLSIDE DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	74ae8c98052142b6974ec1081fb1b451	SHUE RD	SECT PCI 49.6	SECT SCI 61.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 38	SAMP SCI 53

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	200	SQFT
3	BLOCK CR	M	1,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	88 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	HCKRYGRVLN	HICKORY GROVE LN	2	945	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W HILLSIDE DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	74ae8c98052142b6974ec1081fb1b451	SHUE RD	SECT PCI 49.6	SECT SCI 61.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 61	SAMP SCI 70

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	127	SQFT
3	BLOCK CR	L	724	SQFT
10	L & T CR	L	35	FT
15	RUTTING	L	48	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	89 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HCKRYNUTLN	HICKORY NUT LN	2	711	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WILSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	d8545cd4d425445e85dbfeababecc877	LAUREL ST	SECT PCI 85.1	SECT SCI 95.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 83	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	19	SQFT
10	L & T CR	L	182	FT
11	PATCH/UT CUT	L	84	SQFT
20	WEATHERING	L	400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	90 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	HCKRYNUTLN	HICKORY NUT LN	2	711	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WILSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	d8545cd4d425445e85dbfeababecc877	LAUREL ST	SECT PCI 85.1	SECT SCI 95.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 87	SAMP SCI 92

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	125	FT
17	SLIPPAGE CR	L	50	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	91 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HCKRYNUTLN	HICKORY NUT LN	2	247	28
	SECTION ID: 020	BRANCH FROM: LAUREL ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,800	SUNIQUEID: 62f394b498b549b3bfa44967 1748315d	BRANCH TO: CUL-DE-SAC	SECTION PAVEMENT CONDITION INDEX: SECT PCI 82.3		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 93.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 82	SAMP SCI 93

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	12	SQFT
7	EDGE CR	L	119	FT
10	L & T CR	L	125	FT
10	L & T CR	M	27	FT
11	PATCH/UT CUT	L	52	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	92 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	HIGLNDRGDR	HIGHLAND RIDGE DR	2	146	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CUL-DE-SAC	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	61273d5f866f4068acfe97de4234fd7c	W STOKES ST	SECT PCI 64	SECT SCI 68

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 64	SAMP SCI 68

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	66	SQFT
10	L & T CR	L	112	FT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	93 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	HIGLNDRGDR	HIGHLAND RIDGE DR	2	463	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W STOKES ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	a27e4203b75c4b03a462db0024db32d6	LAUREN GLEN DR	SECT PCI 43.9	SECT SCI 49.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 44	SAMP SCI 50

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	306	SQFT
7	EDGE CR	L	51	FT
10	L & T CR	L	44	FT
20	WEATHERING	L	2,300	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	94 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	HIGLNDRGDR	HIGHLAND RIDGE DR	2	405	23
	SECTION ID: 030	BRANCH FROM: LAUREN GLEN DR	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 04531790ad594b75bfd695d132821069	BRANCH TO: MILLER RD	SECTION PAVEMENT CONDITION INDEX: SECT PCI 37.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 50.1

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 37

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 50

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	300	SQFT
3	BLOCK CR	M	1,000	SQFT
7	EDGE CR	L	25	FT
10	L & T CR	L	17	FT
20	WEATHERING	M	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	95 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	JOHN ST	JOHN ST	2	774	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	26dae2001e434c3284bda1a561e5dd3a	LILLIAN ST	SECT PCI 34.4	SECT SCI 49.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 34	SAMP SCI 49

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	255	SQFT
3	BLOCK CR	M	1,275	SQFT
4	BUMPS/SAGS	M	4	FT
7	EDGE CR	L	39	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	96 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	JOHN ST	JOHN ST	2	774	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	26dae2001e434c3284bda1a561e5dd3a	LILLIAN ST	SECT PCI 34.4	SECT SCI 49.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 51

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	222	SQFT
3	BLOCK CR	L	536	SQFT
3	BLOCK CR	M	772	SQFT
11	PATCH/UT CUT	H	15	SQFT
11	PATCH/UT CUT	M	115	SQFT
20	WEATHERING	H	120	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	97 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	JOHN ST	JOHN ST	2	410	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	LILLIAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	b97b8344784e46fbb3c3340455fb7249	S BOSTIAN ST	SECT PCI 35.5	SECT SCI 50.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 36	SAMP SCI 50

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	480	SQFT
6	DEPRESSION	L	238	SQFT
10	L & T CR	M	169	FT
18	SWELL	M	16	SQFT
20	WEATHERING	M	350	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	98 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	JOHN ST	JOHN ST	2	257	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	S BOSTIAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	3908e0a65a1f49cca296a440f2cd3ed4		SECT PCI 41.2	SECT SCI 47.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 41	SAMP SCI 48

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	175	SQFT
2	BLEEDING	M	36	SQFT
7	EDGE CR	L	71	FT
10	L & T CR	L	61	FT
15	RUTTING	M	120	SQFT
19	RAVELING	M	52	SQFT
20	WEATHERING	H	70	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	99 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	KELLER ST	KELLER ST	2	1,020	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	9469e48da0c844d8be218e3ca6aaf908	S BOSTIAN ST	SECT PCI 70.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	M	39	FT
10	L & T CR	L	126	FT
12	POLISHED AG		2,600	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	100 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
09	KELLER ST	KELLER ST	2	1,020	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	9469e48da0c844d8be218e3ca6aaf908	S BOSTIAN ST	SECT PCI 70.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	157	FT
12	POLISHED AG		2,600	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	101 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	KIRK ST	KIRK ST	2	479	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	96120ed3409241c8a2556797982f243e	S FRANKLIN ST	SECT PCI 31	SECT SCI 39.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 31	SAMP SCI 39

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	40	SQFT
1	ALLIGATOR CR	M	507	SQFT
3	BLOCK CR	M	528	SQFT
9	LANE SH DROP	L	43	FT
10	L & T CR	M	59	FT
11	PATCH/UT CUT	H	45	SQFT
11	PATCH/UT CUT	L	125	SQFT
11	PATCH/UT CUT	M	40	SQFT
20	WEATHERING	M	2,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	102 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	KIRK ST	KIRK ST	2	430	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8b2b488448934f3690040a0d289b2fdb	S MYRTLE AV	SECT PCI 55.6	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 56	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	2,456	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	103 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	KIRK ST	KIRK ST	2	364	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	21a9d0063f0241c58409bd4fd009b4d5	HARRY ST	SECT PCI 50.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 51	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	2,600	SQFT
7	EDGE CR	L	99	FT
9	LANE SH DROP	L	33	FT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	104 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	KIRK ST	KIRK ST	2	1,878	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	c21d87203f8b40f5b95df5e2747fd0e8	DEAD END	SECT PCI 68.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 57	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	1,232	SQFT
7	EDGE CR	L	116	FT
9	LANE SH DROP	L	32	FT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	105 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	KIRK ST	KIRK ST	2	1,878	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	c21d87203f8b40f5b95df5e2747fd0e8	DEAD END	SECT PCI 68.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 78	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	602	SQFT
7	EDGE CR	L	10	FT
10	L & T CR	L	34	FT
20	WEATHERING	L	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	106 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
12	KIRK ST	KIRK ST	2	1,878	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	c21d87203f8b40f5b95df5e2747fd0e8	DEAD END	SECT PCI 68.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 67	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	140	FT
11	PATCH/UT CUT	L	648	SQFT
20	WEATHERING	L	1,252	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	107 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
16	KIRK ST	KIRK ST	2	1,878	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	c21d87203f8b40f5b95df5e2747fd0e8	DEAD END	SECT PCI 68.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 73	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	895	SQFT
10	L & T CR	L	34	FT
20	WEATHERING	M	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	108 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	KLONDALEST	KLONDALE ST	2	513	26
	SECTION ID: 010	BRANCH FROM: E LIBERTY ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 7b7c0e998e2440398165464a48ce2441	BRANCH TO: KNIGHT ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 41.6	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 47.6	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 42

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 48

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	415	SQFT
3	BLOCK CR	M	34	SQFT
10	L & T CR	L	325	FT
20	WEATHERING	L	2,600	SQFT



SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	109 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	KLONDALEST	KLONDALE ST	2	376	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	KNIGHT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	4a92578a8c9c4d588e3e6d01df71529e	WASHINGTON ST	SECT PCI 51.1	SECT SCI 66.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 51	SAMP SCI 66

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	62	SQFT
1	ALLIGATOR CR	M	25	SQFT
3	BLOCK CR	L	755	SQFT
3	BLOCK CR	M	482	SQFT
11	PATCH/UT CUT	L	28	SQFT
17	SLIPPAGE CR	L	87	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	110 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	KLONDALEST	KLONDALE ST	2	416	26
	SECTION ID: 030	BRANCH FROM: WASHINGTON ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: bb2aeda781c4406dae3077dcd0fc45a5	BRANCH TO: OLD ROCKWELL RD	SECTION PAVEMENT CONDITION INDEX: SECT PCI 41.1	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 46.7	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 41

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 47

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	24	SQFT
1	ALLIGATOR CR	M	288	SQFT
10	L & T CR	L	71	FT
11	PATCH/UT CUT	H	44	SQFT
11	PATCH/UT CUT	L	32	SQFT
15	RUTTING	L	36	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	111 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	LAUREL ST	LAUREL ST	2	891	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WILSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	0b6705687a854ccfb34db1d10129df66	HICKORY NUT LN	SECT PCI 67	SECT SCI 85.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 72	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
6	DEPRESSION	L	16	SQFT
10	L & T CR	L	306	FT
10	L & T CR	M	20	FT
11	PATCH/UT CUT	L	18	SQFT
20	WEATHERING	M	2,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	112 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	LAUREL ST	LAUREL ST	2	891	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	WILSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	0b6705687a854ccfb34db1d10129df66	HICKORY NUT LN	SECT PCI 67	SECT SCI 85.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 62	SAMP SCI 75

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	152	SQFT
2	BLEEDING	L	56	SQFT
3	BLOCK CR	L	190	SQFT
10	L & T CR	L	225	FT
19	RAVELING	M	60	SQFT
20	WEATHERING	M	2,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	113 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	LAUREL ST	LAUREL ST	2	365	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	HICKORY NUT LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	db0a44e73af4469684eb2d2091bdf2fd	MITCHELL AV	SECT PCI 68.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 68	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	313	FT
10	L & T CR	M	40	FT
19	RAVELING	H	3	SQFT
19	RAVELING	M	236	SQFT
20	WEATHERING	L	2,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	114 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	LAURNGLNDR	LAUREN GLEN DR	2	1,415	23
	SECTION ID: 010	BRANCH FROM: W STOKES ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 85cbba39a07f4812bb5526f7ea9980a9	BRANCH TO: HIGHLAND RIDGE DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 55.7		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 67

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 31

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 47

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	150	SQFT
3	BLOCK CR	M	1,575	SQFT
11	PATCH/UT CUT	M	254	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	115 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	LAURNGLNDR	LAUREN GLEN DR	2	1,415	23
	SECTION ID: 010	BRANCH FROM: W STOKES ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 85cbba39a07f4812bb5526f7ea9980a9	BRANCH TO: HIGHLAND RIDGE DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 55.7		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 67

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 53

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 55

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	576	SQFT
6	DEPRESSION	M	20	SQFT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	116 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
12	LAURNGLNDR	LAUREN GLEN DR	2	1,415	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	W STOKES ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	85cbba39a07f4812bb5526f7ea9980a9	HIGHLAND RIDGE DR	SECT PCI 55.7	SECT SCI 67

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 84	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	180	FT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	117 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	LILLIAN ST	LILLIAN ST	2	357	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E THOM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	4a2680a9cebd4b79bd6d38f5737f4e8b	HANEY ST	SECT PCI 30.3	SECT SCI 34.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 30	SAMP SCI 35

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	289	SQFT
3	BLOCK CR	L	190	SQFT
10	L & T CR	M	289	FT
13	POTHOLE	L	1	COUNT
20	WEATHERING	M	85	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	118 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	LILLIAN ST	LILLIAN ST	2	328	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	HANEY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b777dafab67b4b6f95d68c6abb8cf7b9	JOHN ST	SECT PCI 42.8	SECT SCI 65.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 43	SAMP SCI 66

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	312	SQFT
3	BLOCK CR	M	2,200	SQFT
3	BLOCK CR	M	2,200	SQFT
7	EDGE CR	M	51	FT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	119 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	LOUISE AV	LOUISE AV	2	451	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	08baf93b1dd34b888a7a4888a16af8c7	S MYRTLE AV	SECT PCI 76.7	SECT SCI 81.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 82

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	32	SQFT
10	L & T CR	L	132	FT
13	POTHOLE	L	2	COUNT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	120 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	LOUISE AV	LOUISE AV	2	665	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	68346036401846418eca8ed893ffa794	S CLINTON ST	SECT PCI 62.8	SECT SCI 75.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	335	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	121 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	LOUISE AV	LOUISE AV	2	665	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	68346036401846418eca8ed893ffa794	S CLINTON ST	SECT PCI 62.8	SECT SCI 75.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 47	SAMP SCI 51

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	321	SQFT
10	L & T CR	L	262	FT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	122 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	LUTHCHPLRD	LUTHERAN CHAPEL RD	2	612	21
	SECTION ID: 010	BRANCH FROM: N CHAPEL ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,100	SUNIQUEID: 0b1cffa454364be6afe0a171aa8f7eaf	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 57.9		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 61

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	56	FT
20	WEATHERING	H	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	123 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	LUTHCHPLRD	LUTHERAN CHAPEL RD	2	612	21

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N CHAPEL ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,100	0b1cffa454364be6afe0a171aa8f7eaf	DEAD END	SECT PCI 57.9	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	M	21	SQFT
3	BLOCK CR	M	32	SQFT
7	EDGE CR	L	38	FT
10	L & T CR	L	170	FT
20	WEATHERING	H	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	124 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MILLER ST	MILLER ST	2	426	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	W VANCE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	db9681d3e79f4f49a8888b11e32ce17f	W LIBERTY ST	SECT PCI 62.2	SECT SCI 66.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 62	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	35	SQFT
10	L & T CR	L	170	FT
11	PATCH/UT CUT	M	26	SQFT
17	SLIPPAGE CR	L	300	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	125 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MILLER ST	MILLER ST	2	294	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	W LIBERTY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	6da46322f5444cf28b12613abe15918d	DEAD END	SECT PCI 76.4	SECT SCI 84.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 76	SAMP SCI 85

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	170	FT
17	SLIPPAGE CR	L	100	SQFT
20	WEATHERING	H	100	SQFT
20	WEATHERING	L	2,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	126 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MITCHELLAV	MITCHELL AV	2	397	27

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	W STOKES ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,700	fe2a9445c9eb4df1b079d239b22f2324	OAKWOOD CT	SECT PCI 49.8	SECT SCI 53.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 50	SAMP SCI 53

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	78	SQFT
1	ALLIGATOR CR	L	15	SQFT
10	L & T CR	L	460	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	127 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MITCHELLAV	MITCHELL AV	2	287	27
	SECTION ID: 050	BRANCH FROM: OAKWOOD CT	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,700	SUNIQUEID: ce36e436d22d447ab25fa916ae0e6424	BRANCH TO: COVE LN	SECTION PAVEMENT CONDITION INDEX: SECT PCI 56.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 71.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 56	SAMP SCI 71

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	58	SQFT
3	BLOCK CR	M	500	SQFT
10	L & T CR	L	302	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	128 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	MITCHELLAV	MITCHELL AV	2	129	27
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	060	COVE LN			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,700	7308300451ea4bb080b9a58ffcb8d5d1	SPRING BRANCH LN	SECT PCI 79.7	SECT SCI 90.8	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 80	SAMP SCI 91

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	18	SQFT
3	BLOCK CR	L	114	SQFT
7	EDGE CR	L	101	FT
10	L & T CR	L	211	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	129 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MITCHELLAV	MITCHELL AV	2	289	27

SECTION ID	BRANCH FROM	SECTION COMMENTS
070	SPRING BRANCH LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,700	f137f71e5bdc49149b384d0d9763600e	WILSON ST	SECT PCI 50.3	SECT SCI 65.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 50	SAMP SCI 66

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	325	SQFT
2	BLEEDING	H	180	SQFT
3	BLOCK CR	L	1,875	SQFT
19	RAVELING	H	9	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	130 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	MITCHELLAV	MITCHELL AV	2	813	27
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	080	WILSON ST			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,700	7dd89376602349d094e0e412e7e3557b	LAUREL ST	SECT PCI 68.1	SECT SCI 90.8	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	1,140	SQFT
7	EDGE CR	L	56	FT
10	L & T CR	L	163	FT
11	PATCH/UT CUT	L	135	SQFT
19	RAVELING	H	35	SQFT
19	RAVELING	M	17	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	131 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	MITCHELLAV	MITCHELL AV	2	813	27
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	080	WILSON ST			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,700	7dd89376602349d094e0e412e7e3557b	LAUREL ST	SECT PCI 68.1	SECT SCI 90.8	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 82

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	68	SQFT
3	BLOCK CR	L	80	SQFT
10	L & T CR	L	307	FT
19	RAVELING	L	100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	132 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	NBOSTIANST	N BOSTIAN ST	2	1,018	31
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	010	E CENTERVIEW ST/S BO			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
3,100	e2f046259f0a4f69bc9b61dd6becc73d	E KETCHIE ST	SECT PCI 38.8	SECT SCI 53.8	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 45	SAMP SCI 57

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	150	SQFT
2	BLEEDING	H	25	SQFT
2	BLEEDING	M	64	SQFT
3	BLOCK CR	M	480	SQFT
4	BUMPS/SAGS	L	26	FT
10	L & T CR	L	150	FT
15	RUTTING	L	144	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	133 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	NBOSTIANST	N BOSTIAN ST	2	1,018	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E CENTERVIEW ST/S BO	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	e2f046259f0a4f69bc9b61dd6becc73d	E KETCHIE ST	SECT PCI 38.8	SECT SCI 53.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 32	SAMP SCI 50

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	832	SQFT
10	L & T CR	L	161	FT
19	RAVELING	H	10	SQFT
20	WEATHERING	H	1,100	SQFT
20	WEATHERING	M	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	134 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NBOSTIANST	N BOSTIAN ST	2	720	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	E KETCHIE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b18328ecf67a47e98cd51f5d17a41c9c	E CHURCH ST	SECT PCI 24.9	SECT SCI 31.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 28	SAMP SCI 32

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	856	SQFT
3	BLOCK CR	L	600	SQFT
10	L & T CR	L	112	FT
11	PATCH/UT CUT	H	12	SQFT
13	POTHOLE	L	2	COUNT
15	RUTTING	L	130	SQFT
19	RAVELING	H	6	SQFT
20	WEATHERING	H	800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	135 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	NBOSTIANST	N BOSTIAN ST	2	720	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	E KETCHIE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b18328ecf67a47e98cd51f5d17a41c9c	E CHURCH ST	SECT PCI 24.9	SECT SCI 31.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 22	SAMP SCI 31

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	100	SQFT
3	BLOCK CR	M	568	SQFT
10	L & T CR	L	34	FT
11	PATCH/UT CUT	H	24	SQFT
11	PATCH/UT CUT	M	135	SQFT
15	RUTTING	M	284	SQFT
19	RAVELING	H	38	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	136 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	NBOSTIANST	N BOSTIAN ST	2	952	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	E CHURCH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	69570f6cc4584222956e1cb05297ec28	E LIBERTY ST	SECT PCI 54.5	SECT SCI 76.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 63	SAMP SCI 70

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
6	DEPRESSION	H	110	SQFT
6	DEPRESSION	M	48	SQFT
10	L & T CR	L	193	FT
19	RAVELING	M	129	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	137 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	NBOSTIANST	N BOSTIAN ST	2	952	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	E CHURCH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	69570f6cc4584222956e1cb05297ec28	E LIBERTY ST	SECT PCI 54.5	SECT SCI 76.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 46	SAMP SCI 83

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	193	FT
11	PATCH/UT CUT	H	20	SQFT
19	RAVELING	H	35	SQFT
19	RAVELING	M	258	SQFT
20	WEATHERING	H	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	138 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	NCLINTONST	N CLINTON ST	2	754	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S CLINTON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	15a967bc16c3448e812e3eda61e58970	PARK ST	SECT PCI 48.4	SECT SCI 56.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 60	SAMP SCI 70

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	180	SQFT
3	BLOCK CR	L	305	SQFT
6	DEPRESSION	L	30	SQFT
10	L & T CR	L	300	FT
11	PATCH/UT CUT	L	36	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	139 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	NCLINTONST	N CLINTON ST	2	754	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S CLINTON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	15a967bc16c3448e812e3eda61e58970	PARK ST	SECT PCI 48.4	SECT SCI 56.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 37	SAMP SCI 43

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	100	SQFT
1	ALLIGATOR CR	L	100	SQFT
1	ALLIGATOR CR	M	250	SQFT
6	DEPRESSION	L	75	SQFT
6	DEPRESSION	M	75	SQFT
10	L & T CR	L	250	FT
10	L & T CR	M	20	FT
11	PATCH/UT CUT	L	367	SQFT
18	SWELL	L	9	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	140 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	NCLINTONST	N CLINTON ST	2	592	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	PARK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	f5375565d9194a94b4baa652e7de2b42	W KETCHIE ST	SECT PCI 66	SECT SCI 92

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 92

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	40	SQFT
6	DEPRESSION	L	36	SQFT
10	L & T CR	L	385	FT
11	PATCH/UT CUT	L	260	SQFT
11	PATCH/UT CUT	M	10	SQFT
18	SWELL	L	20	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	141 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NFRANKLNST	N FRANKLIN ST	2	391	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S FRANKLIN ST/W CENTE	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	b78d0c86d1bd41bd85955c33d5765f33	SWINK ST	SECT PCI 68.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 69	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	3,000	SQFT
20	WEATHERING	M	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	142 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NFRANKLNST	N FRANKLIN ST	2	294	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	SWINK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	7afabff1f6b347e4bfd0e27fdbfdada8	PARK ST	SECT PCI 69.6	SECT SCI 78.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 70	SAMP SCI 79

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	84	SQFT
10	L & T CR	L	345	FT
17	SLIPPAGE CR	L	30	SQFT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	143 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	NFRANKLNST	N FRANKLIN ST	2	536	30
	SECTION ID: 030	BRANCH FROM: PARK ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,000	SUNIQUEID: 8970f13536e64fd497ec5438f24b8105	BRANCH TO: W KETCHIE ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 78.7	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	395	FT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	144 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NFRANKLNST	N FRANKLIN ST	2	385	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	W KETCHIE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	d892eeb629964c40951d9ab3bcaab9ff	ROSS ST	SECT PCI 82.2	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 82	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	277	FT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	145 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NFRANKLNST	N FRANKLIN ST	2	473	20
	SECTION ID: 050	BRANCH FROM: ROSS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,000	SUNIQUEID: 080e856b0ec449b7a8f656963b4ab578	BRANCH TO: W CHURCH ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 31.2	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 42.8	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 31

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 43

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	1,400	SQFT
13	POTHOLE	L	1	COUNT
20	WEATHERING	M	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	146 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NHARRISST	N HARRIS ST	2	969	21

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,100	abcce55b56ff4db39ae88cdc9920e2da	E KETCHIE ST	SECT PCI 91.3	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 90	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	72	FT
9	LANE SH DROP	M	33	FT
20	WEATHERING	L	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	147 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	NHARRISST	N HARRIS ST	2	969	21

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,100	abcce55b56ff4db39ae88cdc9920e2da	E KETCHIE ST	SECT PCI 91.3	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 92	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	59	FT
20	WEATHERING	L	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	148 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	NHARRISST	N HARRIS ST	2	680	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	E KETCHIE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	fbf80f510a1640909e3576ae54bdef12	E CHURCH ST	SECT PCI 56.2	SECT SCI 65.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 19	SAMP SCI 31

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	720	SQFT
3	BLOCK CR	M	1,078	SQFT
10	L & T CR	M	22	FT
11	PATCH/UT CUT	H	145	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	149 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	NHARRISST	N HARRIS ST	2	680	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	E KETCHIE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	fbf80f510a1640909e3576ae54bdef12	E CHURCH ST	SECT PCI 56.2	SECT SCI 65.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	77	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	150 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	NHARRISST	N HARRIS ST	2	966	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	E CHURCH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	e9fdf92e565642d0bbf77249ff f19a8b	E LIBERTY ST	SECT PCI 79.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 90	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	28	FT
10	L & T CR	L	95	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	151 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	NHARRISST	N HARRIS ST	2	966	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	E CHURCH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	e9fdf92e565642d0bbf77249ff f19a8b	E LIBERTY ST	SECT PCI 79.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 69	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	247	SQFT
7	EDGE CR	M	64	FT
10	L & T CR	L	255	FT
19	RAVELING	M	222	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	152 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	NMYRTLEAV	N MYRTLE AV	2	569	25

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	PARK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,500	28a608539c434d83821f4e85fd4cb44e	W KETCHIE ST	SECT PCI 67.5	SECT SCI 85.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 68	SAMP SCI 85

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	40	SQFT
10	L & T CR	L	387	FT
20	WEATHERING	M	2,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	153 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	OAK ST	OAK ST	2	500	18
	SECTION ID: 010	BRANCH FROM: E THOM ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 1,800	SUNIQUEID: bbd9655b5f734b1e8ad1a7a7c2f1f7f3	BRANCH TO: ROSE AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 11.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 23.8

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 12

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 24

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	58	SQFT
3	BLOCK CR	L	107	SQFT
4	BUMPS/SAGS	M	50	FT
7	EDGE CR	M	53	FT
10	L & T CR	L	83	FT
15	RUTTING	H	260	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	154 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	OAKWOOD CT	OAKWOOD CT	2	327	27
	SECTION ID: 010	BRANCH FROM: CUL-DE-SAC	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,700	SUNIQUEID: 713cc852a8084151a55fca6dd7216990	BRANCH TO: MITCHELL AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 64.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 66.6

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 65

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	300	SQFT
10	L & T CR	L	178	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	155 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ODRCKWELR	OLD ROCKWELL RD	2	354	17
	SECTION ID: 010	BRANCH FROM: N MAIN ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,700	SUNIQUEID: 61a0c4b1a9424025a58597e3d96463e4	BRANCH TO: KLONDALE ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 46.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 52.1

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 46

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 52

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	250	FT
11	PATCH/UT CUT	L	20	SQFT
11	PATCH/UT CUT	M	13	SQFT
15	RUTTING	H	73	SQFT
20	WEATHERING	L	1,700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	156 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ODRCKWELR	OLD ROCKWELL RD	2	434	17
	SECTION ID: 020	BRANCH FROM: KLONDALE ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 1,700	SUNIQUEID: 905f071881584458aa94cb0281e4311a	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 28.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 44.2

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 28

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 44

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	80	SQFT
3	BLOCK CR	M	165	SQFT
7	EDGE CR	M	24	FT
10	L & T CR	M	162	FT
15	RUTTING	L	138	SQFT
20	WEATHERING	M	1,700	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	157 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	PARK ST	PARK ST	2	185	27

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,700	12a3602986c14d6b810775f3f6558607	TATUM ST	SECT PCI 35.8	SECT SCI 51.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 36	SAMP SCI 52

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	198	SQFT
3	BLOCK CR	M	42	SQFT
10	L & T CR	M	333	FT
11	PATCH/UT CUT	M	60	SQFT
13	POTHOLE	L	2	COUNT
20	WEATHERING	L	2,700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	158 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	PARK ST	PARK ST	2	727	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	TATUM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	54a8d41e42274ea0a6d30d929017e276	N FRANKLIN ST	SECT PCI 51.2	SECT SCI 65.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 43	SAMP SCI 61

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	110	SQFT
3	BLOCK CR	M	1,224	SQFT
9	LANE SH DROP	L	200	FT
20	WEATHERING	L	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	159 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	PARK ST	PARK ST	2	727	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	TATUM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	54a8d41e42274ea0a6d30d929017e276	N FRANKLIN ST	SECT PCI 51.2	SECT SCI 65.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 60	SAMP SCI 71

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	151	SQFT
9	LANE SH DROP	L	200	FT
10	L & T CR	L	272	FT
20	WEATHERING	L	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	160 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	PARK ST	PARK ST	2	524	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	N FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	24cd1646877d4bb3a1fa2ed66f079008	N MYRTLE AV	SECT PCI 30.4	SECT SCI 56.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 30	SAMP SCI 57

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	200	SQFT
3	BLOCK CR	M	789	SQFT
10	L & T CR	M	93	FT
20	WEATHERING	H	1,272	SQFT
20	WEATHERING	L	1,328	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	161 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	PARK ST	PARK ST	2	660	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	N MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8e178f52a0aa4c909bc8d5638a0d46ab	N CLINTON ST	SECT PCI 52.5	SECT SCI 87.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 47	SAMP SCI 76

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	36	SQFT
3	BLOCK CR	M	2,000	SQFT
9	LANE SH DROP	M	200	FT
11	PATCH/UT CUT	L	70	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	162 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	PARK ST	PARK ST	2	660	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	N MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8e178f52a0aa4c909bc8d5638a0d46ab	N CLINTON ST	SECT PCI 52.5	SECT SCI 87.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	200	FT
10	L & T CR	L	50	FT
10	L & T CR	M	421	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	163 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	PARK ST	PARK ST	2	449	22

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	N CLINTON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,200	24f714c58382470189892e85528a6498	ELIZABETH ST	SECT PCI 52.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 53	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	2,200	SQFT
9	LANE SH DROP	L	2,200	FT
20	WEATHERING	L	2,200	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	164 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	PARK ST	PARK ST	2	423	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	ELIZABETH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	53756bd786e04a3092c239a350a78c64	DOTS CIR	SECT PCI 82.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 83	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	36	FT
10	L & T CR	L	7	FT
20	WEATHERING	M	1,900	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	165 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	POWER ST	POWER ST	2	801	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E LIBERTY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	e10fb1ac4a974eadb0a84486f5d50a2e	GROVE ST	SECT PCI 51	SECT SCI 60.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 47	SAMP SCI 58

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	200	SQFT
3	BLOCK CR	L	290	SQFT
3	BLOCK CR	M	490	SQFT
10	L & T CR	L	50	FT
15	RUTTING	L	250	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	166 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	POWER ST	POWER ST	2	801	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E LIBERTY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	e10fb1ac4a974eadb0a84486f5d50a2e	GROVE ST	SECT PCI 51	SECT SCI 60.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 63

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	400	SQFT
3	BLOCK CR	L	766	SQFT
10	L & T CR	L	81	FT
19	RAVELING	L	50	SQFT
20	WEATHERING	H	37	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	167 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	POWER ST	POWER ST	2	1,506	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GROVE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	b9117d448d134ae2bd174bbbfe47e971	KETCHIE ESTATE RD	SECT PCI 51.3	SECT SCI 68.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 31	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	250	SQFT
3	BLOCK CR	M	1,100	SQFT
7	EDGE CR	L	23	FT
10	L & T CR	L	86	FT
20	WEATHERING	H	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	168 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
09	POWER ST	POWER ST	2	1,506	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GROVE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	b9117d448d134ae2bd174bbbfe47e971	KETCHIE ESTATE RD	SECT PCI 51.3	SECT SCI 68.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 23	SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	528	SQFT
3	BLOCK CR	M	820	SQFT
20	WEATHERING	H	2,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	169 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
14	POWER ST	POWER ST	2	1,506	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	GROVE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	b9117d448d134ae2bd174bbbfe47e971	KETCHIE ESTATE RD	SECT PCI 51.3	SECT SCI 68.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 100	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	2	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	170 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	RAILROADAV	RAILROAD AV	2	396	26
	SECTION ID: 010	BRANCH FROM: E LIBERTY ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 4ad078b227fe4a63b8644fcbf3f8ffbf	BRANCH TO: RIDGE ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 80.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 88.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 81	SAMP SCI 89

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	172	FT
11	PATCH/UT CUT	L	70	SQFT
11	PATCH/UT CUT	M	36	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	171 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	RAILROADAV	RAILROAD AV	2	730	26
	SECTION ID: 020	BRANCH FROM: RIDGE ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: f9ebd2386d0d48218f68aee653daf07a	BRANCH TO: HUFFMAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 89		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 85

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	229	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	172 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	RAILROADAV	RAILROAD AV	2	730	26
	SECTION ID: 020	BRANCH FROM: RIDGE ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: f9ebd2386d0d48218f68aee653daf07a	BRANCH TO: HUFFMAN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 89		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 93	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	74	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	173 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	RAILROADAV	RAILROAD AV	2	722	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	HUFFMAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	c78f2f0638e643fc9b244347e8f9322d	CUL-DE-SAC	SECT PCI 86	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 89	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	72	FT
20	WEATHERING	L	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	174 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	RAILROADAV	RAILROAD AV	2	722	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	HUFFMAN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	c78f2f0638e643fc9b244347e8f9322d	CUL-DE-SAC	SECT PCI 86	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 83	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	123	FT
9	LANE SH DROP	M	15	FT
10	L & T CR	L	28	FT
20	WEATHERING	H	35	SQFT
20	WEATHERING	L	1,765	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	175 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	RIDGE ST	RIDGE ST	2	303	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	RAILROAD AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	509a546f77c44ac68ce57d1b7709d75e	DEAD END	SECT PCI 54.9	SECT SCI 95.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	161	SQFT
6	DEPRESSION	L	4	SQFT
10	L & T CR	L	186	FT
11	PATCH/UT CUT	L	130	SQFT
20	WEATHERING	H	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	176 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	ROBERTS ST	ROBERTS ST	2	989	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	BOSTIAN RD	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	5bf8e57c68a4443aa5d993212879bc24	3RD AV	SECT PCI 50.1	SECT SCI 88.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	63	SQFT
10	L & T CR	L	206	FT
20	WEATHERING	H	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	177 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	ROBERTS ST	ROBERTS ST	2	989	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	BOSTIAN RD	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	5bf8e57c68a4443aa5d993212879bc24	3RD AV	SECT PCI 50.1	SECT SCI 88.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 42	SAMP SCI 78

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	70	SQFT
7	EDGE CR	L	37	FT
7	EDGE CR	M	100	FT
10	L & T CR	L	54	FT
10	L & T CR	M	35	FT
19	RAVELING	H	100	SQFT
19	RAVELING	M	34	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	178 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ROBERTS ST	ROBERTS ST	2	332	15
	SECTION ID: 020	BRANCH FROM: 3RD AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,500	SUNIQUEID: 80fd97c5da8341918b7c7af1118c040a	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 29.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 37.2

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 29

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 37

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	90	SQFT
1	ALLIGATOR CR	M	24	SQFT
3	BLOCK CR	L	160	SQFT
6	DEPRESSION	M	70	SQFT
10	L & T CR	L	163	FT
19	RAVELING	H	25	SQFT
20	WEATHERING	M	1,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	179 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	ROSE AV	ROSE AV	2	146	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S US 29 HWY/XING	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	58808d6408624231977146bc628b8554	CHERRY ST	SECT PCI 44.9	SECT SCI 64.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 45	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	70	SQFT
3	BLOCK CR	L	770	SQFT
7	EDGE CR	M	80	FT
9	LANE SH DROP	L	46	FT
10	L & T CR	L	41	FT
19	RAVELING	H	30	SQFT
19	RAVELING	M	8	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	180 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ROSE AV	ROSE AV	2	333	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	CHERRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	23787353724c4d37b81bc417cf7d95a6	OAK ST	SECT PCI 10.6	SECT SCI 16.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 11	SAMP SCI 17

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	250	SQFT
3	BLOCK CR	M	600	SQFT
7	EDGE CR	M	61	FT
10	L & T CR	L	47	FT
11	PATCH/UT CUT	M	15	SQFT
15	RUTTING	H	220	SQFT
15	RUTTING	L	164	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	181 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	ROSE AV	ROSE AV	2	334	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	OAK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	77d445bf22b14cc590c6bbecb6288b38	WALNUT ST	SECT PCI 45.2	SECT SCI 59.4

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 45	SAMP SCI 59

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	308	SQFT
3	BLOCK CR	M	315	SQFT
6	DEPRESSION	H	20	SQFT
11	PATCH/UT CUT	L	20	SQFT
19	RAVELING	H	13	SQFT
19	RAVELING	M	89	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	182 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	ROSE AV	ROSE AV	2	194	22
	SECTION ID: 040	BRANCH FROM: WALNUT ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,200	SUNIQUEID: 843c025bf76948e5bcec238bb824c1a6	BRANCH TO: PARKING LOT	SECTION PAVEMENT CONDITION INDEX: SECT PCI 34.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 40.8

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 35

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	200	SQFT
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	455	SQFT
19	RAVELING	H	15	SQFT
19	RAVELING	M	42	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	183 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	ROSS ST	ROSS ST	2	1,283	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b0a6b94cd69e40ef8d9986605c2dc073	N FRANKLIN ST	SECT PCI 50.6	SECT SCI 60.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 57	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	281	SQFT
10	L & T CR	L	532	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	184 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	ROSS ST	ROSS ST	2	1,283	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b0a6b94cd69e40ef8d9986605c2dc073	N FRANKLIN ST	SECT PCI 50.6	SECT SCI 60.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 62	SAMP SCI 75

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	140	SQFT
7	EDGE CR	L	20	FT
10	L & T CR	L	433	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	185 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
12	ROSS ST	ROSS ST	2	1,283	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	b0a6b94cd69e40ef8d9986605c2dc073	N FRANKLIN ST	SECT PCI 50.6	SECT SCI 60.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 33	SAMP SCI 39

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	125	SQFT
1	ALLIGATOR CR	L	300	SQFT
10	L & T CR	L	353	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	186 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	ROSS ST	ROSS ST	2	1,380	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	N FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	7f234438850244d289d3a67b76fb07aa	W KETCHIE ST	SECT PCI 50.7	SECT SCI 57.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 40	SAMP SCI 42

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	158	SQFT
10	L & T CR	L	79	FT
11	PATCH/UT CUT	L	71	SQFT
15	RUTTING	H	42	SQFT
15	RUTTING	L	44	SQFT
15	RUTTING	M	36	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	187 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	ROSS ST	ROSS ST	2	1,380	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	N FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	7f234438850244d289d3a67b76fb07aa	W KETCHIE ST	SECT PCI 50.7	SECT SCI 57.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 54	SAMP SCI 64

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	213	SQFT
9	LANE SH DROP	L	20	FT
9	LANE SH DROP	M	12	FT
10	L & T CR	L	211	FT
17	SLIPPAGE CR	L	24	SQFT
19	RAVELING	H	12	SQFT
19	RAVELING	M	15	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	188 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
12	ROSS ST	ROSS ST	2	1,380	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	N FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	7f234438850244d289d3a67b76fb07aa	W KETCHIE ST	SECT PCI 50.7	SECT SCI 57.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	223	SQFT
10	L & T CR	L	271	FT
20	WEATHERING	L	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	189 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	961	31
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	010	E CENTERVIEW ST/N BO			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX		SECTION STRUCTURAL CONDITION INDEX
3,100	f9215a11ad92476e828717d9b1d5894b	WOODHAVEN ST	SECT PCI 37		SECT SCI 48.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 19	SAMP SCI 31

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	256	SQFT
2	BLEEDING	L	50	SQFT
3	BLOCK CR	M	1,600	SQFT
10	L & T CR	L	57	FT
15	RUTTING	M	220	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	190 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	SBOSTIANST	S BOSTIAN ST	2	961	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E CENTERVIEW ST/N BO	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	f9215a11ad92476e828717d9b1d5894b	WOODHAVEN ST	SECT PCI 37	SECT SCI 48.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 55	SAMP SCI 66

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	M	15	SQFT
3	BLOCK CR	M	620	SQFT
4	BUMPS/SAGS	L	15	FT
15	RUTTING	M	136	SQFT
19	RAVELING	M	20	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	191 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	347	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	WOODHAVEN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	3e27f68979fe481085c6d094f14297b5	CHAPEL ST	SECT PCI 58.4	SECT SCI 78.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 79

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	108	SQFT
3	BLOCK CR	L	1,473	SQFT
20	WEATHERING	H	600	SQFT
20	WEATHERING	M	2,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	192 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	340	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	CHAPEL ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	6afb3263c84544a2bd09c0ed1fbb27fb	BLACKWELDER ST	SECT PCI 24.5	SECT SCI 31.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 25	SAMP SCI 32

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	500	SQFT
2	BLEEDING	L	32	SQFT
3	BLOCK CR	L	1,776	SQFT
10	L & T CR	L	29	FT
15	RUTTING	H	127	SQFT
18	SWELL	L	40	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	193 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	337	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	BLACKWELDER ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	e1fc9498a7bc42a48582c2c3bd3aa76d	KELLER ST	SECT PCI 52.7	SECT SCI 61.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 53	SAMP SCI 61

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	540	SQFT
3	BLOCK CR	L	2,200	SQFT
4	BUMPS/SAGS	L	36	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	194 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SBOSTIANST	S BOSTIAN ST	2	389	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	KELLER ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	d3827a3dc93542c29b750f602725b453	CHINABERRY DR	SECT PCI 34.7	SECT SCI 51.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 52

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	300	SQFT
2	BLEEDING	H	156	SQFT
2	BLEEDING	L	70	SQFT
3	BLOCK CR	M	2,007	SQFT
11	PATCH/UT CUT	M	8	SQFT
19	RAVELING	H	5	SQFT
19	RAVELING	M	20	SQFT



SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	195 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	343	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	CHINABERRY DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	4c22e6a6c49046f0a4b4c58a7183f6c6	BENCHMARK LN	SECT PCI 54.4	SECT SCI 72.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 54	SAMP SCI 73

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	132	SQFT
2	BLEEDING	M	88	SQFT
3	BLOCK CR	L	1,042	SQFT
6	DEPRESSION	M	18	SQFT
10	L & T CR	L	40	FT
13	POTHOLE	L	1	COUNT
19	RAVELING	H	83	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	196 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SBOSTIANST	S BOSTIAN ST	2	505	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
070	BENCHMARK LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	a3df6c11cf8a40e3b34cc404a7eed8f2	JOHN ST	SECT PCI 58.4	SECT SCI 73

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 73

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	160	SQFT
3	BLOCK CR	L	108	SQFT
6	DEPRESSION	L	12	SQFT
10	L & T CR	L	232	FT
10	L & T CR	M	83	FT
20	WEATHERING	M	3,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	197 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SBOSTIANST	S BOSTIAN ST	2	353	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
080	JOHN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	5081db59ba29462186e66249dc3f81ed	HANEY ST	SECT PCI 28.5	SECT SCI 47.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 29	SAMP SCI 48

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	466	SQFT
1	ALLIGATOR CR	M	114	SQFT
3	BLOCK CR	M	2,200	SQFT
4	BUMPS/SAGS	M	8	FT
20	WEATHERING	M	3,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	198 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SBOSTIANST	S BOSTIAN ST	2	364	31

SECTION ID	BRANCH FROM	SECTION COMMENTS
090	HANEY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,100	7253c500f84f4a46af8fde96363f84f3	E THOM ST/WALNUT ST	SECT PCI 59.7	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 60	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	2,300	SQFT
7	EDGE CR	L	81	FT
18	SWELL	L	400	SQFT
19	RAVELING	H	66	SQFT
20	WEATHERING	L	1,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	199 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SCLINTONST	S CLINTON ST	2	308	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N CLINTON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	a7b8fb72387e4b129aa4a36529f17e1b	LOUISE AV	SECT PCI 77.9	SECT SCI 95.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 78	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	200	SQFT
6	DEPRESSION	L	20	SQFT
10	L & T CR	L	200	FT
11	PATCH/UT CUT	L	88	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	200 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SCLINTONST	S CLINTON ST	2	450	26
	SECTION ID: 020	BRANCH FROM: LOUISE AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 6b0a043088b94164a2cc7ead245983ab	BRANCH TO: PATTERSON ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 45.3		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 52.2

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 45	SAMP SCI 52

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	80	SQFT
6	DEPRESSION	L	10	SQFT
10	L & T CR	L	275	FT
11	PATCH/UT CUT	L	77	SQFT
11	PATCH/UT CUT	M	16	SQFT
13	POTHOLE	L	10	COUNT
20	WEATHERING	L	2,600	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	201 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SFRANKLNST	S FRANKLIN ST	2	369	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	N FRANKLIN ST/W CENT	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	8e3b189ceaa64a9fa8b0f26aa3307462	LOUISE AV	SECT PCI 52.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 53	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	3,000	SQFT
9	LANE SH DROP	L	140	FT
20	WEATHERING	M	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	202 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SFRANKLNST	S FRANKLIN ST	2	446	30
	SECTION ID: 020	BRANCH FROM: LOUISE AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,000	SUNIQUEID: 66a08fc972524407afb36f153d090b41	BRANCH TO: PATTERSON ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 43.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 85.3

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 44

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 85

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	40	FT
10	L & T CR	M	549	FT
11	PATCH/UT CUT	L	982	SQFT
11	PATCH/UT CUT	M	66	SQFT
20	WEATHERING	M	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	203 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SFRANKLNST	S FRANKLIN ST	2	438	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	PATTERSON ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	3ff7ddff2f1145c89a4e59b8dc2f0a25	W FIRST ST	SECT PCI 78.4	SECT SCI 95.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 78	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
6	DEPRESSION	L	25	SQFT
10	L & T CR	L	271	FT
11	PATCH/UT CUT	L	72	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	204 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SFRANKLNST	S FRANKLIN ST	2	451	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	W FIRST ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	b4e2700bcec34b73ad88965dcf02a787	STEVENS ST	SECT PCI 81.4	SECT SCI 96

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 81	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	276	SQFT
6	DEPRESSION	L	4	SQFT
10	L & T CR	L	194	FT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	205 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	SFRANKLNST	S FRANKLIN ST	2	56	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	STEVENS ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,680	d5124eb8721a4fb1a8fa7e9fe940698f	STEVENS ST	SECT PCI 80.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 80	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	172	FT
19	RAVELING	L	4	SQFT
20	WEATHERING	L	1,680	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	206 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SFRANKLNST	S FRANKLIN ST	2	1,722	34

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	STEVENS ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,400	dad364f99b344aac877b6bd4de985f6e	KIRK ST	SECT PCI 77.1	SECT SCI 99

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	6	FT
9	LANE SH DROP	L	51	FT
10	L & T CR	L	1,192	FT
20	WEATHERING	L	3,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	207 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	SFRANKLNST	S FRANKLIN ST	2	1,722	34
	SECTION ID: 060	BRANCH FROM: STEVENS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,400	SUNIQUEID: dad364f99b344aac877b6bd4de985f6e	BRANCH TO: KIRK ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 77.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 99

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 84

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	74	FT
10	L & T CR	L	210	FT
20	WEATHERING	L	3,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	208 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
11	SFRANKLNST	S FRANKLIN ST	2	1,722	34
	SECTION ID: 060	BRANCH FROM: STEVENS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,400	SUNIQUEID: dad364f99b344aac877b6bd4de985f6e	BRANCH TO: KIRK ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 77.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 99

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 79

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	280	SQFT
4	BUMPS/SAGS	L	2	FT
4	BUMPS/SAGS	L	2	FT
6	DEPRESSION	L	4	SQFT
9	LANE SH DROP	L	20	FT
10	L & T CR	L	210	FT
20	WEATHERING	L	3,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	209 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
15	SFRANKLNST	S FRANKLIN ST	2	1,722	34
	SECTION ID: 060	BRANCH FROM: STEVENS ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 3,400	SUNIQUEID: dad364f99b344aac877b6bd4de985f6e	BRANCH TO: KIRK ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 77.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 99

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 79

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	1,056	SQFT
10	L & T CR	L	78	FT
19	RAVELING	L	6	SQFT
20	WEATHERING	L	3,400	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	210 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SFRANKLNST	S FRANKLIN ST	2	711	30

SECTION ID	BRANCH FROM	SECTION COMMENTS
070	KIRK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
3,000	dc406bda6ab04a6c85fc6f6fdce2c611	W THOM ST	SECT PCI 81.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 81	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	150	SQFT
7	EDGE CR	L	80	FT
10	L & T CR	L	200	FT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	211 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	SFRANKLNST	S FRANKLIN ST	2	711	30
	SECTION ID: 070	BRANCH FROM: KIRK ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 3,000	SUNIQUEID: dc406bda6ab04a6c85fc6f6fdce2c611	BRANCH TO: W THOM ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 81.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 82

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	311	SQFT
7	EDGE CR	L	80	FT
10	L & T CR	L	182	FT
20	WEATHERING	L	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	212 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	SMYRTLEAV	S MYRTLE AV	2	575	26
	SECTION ID: 010	BRANCH FROM: CUL-DE-SAC	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: d6b115d4dbbd4adfae93524ab789f96f	BRANCH TO: LOUISE AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 53.7		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 60.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 54	SAMP SCI 61

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	400	SQFT
2	BLEEDING	L	25	SQFT
3	BLOCK CR	L	1,500	SQFT
6	DEPRESSION	L	15	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	213 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SMYRTLEAV	S MYRTLE AV	2	451	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	LOUISE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	67aea87d388c4b65a24da99518dbb695	PATTERSON ST	SECT PCI 66.1	SECT SCI 89.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 89

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	2,500	SQFT
13	POTHOLE	L	1	COUNT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	214 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SMYRTLEAV	S MYRTLE AV	2	442	26
	SECTION ID: 030	BRANCH FROM: PATTERSON ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 6c2c6b6e138449cd9a54b876ca03ad9b	BRANCH TO: W FIRST ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 35.3		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 40.7

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 35

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 41

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	522	SQFT
3	BLOCK CR	M	918	SQFT
6	DEPRESSION	L	90	SQFT
9	LANE SH DROP	L	200	FT
10	L & T CR	L	128	FT
11	PATCH/UT CUT	L	45	SQFT
13	POTHOLE	L	1	COUNT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	215 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SMYRTLEAV	S MYRTLE AV	2	436	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	W FIRST ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	9adf178a4fb14867a121468b02b640c8	STEVENS ST	SECT PCI 31.3	SECT SCI 64.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 31	SAMP SCI 65

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	100	SQFT
3	BLOCK CR	M	339	SQFT
5	CORRUGATION	M	234	SQFT
10	L & T CR	L	133	FT
19	RAVELING	H	85	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	216 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SMYRTLEAV	S MYRTLE AV	2	422	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
050	STEVENS ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	677eaac175c44bbe83e7f2ee538d31bb	DEAD END	SECT PCI 51.4	SECT SCI 65.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 51	SAMP SCI 66

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	349	SQFT
7	EDGE CR	M	91	FT
10	L & T CR	L	257	FT
15	RUTTING	M	120	SQFT
19	RAVELING	M	32	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	217 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SMYRTLEAV	S MYRTLE AV	2	713	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	KIRK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	3f73a5f679ab4b128b91d8e2890e8429	W THOM ST	SECT PCI 63.9	SECT SCI 92.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 68	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	407	SQFT
7	EDGE CR	L	53	FT
9	LANE SH DROP	L	200	FT
10	L & T CR	L	84	FT
11	PATCH/UT CUT	L	162	SQFT
11	PATCH/UT CUT	L	162	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	218 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	SMYRTLEAV	S MYRTLE AV	2	713	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
060	KIRK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	3f73a5f679ab4b128b91d8e2890e8429	W THOM ST	SECT PCI 63.9	SECT SCI 92.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 60	SAMP SCI 84

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	M	200	FT
9	LANE SH DROP	L	200	FT
10	L & T CR	L	259	FT
11	PATCH/UT CUT	M	66	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	219 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SALSBURYST	SALISBURY ST	2	505	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E CHURCH ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	a3ab40af81024d978130bcdce9acbfce	E VANCE ST	SECT PCI 52.3	SECT SCI 64.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 52	SAMP SCI 64

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	170	SQFT
10	L & T CR	L	375	FT
15	RUTTING	L	132	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	220 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SALSBURYST	SALISBURY ST	2	490	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	E VANCE ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	5486ff9b98ab47778e6f785794f5245b	E LIBERTY ST	SECT PCI 52.2	SECT SCI 76.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 52	SAMP SCI 77

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	33	FT
10	L & T CR	L	270	FT
11	PATCH/UT CUT	L	884	SQFT
13	POTHOLE	L	3	COUNT
20	WEATHERING	M	1,716	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	221 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	SPNGBRNHLN	SPRING BRANCH LN	2	770	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	MITCHELL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	3b48dc27f7f0463cacedbdf9e4cd6de5	W HILLSIDE DR	SECT PCI 77.7	SECT SCI 91.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 89

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	27	SQFT
3	BLOCK CR	L	50	SQFT
10	L & T CR	L	281	FT
11	PATCH/UT CUT	L	24	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	222 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	SPNGBRNHLN	SPRING BRANCH LN	2	770	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	MITCHELL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	3b48dc27f7f0463cacedbdf9e4cd6de5	W HILLSIDE DR	SECT PCI 77.7	SECT SCI 91.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 95

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	9	SQFT
3	BLOCK CR	L	127	SQFT
3	BLOCK CR	M	27	SQFT
10	L & T CR	L	199	FT
20	WEATHERING	L	2,800	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	223 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	STEVENS ST	STEVENS ST	2	431	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	999b48964db547d696195d020456b45a	S FRANKLIN ST	SECT PCI 67.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 68	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	400	SQFT
10	L & T CR	L	216	FT
19	RAVELING	L	6	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	224 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	STEVENS ST	STEVENS ST	2	448	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	33738eb5488244c3b2d7f0567820f1c8	S MYRTLE AV	SECT PCI 83.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 84	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	276	SQFT
10	L & T CR	L	156	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	225 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	STEVENS ST	STEVENS ST	2	445	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	26c003260b984cd78484c4d8814f1397	CEDAR ST	SECT PCI 59.5	SECT SCI 79.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 53	SAMP SCI 59

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	110	SQFT
7	EDGE CR	L	31	FT
10	L & T CR	L	197	FT
19	RAVELING	M	6	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	226 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	STEVENS ST	STEVENS ST	2	445	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	26c003260b984cd78484c4d8814f1397	CEDAR ST	SECT PCI 59.5	SECT SCI 79.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 66	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	60	SQFT
10	L & T CR	L	152	FT
10	L & T CR	M	31	FT
18	SWELL	L	39	SQFT
18	SWELL	M	58	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	227 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	STEVENS ST	STEVENS ST	2	286	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
040	CEDAR ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	94758d92fb0b463aac7b363e5694a77c	DEAD END	SECT PCI 63	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 63	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	918	SQFT
10	L & T CR	L	197	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	228 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	SWINK ST	SWINK ST	2	179	24
	SECTION ID: 010	BRANCH FROM: N MAIN ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,400	SUNIQUEID: 246c0d0f6be24346b6be3638c83b0b44	BRANCH TO: TATUM ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 94.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 95	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
20	WEATHERING	L	2,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	229 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	SWINK ST	SWINK ST	2	612	24

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	TATUM ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,400	c0ee5f3bf03743ec8e6bfca16e44898b	N FRANKLIN ST	SECT PCI 94.8	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 95	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
20	WEATHERING	L	2,400	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	230 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	SWINK ST	SWINK ST	2	612	24
	SECTION ID: 020	BRANCH FROM: TATUM ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,400	SUNIQUEID: c0ee5f3bf03743ec8e6bfca16e44898b	BRANCH TO: N FRANKLIN ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 94.8	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 95

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
20	WEATHERING	L	2,400	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	231 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	TATUM ST	TATUM ST	2	226	20

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	SWINK ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,000	2304496df641445aaec7f8caa565938d	PARK ST	SECT PCI 0	SECT SCI 0

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 0	SAMP SCI 0

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	1,000	SQFT
6	DEPRESSION	H	16	SQFT
6	DEPRESSION	M	25	SQFT
10	L & T CR	H	30	FT
13	POTHOLE	H	100	COUNT
20	WEATHERING	M	1,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	232 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WCNTRVEWS	W CENTERVIEW ST	2	629	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E CENTERVIEW ST/N MAI	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	9f2c8f22ba69481aac3b533c83e6b6b3	N FRANKLIN ST/S FRANK	SECT PCI 51.1	SECT SCI 65.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	100	SQFT
10	L & T CR	L	203	FT
20	WEATHERING	M	3,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	233 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	WCNTRVEWS	W CENTERVIEW ST	2	629	26
	SECTION ID: 010	BRANCH FROM: E CENTERVIEW ST/N MAI	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 9f2c8f22ba69481aac3b533c83e6b6b3	BRANCH TO: N FRANKLIN ST/S FRANK	SECTION PAVEMENT CONDITION INDEX: SECT PCI 51.1	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 65.6	

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 25

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 31

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	341	SQFT
1	ALLIGATOR CR	M	110	SQFT
3	BLOCK CR	L	554	SQFT
3	BLOCK CR	M	256	SQFT
10	L & T CR	L	80	FT
20	WEATHERING	M	0	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	234 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
04	W FIRST ST	W FIRST ST	2	458	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	506d3f8eddeb4808a627c6bea5d64202	S MYRTLE AV	SECT PCI 48.1	SECT SCI 66.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 48	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	102	SQFT
3	BLOCK CR	M	560	SQFT
11	PATCH/UT CUT	L	300	SQFT
11	PATCH/UT CUT	M	306	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	235 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	W FIRST ST	W FIRST ST	2	435	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	48a4d021bfbf4a7cae6145ab81355e56	CEDAR ST	SECT PCI 34.2	SECT SCI 67.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 12	SAMP SCI 35

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	100	SQFT
1	ALLIGATOR CR	L	100	SQFT
1	ALLIGATOR CR	M	100	SQFT
3	BLOCK CR	H	400	SQFT
3	BLOCK CR	L	400	SQFT
3	BLOCK CR	M	800	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO



CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	236 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	W FIRST ST	W FIRST ST	2	435	36

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S MYRTLE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	48a4d021bfbf4a7cae6145ab81355e56	CEDAR ST	SECT PCI 34.2	SECT SCI 67.5

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 57	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	L	500	SQFT
3	BLOCK CR	M	1,200	SQFT
20	WEATHERING	M	1,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	237 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WHLLSIDEDR	W HILLSIDE DR	2	351	27
	SECTION ID: 010	BRANCH FROM: DEAD END	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,700	SUNIQUEID: ff7a1737bb244982afb9bca83680f0a0	BRANCH TO: SPRING BRANCH LN	SECTION PAVEMENT CONDITION INDEX: SECT PCI 35.1		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 48.5

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 35

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 49

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	1,900	SQFT
19	RAVELING	H	19	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	238 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WHLLSIDEDR	W HILLSIDE DR	2	610	25

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	SPRING BRANCH LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,500	88386c1711bb4851994fe7858597f432	ARBOR DR	SECT PCI 74.6	SECT SCI 85

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 78	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	6	SQFT
10	L & T CR	L	289	FT
20	WEATHERING	L	2,500	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	239 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
05	WHLLSIDEDR	W HILLSIDE DR	2	610	25
	SECTION ID: 020	BRANCH FROM: SPRING BRANCH LN	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,500	SUNIQUEID: 88386c1711bb4851994fe7858597f432	BRANCH TO: ARBOR DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 74.6		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 85

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 71

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 74

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	142	SQFT
10	L & T CR	L	173	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	240 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WHLLSIDEDR	W HILLSIDE DR	2	583	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	ARBOR DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	c8280f382df44b3da1c4b37f516f8dab	HICKORY GROVE LN	SECT PCI 77.2	SECT SCI 87.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 88

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	26	SQFT
10	L & T CR	L	233	FT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	241 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WLIBERTYST	W LIBERTY ST	2	415	26
	SECTION ID: 010	BRANCH FROM: E LIBERTY ST/N MAIN ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 9af50fe844e24ff2924a06756bd6fa45	BRANCH TO: MILLER ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 79.3	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	388	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	242 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WSTOKESST	W STOKES ST	2	404	23
	SECTION ID: 010	BRANCH FROM: DEAD END	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 7db910837a544afb8ecf96fab935e596	BRANCH TO: MITCHELL AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 90		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 90	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
11	PATCH/UT CUT	L	110	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	243 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WSTOKESST	W STOKES ST	2	2,663	21
	SECTION ID: 020	BRANCH FROM: MITCHELL AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,100	SUNIQUEID: 8295267df879456fbb86effba42cb653	BRANCH TO: LAUREN GLEN DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 44.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 47.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 30

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 33

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	H	203	SQFT
1	ALLIGATOR CR	L	48	SQFT
10	L & T CR	L	235	FT
15	RUTTING	L	203	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	244 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
08	WSTOKESST	W STOKES ST	2	2,663	21
	SECTION ID: 020	BRANCH FROM: MITCHELL AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,100	SUNIQUEID: 8295267df879456fbb86effba42cb653	BRANCH TO: LAUREN GLEN DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 44.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 47.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 75

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 79

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	18	SQFT
13	POTHOLE	M	1	COUNT
19	RAVELING	M	23	SQFT
20	WEATHERING	L	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	245 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
14	WSTOKESST	W STOKES ST	2	2,663	21
	SECTION ID: 020	BRANCH FROM: MITCHELL AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,100	SUNIQUEID: 8295267df879456fbb86effba42cb653	BRANCH TO: LAUREN GLEN DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 44.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 47.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 69

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 72

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	80	SQFT
6	DEPRESSION	M	176	SQFT
20	WEATHERING	L	2,100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	246 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
20	WSTOKESST	W STOKES ST	2	2,663	21
	SECTION ID	BRANCH FROM	SECTION COMMENTS		
	020	MITCHELL AV			
SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX	
2,100	8295267df879456fbb86effba42cb653	LAUREN GLEN DR	SECT PCI 44.2	SECT SCI 47.9	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 3	SAMP SCI 7

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	300	SQFT
3	BLOCK CR	M	764	SQFT
10	L & T CR	L	78	FT
15	RUTTING	H	287	SQFT
15	RUTTING	M	368	SQFT
20	WEATHERING	L	1,900	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	247 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WSTOKESST	W STOKES ST	2	1,431	23
	SECTION ID: 030	BRANCH FROM: LAUREN GLEN DR	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: cef03f4097314456906dcaefd145187a	BRANCH TO: HIGHLAND RIDGE DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 45.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 54.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 63

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 69

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	200	SQFT
7	EDGE CR	M	17	FT
10	L & T CR	M	23	FT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	248 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	WSTOKESST	W STOKES ST	2	1,431	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	LAUREN GLEN DR	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	cef03f4097314456906dcaefd145187a	HIGHLAND RIDGE DR	SECT PCI 45.5	SECT SCI 54.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 40	SAMP SCI 51

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	400	SQFT
1	ALLIGATOR CR	M	40	SQFT
3	BLOCK CR	L	1,900	SQFT
6	DEPRESSION	M	40	SQFT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	249 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
10	WSTOKESST	W STOKES ST	2	1,431	23
	SECTION ID: 030	BRANCH FROM: LAUREN GLEN DR	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: cef03f4097314456906dcaefd145187a	BRANCH TO: HIGHLAND RIDGE DR	SECTION PAVEMENT CONDITION INDEX: SECT PCI 45.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 54.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 33

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 45

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	400	SQFT
3	BLOCK CR	M	1,600	SQFT
6	DEPRESSION	L	16	SQFT
20	WEATHERING	L	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	250 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	W THOM ST	W THOM ST	2	469	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	S MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	2a737a35d09346869ecac9044144619a	S FRANKLIN ST	SECT PCI 83.9	SECT SCI 89.6

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 84	SAMP SCI 90

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
10	L & T CR	L	51	FT
11	PATCH/UT CUT	L	20	SQFT
11	PATCH/UT CUT	M	30	SQFT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	251 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	W THOM ST	W THOM ST	2	439	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	S FRANKLIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	67f807b35fe74d1084c8d603eb0cf498	S MYRTLE AV	SECT PCI 88.4	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 88	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	100	FT
10	L & T CR	L	86	FT
20	WEATHERING	L	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	252 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	W THOM ST	W THOM ST	2	104	24
	SECTION ID: 030	BRANCH FROM: S MYRTLE AV	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,400	SUNIQUEID: 55507f54f20a4a61a70ff126bb7a501d	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 71.9		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 87.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 72	SAMP SCI 88

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	M	1	SQFT
6	DEPRESSION	L	138	SQFT
9	LANE SH DROP	L	90	FT
10	L & T CR	L	160	FT
20	WEATHERING	H	200	SQFT
20	WEATHERING	M	2,200	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	253 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	W VANCE ST	W VANCE ST	2	414	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E VANCE ST/N MAIN ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	29a5d43071a342299530031 6ac8108d0	MILLER ST	SECT PCI 58.4	SECT SCI 63.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 58	SAMP SCI 64

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	310	SQFT
3	BLOCK CR	L	600	SQFT
11	PATCH/UT CUT	M	26	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	254 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	W VANCE ST	W VANCE ST	2	970	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	MILLER ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	3e6ee98f00ec4a55862bf57f33120701	MITCHELL AV	SECT PCI 47.5	SECT SCI 55.9

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 33	SAMP SCI 40

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	830	SQFT
1	ALLIGATOR CR	M	30	SQFT
10	L & T CR	L	120	FT
10	L & T CR	M	80	FT
11	PATCH/UT CUT	M	185	SQFT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	255 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
07	W VANCE ST	W VANCE ST	2	970	26
	SECTION ID: 020	BRANCH FROM: MILLER ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 3e6ee98f00ec4a55862bf57f33120701	BRANCH TO: MITCHELL AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 47.5		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 55.9

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 62

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 72

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	180	SQFT
10	L & T CR	L	420	FT
20	WEATHERING	L	2,600	SQFT



SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	256 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WALNUT ST	WALNUT ST	2	491	21

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	E THOM ST/S BOSTIAN S	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,100	b9a53abbcd534c6bb898be46d895fb05	ROSE AV	SECT PCI 94.2	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 94	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	25	FT
10	L & T CR	L	34	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	257 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WALNUT ST	WALNUT ST	2	393	19

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	ROSE AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,900	159ad954c4f54fa7b9273626468bda22	CENTRAL AV	SECT PCI 90.5	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 90	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	28	FT
10	L & T CR	L	62	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	258 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WALNUT ST	WALNUT ST	2	310	18

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	CENTRAL AV	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,800	18daee887da945eaac56383 62c51cba3	1ST AV	SECT PCI 81.2	SECT SCI 87.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 81	SAMP SCI 87

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	37	FT
10	L & T CR	L	94	FT
17	SLIPPAGE CR	L	54	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	259 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WALNUT ST	WALNUT ST	2	371	19
	SECTION ID: 040	BRANCH FROM: 1ST AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,900	SUNIQUEID: 9935d0a28ef24f39b3bec373a77fe813	BRANCH TO: 2ND AV	SECTION PAVEMENT CONDITION INDEX: SECT PCI 86.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 87

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
7	EDGE CR	L	6	FT
10	L & T CR	L	106	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	260 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WALNUT ST	WALNUT ST	2	281	18
	SECTION ID: 050	BRANCH FROM: 2ND AV	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,800	SUNIQUEID: 92363a9c06214fa097659b76fcf7babf	BRANCH TO: 3RD AV/WALNUT ST EX	SECTION PAVEMENT CONDITION INDEX: SECT PCI 93.4		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 100

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 93

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
9	LANE SH DROP	L	48	FT
10	L & T CR	L	22	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	261 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WALNUTSTEX	WALNUT ST EX	2	485	23

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	BIRCH CT	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,300	b497b9ccba74494fb468752be246b88f	3RD AV/WALNUT ST	SECT PCI 64.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 64	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
3	BLOCK CR	M	1,000	SQFT
10	L & T CR	L	30	FT
20	WEATHERING	M	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	262 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WALNUTSTEX	WALNUT ST EX	2	345	23
	SECTION ID: 020	BRANCH FROM: BOSTIAN RD/N CHAPEL S	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,300	SUNIQUEID: 44618c36a48c4744aeea453c6d7de2f1	BRANCH TO: BIRCH CT	SECTION PAVEMENT CONDITION INDEX: SECT PCI 35.4	SECTION STRUCTURAL CONDITION INDEX: SECT SCI 50.1	

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 35	SAMP SCI 50

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	300	SQFT
3	BLOCK CR	M	1,400	SQFT
10	L & T CR	L	35	FT
20	WEATHERING	M	2,300	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	263 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WASHGTONS	WASHINGTON ST	2	355	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CHINA GROVE SCHOOL	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	ff506ca006a744d9830e2870413e2b50	KLONDALE ST	SECT PCI 37.8	SECT SCI 60

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 38	SAMP SCI 60

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	150	SQFT
3	BLOCK CR	M	1,750	SQFT
10	L & T CR	L	245	FT
20	WEATHERING	M	2,600	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	264 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WASHGTONS	WASHINGTON ST	2	435	26
	SECTION ID: 020	BRANCH FROM: KLONDALE ST	SECTION COMMENTS:		
SAMPLE AREA (SQ FT): 2,600	SUNIQUEID: 032a3a827bea4ac498af82e4f9abed71	BRANCH TO: DEAD END	SECTION PAVEMENT CONDITION INDEX: SECT PCI 12.8		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 27.1

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 13

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 27

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	M	200	SQFT
3	BLOCK CR	M	1,150	SQFT
6	DEPRESSION	H	56	SQFT
10	L & T CR	M	200	FT
13	POTHOLE	L	1	COUNT
13	POTHOLE	M	6	COUNT
20	WEATHERING	M	1,000	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	265 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WSTSIDECIR	WESTSIDE CIR	2	1,765	17
	SECTION ID: 010	BRANCH FROM: HARRY ST	SECTION COMMENTS		
SAMPLE AREA (SQ FT): 1,700	SUNIQUEID: dcae378f3bf4407d9a54634881c11ac3	BRANCH TO: SHORT ST	SECTION PAVEMENT CONDITION INDEX: SECT PCI 86.2		SECTION STRUCTURAL CONDITION INDEX: SECT SCI 97.7

INSPECTION DATE: 7/11/23

INSPECTION COMMENTS: KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX: SAMP PCI 85

SAMPLE STRUCTURAL CONDITION INDEX: SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	L	108	SQFT
7	EDGE CR	L	73	FT
10	L & T CR	L	68	FT
20	WEATHERING	L	1,700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	266 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	WSTSIDECIR	WESTSIDE CIR	2	1,765	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	dcae378f3bf4407d9a54634881c11ac3	SHORT ST	SECT PCI 86.2	SECT SCI 97.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 90	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	M	4	SQFT
10	L & T CR	L	43	FT
20	WEATHERING	L	1,660	SQFT
20	WEATHERING	M	40	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	267 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
10	WSTSIDECIR	WESTSIDE CIR	2	1,765	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	dcae378f3bf4407d9a54634881c11ac3	SHORT ST	SECT PCI 86.2	SECT SCI 97.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 87	SAMP SCI 95

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
6	DEPRESSION	L	21	SQFT
10	L & T CR	L	55	FT
20	WEATHERING	L	1,600	SQFT
20	WEATHERING	M	100	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	268 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
14	WSTSIDECIR	WESTSIDE CIR	2	1,765	17

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	HARRY ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,700	dcae378f3bf4407d9a54634881c11ac3	SHORT ST	SECT PCI 86.2	SECT SCI 97.7

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 83	SAMP SCI 96

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
6	DEPRESSION	L	8	SQFT
9	LANE SH DROP	L	9	FT
10	L & T CR	L	4	FT
20	WEATHERING	L	1,000	SQFT
20	WEATHERING	M	700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	269 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WSTSIDECIR	WESTSIDE CIR	2	411	16

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	SHORT ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
1,600	8e0ec29b66f84067b121ec043c2c643d	HARRY ST	SECT PCI 79.2	SECT SCI 91.8

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 79	SAMP SCI 92

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	6	SQFT
6	DEPRESSION	L	15	SQFT
10	L & T CR	L	22	FT
19	RAVELING	L	48	SQFT
20	WEATHERING	L	1,000	SQFT
20	WEATHERING	M	700	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	270 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
01	WILSON ST	WILSON ST	2	169	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	DEAD END	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	0e16de942f6f4ecd823950a9f5539d58	LAUREL ST	SECT PCI 69.1	SECT SCI 100

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 69	SAMP SCI 100

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
2	BLEEDING	H	1	SQFT
3	BLOCK CR	L	420	SQFT
10	L & T CR	L	320	FT
19	RAVELING	H	12	SQFT
20	WEATHERING	M	2,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	271 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
02	WILSON ST	WILSON ST	2	382	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
020	LAUREL ST	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	65a010d39076444dabc1bdba3d6a9ba0	HICKORY NUT LN	SECT PCI 53.1	SECT SCI 67.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 53	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	300	SQFT
2	BLEEDING	M	8	SQFT
3	BLOCK CR	L	1,675	SQFT
10	L & T CR	L	70	FT
20	WEATHERING	M	2,800	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	272 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WILSON ST	WILSON ST	2	365	28

SECTION ID	BRANCH FROM	SECTION COMMENTS
030	HICKORY NUT LN	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,800	ff604416f7cf47e6a134efe5558021db	MITCHELL AV	SECT PCI 49.5	SECT SCI 67.1

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 50	SAMP SCI 67

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	300	SQFT
3	BLOCK CR	M	1,090	SQFT
10	L & T CR	L	69	FT
10	L & T CR	M	10	FT
19	RAVELING	M	50	SQFT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	273 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
03	WODHAVENST	WOODHAVEN ST	2	784	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CUL-DE-SAC	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8a312f15333b494a91a06a5d9407694d	S BOSTIAN ST	SECT PCI 59.6	SECT SCI 62.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 77	SAMP SCI 81

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	70	SQFT
7	EDGE CR	L	30	FT
10	L & T CR	L	128	FT

SAMPLE PHOTO

CHINA GROVE INSPECTION REPORT

BOOK	SHEET
1 OF 1	274 OF 274

SAMPLE NUMBER	BRANCH ID	BRANCH NAME	NUMBER OF LANES	LENGTH (FT)	WIDTH (FT)
06	WODHAVENST	WOODHAVEN ST	2	784	26

SECTION ID	BRANCH FROM	SECTION COMMENTS
010	CUL-DE-SAC	

SAMPLE AREA (SQ FT)	SUNIQUEID	BRANCH TO	SECTION PAVEMENT CONDITION INDEX	SECTION STRUCTURAL CONDITION INDEX
2,600	8a312f15333b494a91a06a5d9407694d	S BOSTIAN ST	SECT PCI 59.6	SECT SCI 62.3

INSPECTION DATE	INSPECTION COMMENTS
7/11/23	KCA 2023 Inspection

SAMPLE PAVEMENT CONDITION INDEX	SAMPLE STRUCTURAL CONDITION INDEX
SAMP PCI 42	SAMP SCI 43

SAMPLE DISTRESSES

#	DISTRESS	SV	QUANT	UNITS
1	ALLIGATOR CR	L	45	SQFT
1	ALLIGATOR CR	M	170	SQFT
10	L & T CR	L	80	FT
15	RUTTING	M	104	SQFT

SAMPLE PHOTO