Municipal Building 18500 W. 13 Mile Rd. 7:30 p.m.

AGENDA

Roll Call/Call to order

Pledge of Allegiance

Amendments to Agenda/Approve Agenda

Community Announcements

Public Comments on items not on the published agenda

Consent Agenda

- 1. Review and consider approval of minutes of a regular Council meeting held October 1, 2019.
- 2. Review and file bills recapped as of Monday, October 15, 2019.
- 3. Set Public Hearing date for reprogramming of Community Development Block Grant allocation for Program Year 2017 for Tuesday, November 19, 2019.

Business Agenda

- 1. Receive and File Audit Presentation by Plante Moran.
- 2. Public Hearing to receive comments on the proposed Middle School Guard House construction at Detroit Country Day School, 22305 W. 13 Mile Road.
- 3. Review and consider site plan approval and special land use request from Detroit Country Day School, 22305 W. 13 Mile Road, for Middle School Guard House.
- 4. Review and consider site plan approval request from Detroit Country Day School, 22305 W. 13 Mile Road, for tennis court upgrades.

Public comments

Manager's report

Council comments

Adjournment

Present: President Peddie; President Pro-Tem Abboud; Members: George, Hrydziuszko, Mooney, Mueller, and Nunez

Absent: None

Also Present: Village Manager, Wilson Village Clerk / Assistant Manager, Rutkowski Village Attorney, Ryan Public Safety Director, Torongeau

Peddie called the regular Council meeting to order at 7:30 p.m. in the Village of Beverly Hills municipal building at 18500 W. Thirteen Mile Road. The Pledge of Allegiance was recited by those in attendance.

AMENDMENTS TO AGENDA/APPROVE AGENDA

Motion by Mooney, second by Mueller, to approve the agenda as published.

Motion passed.

COMMUNITY ANNOUNCEMENTS None.

PUBLIC COMMENTS

None.

CONSENT AGENDA

Motion by Mooney, second by Nunez, be it resolved, the consent agenda is approved as published.

- 1. Review and consider approval of minutes of a regular Council meeting held September 17, 2019.
- 2. Review and file bills recapped as of Monday, September 30, 2019.
- 3. Set Public Hearing Date for November 5, 2019 to receive comments on proposed 2020 Community Development Block Grant funding allocation.

Roll Call Vote: Motion passed (7-0)

BUSINESS AGENDA REVIEW AND CONSIDER REQUEST FROM OUR LADY QUEEN OF MARTYRS TO USE VILLAGE STREETS FOR THEIR OKTOBERFEST 5K ON OCTOBER 5, 2019

Administration received a request from Our Lady Queen of Martyrs School to use Village streets for their annual Oktoberfest 5K run on Saturday, October 5, 2019. The race kicks off their annual charity event. The map of the 5K route was provided.

Michael Hughes, Pastoral Associate at Our Lady Queen of Martyrs, thanked the Village for their continued support of this event.

Motion by Hrydziuszko, second by Mooney be it resolved that the Village Council of Beverly Hills hereby authorizes Our Lady Queen of Martyrs School to hold their annual Oktoberfest 5K Race and use the Village streets and sidewalks on Saturday, October 5, 2019 outlined on the attached map provided that they submit the required Certificate of Liability Insurance naming the Village of Beverly Hills as an additional insured for the date of the event.

Roll call vote: Motion passed (7-0)

SECOND READING AND CONSIDERATION OF ORDINANCE NO. 370, AMENDING CHAPTER 41 OF THE MUNICIPAL CODE OF THE VILLAGE OF BEVERLY HILLS, "TRAFFIC," SECTIONS 41.08 AND 41.09, "MICHIGAN VEHICLE CODE," TO ADOPT SECTION 625(1)(C) OF THE MICHIGAN VEHICLE CODE BY REFERENCE AND TO PROVIDE PENALTIES FOR A VIOLATION OF THAT SECTION, PURSUANT TO PUBLIC ACT 7 OF 2012

Motion by Mueller, second by Mooney, that the Village of Beverly Hills Ordains:

Section 1.01. SHORT TITLE. This Ordinance shall be known as and may be cited as the "High BAC Amendment" to the 2002 Motor Vehicle Code Ordinance.

Section 2.01. STATEMENT OF PURPOSE. This is an ordinance to amend Chapter 41 of the Municipal Code of the Village of Beverly Hills, "Traffic", Section 41.09, "Michigan Vehicle Code", to adopt Section 625(1)(C) of the Michigan Vehicle code by reference and to provide penalties for a violation of that Section, pursuant to Public Act 7 of 2012.

Section 3.01. AMENDMENT TO SECTION 41.09. Chapter 41 of the Municipal Code of the Village of Beverly Hills, "Traffic", is hereby amended at Chapter 41.09, "Michigan Vehicle Code", Section 41.09 "Adoption of Code by Reference", which shall now read as follows:

"Section 41.09 Adoption of Code by Reference. The Michigan Vehicle Code, 1949 PA 300, MCL 257.1 to 257.923, as amended, is hereby adopted by reference. MCL 257.625(1)(C) of the Vehicle Code is specifically adopted by reference, pursuant to Public Act 7 of 2012."

Section 4.01. AMENDMENT TO SECTION 41.08(b). Chapter 41 of the Municipal Code of the Village of Beverly Hills, "Traffic", is hereby amended at Section 41.08(b), Violations, which shall now read as follows:

(b) Misdemeanor: The penalties provided by the Michigan Vehicle Code are adopted by reference. The Village of Beverly Hills may not enforce any provision of the Michigan Vehicle Code for which the maximum period of imprisonment is greater than 93 days; provided, however, that a violation of MCL 625(1)(C) is punishable by one or more of the following:

(i) Community service of not more than 350 hours.

(ii) Imprisonment for not more than 180 days.

(iii) A fine of not less than \$200.00 or more than \$700.00.

Section 5.01. SEVERABILITY. If any section, clause or provision of this Ordinance shall be declared to be inconsistent with the Constitution and laws of the State of Michigan and voided by

any court of competent jurisdiction, said section, clause or provision declared to be unconstitutional and void shall thereby cease to be a part of this Ordinance, but the remainder of this Ordinance shall stand and be in full force.

Section 6.01. SAVING CLAUSE. All proceedings pending and all rights and liabilities existing, acquired or incurred at the time this Ordinance takes effect are saved and may be consummated according to the law when they were commenced.

Section 7.01. REPEALER. Any Ordinance conflicting with this Ordinance be and the same is hereby repealed.

Section 8.01. EFFECTIVE DATE. This Ordinance shall become effective 20 days following its publication in The Eccentric, a newspaper circulated within said Village.

Motion passed.

REVIEW AND CONSIDER ANNUAL CONTRACT AND FUNDING REQUEST FROM NEXT BIRMINGHAM FOR SENIOR SERVICES

Next is a non-profit organization that works to identify and meet the needs of older adults by coordinating community resources to provide educational, recreational, and social programs. Next provides supportive outreach services and volunteer opportunities to seniors in the Village of Beverly Hills and the greater Birmingham School District community. The Village of Beverly Hills does not currently provide these opportunities on its own.

Village Council approved funding in the Fiscal Year 2019-20 budget in the amount of \$38,375.00 for contract services for senior services. A contract with Next requesting funding and outlining the services it provides was attached for review.

Greg Burry, Next, thanked the Council for its continued support of Next and the services they offer. Next has over 1,800 members and provides an invaluable service to the Beverly Hills community. Mooney thanked Burry for attending and asked he extend their gratitude to the Next Board for all that they do.

Motion by Mooney, second by Mueller be it resolved, the Village Council of Beverly Hills approves the funding request from Next in the amount of \$38,375.00 and authorizes Administration to sign the annual contract with Next for senior services. Funds for these services are available in account #101-747-891.

Roll Call Vote: Motion passed (7-0)

REVIEW AND CONSIDER RENEWING LIABILITY AND PROPERTY INSURANCE POLICY WITH MICHIGAN MUNICIPAL RISK MANAGEMENT AUTHORITY

Council will review and consider is the renewal of the Village's Liability Insurance Policy. This policy renews on November 1 of this year. The terms of this policy are the same as the current policy: A self-insured retention of \$75,000 for liability and, for vehicle and physical damage a self-insured retention of \$15,000 per vehicle and \$30,000 per occurrence. The liability limit is \$10,000,000 with various other limits listed on page 3. There is also a stop loss policy that would

THESE MINUTES ARE NOT OFFICIAL. THEY HAVE NOT BEEN APPROVED BY THE VILLAGE COUNCIL.

limit all liability in any village fiscal year to \$150,000. The cost for retaining this stop-loss policy is \$4,559. The stop-loss policy was provided.

The total cost for the liability policy for one year is \$132,927. This is a slight increase of our premium for last year of \$130,480. Our carrier, Michigan Municipal Risk Management Authority (MMRMA) is also requesting a contribution to our loss retention fund of \$40,000 upon renewal. The total premium, stop loss cost and retention fund contribution is \$177,486. With the contribution of \$40,000 to our loss retention fund the Village will have approximately \$300,000 retained to cover loses. At this time, we do not have any reserves set aside against our retention funds.

Upon renewal, the Village will be eligible for a disbursement through MMRMA. Our disbursement for this year is \$89,819. Given the current strong position of our retention fund Administration recommends that the disbursement amount be allocated back to the General Fund. Village Administration has reviewed the liability insurance renewal and recommends approval at this time.

Motion by Abboud, second by Hrydziuszko, be it resolved, the Village of Beverly Hills Council approve and authorize the Village Manager to sign the Michigan Municipal Risk Management Authority Liability and Property Insurance renewal effective November 1, 2019 through November 1, 2020 in the amount of \$177,486.00. Funds for these expenditures are available in accounts 101.248.910.00, 205.345.910.00, 205.346.910.00, 592.540.910.00.

Roll Call Vote: Motion passed (7-0)

REVIEW AND CONSIDER AWARDING CONTRACT TO HMC, LLC FOR THE 2019 CONCRETE ROAD IMPROVEMENT PROGRAM

The Village of Beverly Hills received bids on September 24, 2019 for the 2019 Concrete Road Improvement Program of which the major portion is for repair and replacement of concrete on Foxboro between Metamora Lane and Sleepy Hollow Lane. This will include drainage improvements, as well as surface improvements. Foxboro was chosen for replacement based on its low rating on the street rating assessment that was done approximately a year ago.

There were four bids received, copies of which were provided to Council, ranging from a low bid of \$285,813.33 to a high bid of \$388,004.00. HMC, LLC was the low bidder at \$285,813.33 for this project. HMC, LLC has not worked in the Village before so extensive research was done to vet this company's qualification and work quality. All information received indicates that this company is qualified to perform this work. The plan is to get the underground work and the pavement replacement completed before Thanksgiving with restoration done in the Spring of 2020.

The FY 19/20 budget for this project is \$600,000. Based on the low bid, the budget will have a balance of approximately \$300,000. We have researched the bid prices as submitted for concrete patching compared to other recent bids received in other communities by HRC and found them to be very reasonable. There are many areas in this same subdivision that require concrete patching.

Administration spoke to the contractor and he is willing to extend his price into the Spring of 2020 to do additional patching in this subdivision, therefore; it is recommended that we utilize the THESE MINUTES ARE NOT OFFICIAL. THEY HAVE NOT BEEN APPROVED BY THE VILLAGE COUNCIL.

balance of this budget for patching in this subdivision in the Spring of 2020. Administration recommends that the Village of Beverly Hills Council award the project to HMC, LLC for the 2019 Concrete Road Improvement Program. Funds for this project are available in 203-451-810.03.

Nunez inquired on recourse for the Village if there are completion problems with the contractor. Wilson explained that a bond verification is required at the time of bid, and that bond would then be secured prior to project start date and would be held if the work were not completed.

Motion by George, second by Hrydziuszko, be it resolved that Village Council award the 2019 Concrete Road Improvement Program to HMC, LLC in the amount of \$285,813.33 and an additional \$300,000.00 in patching for this subdivision.

Roll Call Vote: Motion passed (7-0)

PUBLIC COMMENTS

None.

MANAGER'S REPORT Cub Scout Pack 1049

The Village was happy to host Cub Scout Pack 1049 from Bingham Farms Elementary at the Village Offices and Public Safety Building for a tour and discussion about local government on Tuesday, October 1st.

FY 2018-19 Audit and OPEB Reports – Village Administration, especially Finance Director McCarthy, has been working with the auditors to wrap up the 2018-19 Audit report. We anticipate having the full audit report presentation to Council at our regular meeting of October 15. As a part of this report the Village is updating the Other Post-Employment Benefits (OPEB) actuarial report. This has taken a bit longer than anticipated as the Village is ahead of many other municipalities in the funding and paying for retiree health care benefits.

As Council may recall, in a previous budget year, the Village began utilizing existing Retiree Health Care assets to pay for current costs. This was done by paying all benefit costs from the Retiree Health Care Trust Fund while making fixed annual contributions to that fund. The fixed annual contribution was established at \$400,000 split between the General Fund and the Public Safety Fund. Our OPEB auditors are examining all the data to determine the adequacy of this fixed amount through at least 2040. The Village was able to make the change in how these costs were met due to the aggressive pre-funding of these liabilities in previous years and the fact that retiree health care benefits of this type have been "closed" to new hires as of 2013. Employees hired after 2013 now have individual retiree health care accounts to utilize upon retirement to cover health care costs. Along with annual audit results, Village Administration will review the results of the OPEB audit with Council as soon as they are available.

Public Safety Boiler Replacement – The boiler replacement project at the Public Safety Building is proceeding well. Public Safety Administration was able to secure grant funding from Consumers Energy in the amount of \$4,678.20 to help offset the costs of these improvements. I have included a copy of the grant award letter for your review.

THESE MINUTES ARE NOT OFFICIAL. THEY HAVE NOT BEEN APPROVED BY THE VILLAGE COUNCIL.

Mayors Association Dinner – Council members should have received their invitation to the October South Oakland Mayors Association Dinner on Wednesday, October 16th. The Village is jointly hosting this event along with the cities of Birmingham, Berkley, Lathrup Village and Royal Oak Township. Newly appointed Oakland County Executive Dave Coulter has agreed to be the guest speaker at this event.

Vehicle-Deer Crashes

Clerk Rutkowski was able to work with SEMCOG to create a map of reported vehicle crashes involving deer over the last 5 years. The majority of the crashes occurred near the 13 Mile and Lahser intersection, which is in close proximity to the river.

COUNCIL COMMENTS

Hrydziuszko reported the Planning Commission subcommittees continue to make progress, and the tennis court updates at Detroit Country Day School were approved.

Mueller invited residents to attend the Parks and Recreation clean up event on Saturday, October 5 in Beverly Park. He thanked Administration for the completion of the crosswalk at Evergreen and Groves High School.

Nunez expressed his concern about the rate of progress at the BP Gas station renovation. Wilson reported that some work has been done, and Administration continues to closely monitor the project.

Abboud reported on the various committees he represents the Village at and updated that the finance committee continues to meet to develop a plan for the millage proposal in 2020.

Motion by Mooney, second by George, to adjourn the meeting at 8:14 pm.

Motion passed.

Lee Peddie Council President Kristin Rutkowski Village Clerk Elizabeth Lyons Recording Secretary



TO PRESIDENT PEDDIE & MEMBERS OF THE VILLAGE COUNCIL. THE FOLLOWING IS A LIST OF

EXPENDITURES FOR APPROVAL. ACCOUNTS PAYABLE RUN FROM 9/30/2019 THROUGH 10/14/2019.

ACCOUNT TOTALS:

101	GENERAL FUND		\$101,716.49
202	MAJOR ROAD FUND		\$25,420.52
203	LOCAL STREET FUND		\$26,643.86
205	PUBLIC SAFETY DEPARTMENT FUND		\$138,234.05
592	WATER/SEWER OPERATION FUND		\$413,562.49
701	TRUST & AGENCY FUND		\$1,911.45
		TOTAL	\$707,488.86
	MANUAL CHECKS- COMERICA		\$0.00
	MANUAL CHECKS- INDEPENDENT		\$67.50
	ACCOUNTS PAYABLE		\$707,488.86
		GRAND TOTAL	\$707,556.36

Bank Check

Vendor

Check Date

CHECK REGISTER FOR VILLAGE OF BEVERLY HILLS CHECK DATE FROM 10/14/2019 - 10/14/2019

Vendor Name

Page: 1/2

Amount

Invoice Vendor

10/14/2019 COM 8101 3284 APELIED IMACING APELIED IMACING 10/14/2019 COM 81018 31004 BATTERIES FUUS SARGO OFFICE SUPPLY CO. 10/14/2019 COM 81020 ATISC DATTERIES FUUS SARGO OFFICE SUPPLY CO. 10/14/2019 COM 81021 30020 BATTERIES FUUS SARGO OFFICE SUPPLY CO. 10/14/2019 COM 81021 30020 BALLE TIRE SARGO OFFICE SUPPLY CO. 10/14/2019 COM 81024 5071 BLUE CROSS HUE SARGO CIN BLOOKTELLO CONSTRUCTION INC 10/14/2019 COM 81026 49980 CLG FUBLIGHING CILANSE 10/14/2019 COM 81028 50332 CILTY OF BITMINGHM CILANSE 10/14/2019 COM 81029 51343 COMLART CULANSE CILANSE 10/14/2019 COM 81033 55589 COMLART TIMENSER CILANSE 10/14/2019 COM 81034 50319 DTE ENERGY DTE ENERGY DTE ENERGY DTE ENERGY <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>						
10/14/2013 COM 01013 31160 ALLARCE MONLE HEALTH ALLARCE MONLE HEALTH ALLARCE	nk COM COME	RICA				
10/14/2013 COM 01013 31160 ALLARCE MONLE HEALTH ALLARCE MONLE HEALTH ALLARCE	14/2019	COM	81012	MISC	ABOVE BOARD CONSTRUCTION ABOVE BOARD CONSTRUCTION	300.00
11/14/2019 COM 01/14 24/14 ANTEREY VAN HORN ANTERY VAN HORN						148.00
10/14/2019 COM 81015 RLEC APEX MODELING INC APEX						100.00
10/14/2019 COM 61015 31164 AFOLD FINE AFEARAGUE AFOLD FINE AFEARAGUE AFOLD FINE AFEARAGUE 10/14/2019 COM 61015 51364 ARROW OFTICE SUTURE CO. ARROW OFTICE SUTURE CO. ARROW OFTICE SUTURE CO. 10/14/2019 COM 61013 51364 ARROW OFTICE SUTURE CO. ARROW OFTICE SUTURE CO. ARROW OFTICE SUTURE CO. 10/14/2019 COM 61024 MISC DEALE TIRE DELLE TIRE						300.00
10/14/2015 COM 8:017 53224 ATTLED INAGENE ATTLED INAGENE 10/14/2015 COM 8:018 3:000 EARDY DEFICE SUPER (C). EARDY DEFICE SUPER (C). 10/14/2015 COM 8:018 3:000 EARDY DEFICE SUPER (C). EARDY DEFICE SUPER (C). 10/14/2015 COM 8:021 3:000 EARDY DEFICE SUPER (C). EARDY DEFICE SUPER (C). 10/14/2015 COM 8:022 5:001 EDUCE TITLES ENDOWERING TITLES FUEL SUPER (C). 10/14/2015 COM 8:023 5:001 EDUCE TITLES ENDOWERING TITLES COM SUPER TITLES 10/14/2015 COM 8:023 5:001 EDUCE TITLES COM SUPER TITLES COM SUPER TITLES 10/14/2015 COM 8:023 5:001 EDUCE TITLES COM SUPER TITLES COM SUPER TITLES 10/14/2015 COM SUPER TITLES SUPER TITLES COM SUPER TITLES COM SUPER TITLES COM SUPER TITLES 10/14/2015 COM SUPER TITLES SUPER TITLES COM SUPER TITLES COM SUPER TITLES 10/14/2015 COM S						1,855.00
10/14/2019 COM BIG18 JARGM OFFICE SUPERY CO. ARGM OFFICE SUPERY CO. 10/14/2019 COM BIG19 JARGM OFFICE SUPERY CO. ARGM OFFICE SUPERY CO. 10/14/2019 COM BIG20 HISC BCCM MOME INTROVEMENT ECM MOME INTROVEMENT 10/14/2019 COM BIG20 HISC BCCM MOME INTROVEMENT ECM MOME INTROVEMENT 10/14/2019 COM BIG20 HISC BLOWE FILE CONSTRUCTION BLOWE SHILLD CONSTRUCTION 10/14/2019 COM BIG20 SIG10 BLOWE CONSTRUCTION BLOWE CONSTRUCTION 10/14/2019 COM BIG20 SIG302 CEX FINITIATING CCI CONSTRUCTION 10/14/2019 COM BIG20 SIG302 CEX FINITIATING CCI CONSTRUCTION 10/14/2019 COM BIG31 SIG302 CEX FINITIATING CCI CONSTRUCTION 10/14/2019 COM BIG31 SIG310 COMEAJ EQUIPMENT CO LICCONSTRUCTION BIG20 10/14/2019 COM BIG31 SIG310 COMEAJ EQUIPMENT CO LICCONSTRUCTION BIG20 10/14						131.47
10/14/2019 COM 81220 NISC EICH MODE INFROVEMENT ECH MODE INFROVEMENT 10/14/2019 COM 81021 51409 EDULE TILE ALLE EDULE ALLE EDULE ALLE <td< td=""><td></td><td>COM</td><td>81018</td><td>51802</td><td>ARROW OFFICE SUPPLY CO. ARROW OFFICE SUPPLY CO.</td><td>225.88</td></td<>		COM	81018	51802	ARROW OFFICE SUPPLY CO. ARROW OFFICE SUPPLY CO.	225.88
10/14/2019 COM 81021 3920 BELLE THE BELLE THE BELLE THE 10/14/2019 COM 81024 51409 BEVERLY HILLS ACE BEVERLY HILLS ACE BEVERLY HILLS ACE 10/14/2019 COM 81024 40960 BECOMPTEID CONSTRUCTION BLOOMESTRUCTION 10/14/2019 COM 81026 40960 BECOMPTEID CONSTRUCTION BLOOMESTRUCTION 10/14/2019 COM 81026 53392 CIEVY OF BENERITY ALS INCOMPTENT ALS INTERNATION BLOOMESTRUTY 10/14/2019 COM 81028 53392 CIEVY OF BENERITY CIEVANDE 10/14/2019 COM 81031 54300 COMPLETE INTERNATION ALS INTERNATION HEIDINER 10/14/2019 COM 81032 54391 COMPLETE INTERNATION ALS INTERNATION BUDDETEINER 10/14/2019 COM 81034 54919 DTE DERROY DTE DERROY DTE DERROY 10/14/2019 COM 81038 54919 DTE DERROY DTE DERROY DTE DERROY 10/14/2019 COM 81038 600600<	14/2019	COM	81019	33004	BATTERIES PLUS BATTERIES PLUS	71.35
10/14/2019 COM S1022 51403 DEVERLY HILLS ACS DEVERLY HILLS ACS 10/14/2019 COM S1024 52071 BLOUE CNUSS BLUE SHIELD BUD CONSTRUCTION, INC. 10/14/2019 COM S1024 53071 BLOUE CNUSS BLUE SHIELD BUD CONSTRUCTION, INC. 10/14/2019 COM S1025 45337 CONTAS CONSTRUCTION, INC. 10/14/2019 COM S1027 55337 CLEANNEY CLEANNEY 10/14/2019 COM S1029 55323 CLEANNEY CLEANNEY 10/14/2019 COM S1029 55323 CLEANNEY CLEANNEY 10/14/2019 COM S1030 04560 COMEAD COMCAST 10/14/2019 COM S1033 55339 COMEAD COMEAD COMCAST 10/14/2019 COM S1035 DTE ENTERY DTE ENTERY DTE ENTERY 10/14/2019 COM S1037 60173 ELIABATY HILLS ACS DEVENCY 10/14/2019 COM S1043 DTE ENTERY	14/2019	COM	81020	MISC	BCM HOME IMPROVEMENT BCM HOME IMPROVEMENT	200.00
10/14/2019 COM 81023 HISC PLOWETELD CONFIGUETON PLOWETELD CONFIGUETON 10/14/2019 COM 81025 HISC HOA CONSTRUCTION, INC HOA CONSTRUCTION, INC 10/14/2019 COM 81025 HISC HOA CONSTRUCTION, INC HOA CONSTRUCTION, INC 10/14/2019 COM 81025 HISC HOA CONSTRUCTION, INC HOA CONSTRUCTION, INC 10/14/2019 COM 81026 HISC HIAC CONSTRUCTION, INC HOA CONSTRUCTION, INC 10/14/2019 COM 81030 HIAS COMPAND CLEANNEY 10/14/2019 COM 81031 HIAS COMPAND COMPAND 10/14/2019 COM 81032 HIAS COMPAND COMPAND HIAS HIAS 10/14/2019 COM 81033 HIAS HIAS HIAS HIAS HIAS HIAS 10/14/2019 COM 81033 HIAS	14/2019	COM	81021		BELLE TIRE BELLE TIRE	38.98
10/14/2019 COM 81024 52071 FLUE CROSS FILE SHTELD FLUE CROSS FILE SHTELD 10/14/2019 COM 81025 SIGE 49980 CGS PUBLISHING CGS PUBLISHING 10/14/2019 COM 81026 49980 CGS PUBLISHING CGS PUBLISHING 10/14/2019 COM 81026 59347 CIMISS CORPORTING CCM CARCENT 10/14/2019 COM 81026 50338 CITY OF FIRMINGEM CITICS CORRECT 10/14/2019 COM 81033 59589 COMEAU EQUIPMENT CO INC. COMEAU TECOMPLETE INTERACTIVE TECOMPLETE 10/14/2019 COM 81034 59589 COME # MIN COME AND 10/14/2019 COM 81034 59519 DIE BINERAL DIE BINERAL 10/14/2019 COM 81038 50519 DIE BINERAL DIE BINERAL 10/14/2019 COM 81038 60501 EDROBET CUSTOR BUILINGEN MUTICEN NUTURENT CO INC. 10/14/2019 COM 81038 60513 ELLIZABENT KIERE ELLIZABENT KIERE 10/14/2019				51409		29.50
10/14/2015 COM \$1025 HISC BOA CONSTRUCTION, INC BOA CONSTRUCTIO						200.00
10/14/2019 COM 81026 49980 CoS FUELSEING CAS FUELSEING CAS FUELSEING 10/14/2019 COM 81027 59347 CITWIS CORPORTION #31 CITWIS CORPORTION #31 10/14/2019 COM 81028 59323 CITWI OF DEMINDRIMM CITWING CORPORTION #31 10/14/2019 COM 81029 53233 CITMING CORPORTION #31 10/14/2019 COM 81033 59589 CORPANTER TO INCOMENT TO INCOMENT ON THE COMPLETE INTERCTURE TECC 10/14/2019 COM 81034 59589 CORPANTER INTERCOMPLETE INTERCTURE TECC 10/14/2019 COM 81035 59199 DTE ENDERGY DTE ENDERGY 10/14/2019 COM 81035 501919 DTE ENDERGY DTE ENDERGY 10/14/2019 COM 81036 50135 ELIZIANTER INTERCOMPLETEIN INTERCOMENT 10/14/2019 COM 81040 30635 ELIZIANTER ELIZIANTER 10/14/2019 COM 81044 59137 ELIZIANTER ELIZIANTER 10/14/2019 COM 81044 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td>34,402.30</td>						34,402.30
10/14/2019 COM 9122/ S9347 CITYLOS CORRONATION #31 CITYLOS TINAS CORTORATION #31 10/14/2019 COM 81029 S9323 CITYLOS TENNINGRAM CITYLOS TENNINGRAM 10/14/2019 COM 81039 S9323 CIENNINET CURCART 10/14/2019 COM 81031 04500 COMEAN CUIDNENT COLING. 10/14/2019 COM 81033 04500 COMEAN EULENNET COMEAN EULENNET 10/14/2019 COM 81034 MISC PREMERY DITE INTREGY DITE INTREGY DITE INTREGY 10/14/2019 COM 81035 51385 DTE INTREGY DITE INTREGY DITE INTREGY 10/14/2019 COM 81038 60017 EINTREGY DITE INTREGY DITE INTREGY 10/14/2019 COM 81038 60017 EINTREGY INTREGY DITE INTREGY 10/14/2019 COM 81048 MISC POUNDATION SYSTEMS OF INTUNATION SYSTEMS OF INTU						500.00
10/14/2015 COLAINSE CLEANNEE CLEANNEE CLEANNEE 10/14/2019 COM 81030 04500 COMEAT COMMAT 10/14/2019 COM 81031 04500 COMEAT COMMAT 10/14/2019 COM 81031 04500 COMEAT COMMAT 10/14/2019 COM 81033 59389 COME & MAIN COME & ANN 10/14/2019 COM 81033 59389 COME & MAIN COME & ANN 10/14/2019 COM 81033 50919 DTE ENERGY DTE ENERGY DTE ENERGY 10/14/2019 COM 81033 60017 ELSTERPT HUME ELSTERPT HUME 10/14/2019 COM 81043 50919 DETE ENERGY ELSTERPT HUME 10/14/2019 COM 81041 50987 ERIC KORNIG ELSTERPT HUME 10/14/2019 COM 81044 60130 FROM THE DESK OF LIZ LYCRON HUMENTSSYSTEMS OF MI 10/14/2019 COM 81046 60130 FROM THE DESK OF LIZ LYCRON HUMENTSSYSTEMS OF M					C&G PUBLISHING C&G PUBLISHING	106.00
10/14/2015 COLAINSE CLEANNEE CLEANNEE CLEANNEE 10/14/2019 COM 81030 04500 COMEAT COMMAT 10/14/2019 COM 81031 04500 COMEAT COMMAT 10/14/2019 COM 81031 04500 COMEAT COMMAT 10/14/2019 COM 81033 59389 COME & MAIN COME & ANN 10/14/2019 COM 81033 59389 COME & MAIN COME & ANN 10/14/2019 COM 81033 50919 DTE ENERGY DTE ENERGY DTE ENERGY 10/14/2019 COM 81033 60017 ELSTERPT HUME ELSTERPT HUME 10/14/2019 COM 81043 50919 DETE ENERGY ELSTERPT HUME 10/14/2019 COM 81041 50987 ERIC KORNIG ELSTERPT HUME 10/14/2019 COM 81044 60130 FROM THE DESK OF LIZ LYCRON HUMENTSSYSTEMS OF MI 10/14/2019 COM 81046 60130 FROM THE DESK OF LIZ LYCRON HUMENTSSYSTEMS OF M					CINTAS CORPORATION #31 CINTAS CORPORATION #31	62.02
10/14/2019 COM \$1031 OBASIS COMEAST CONCAST 10/14/2019 COM \$1031 04900 COMPLETE INTERACTIVE TEC 10/14/2019 COM \$1033 \$9338 COMPLETE INTERACTIVE TEC INTERACTIVE TEC 10/14/2019 COM \$1033 \$9639 COME & MAIN COME & MAIN COME & MAIN 10/14/2019 COM \$1033 \$0137 DETER INTERACTIVE TEC ENTRON 10/14/2019 COM \$1033 \$60107 PERTERNON DETER INTERNON 10/14/2019 COM \$1033 \$60107 PERTERNON ELTABETR XIME ELTABETR XIME 10/14/2019 COM \$1040 \$9897 RINI LAPERE ENTER NORATION SYSTEMS OF MILLAPERE 10/14/2019 COM \$1041 \$9897 RINI LAPERE ENTER NORATION SYSTEMS OF MILLAPERE 10/14/2019 COM \$1042 S9921 FEDEX OFFICE INTERNATION SYSTEMS OF MILLAPERE 10/14/2019 COM \$1043 MISS					CITI OF DINHINGHAM CITI OF DINHINGHAM	86,331.75
10/14/2019 COM 81331 04500 COMEAU EQUIPMENT CO INC. CONFLETE LITERACTIVE TEC 10/14/2019 COM 81332 59589 COMELETE INTERACTIVE TEC COMPLETE INTERACTIVE TEC 10/14/2019 COM 81333 59589 COMELETE INTERACTIVE TEC COMPLETE INTERACTIVE TEC 10/14/2019 COM 81334 59589 COME 6 MAIN COME 6 MAIN <td></td> <td></td> <td></td> <td></td> <td></td> <td>858.00</td>						858.00
10/14/2019 COM 81032 9338 COMPLETE INTERACTIVE TEC COMPLETE INTERACTIVE TEC 10/14/2019 COM 81033 MISC DROBOT CUSTOM BUILDING I DURAGE CUSTOM BUILDING I 10/14/2019 COM 81035 SD919 DTE ENERGY DTE ENERGY 10/14/2019 COM 81036 S1335 DTE ENERGY DTE ENERGY 10/14/2019 COM 81036 60010 EDRAGT DTE ENERGY 10/14/2019 COM 81038 60010 EDRAGT EDRAGT EDRAGT 10/14/2019 COM 81041 59897 ENTH LAPENE EDRAGT EDRAGT<						125.85
10/14/2019 COM 81033 55698 CORE 4 MAIN CORE 4 MAIN 10/14/2019 COM 81034 MISC DPG FUNCT CUSTOM BUILDING IDENOS IDUSTON USURG MULTURS 10/14/2019 COM 81035 50919 DTE ENREGY DTE ENREGY DTE ENREGY 10/14/2019 COM 81036 60017 EASTERN MICHIGAN UNIVERSESTEN MICHIGAN UNIVERS 10/14/2019 COM 81039 60173 ELIZABETH KIME ELIZABETH KIME 10/14/2019 COM 81040 306857 ERIN LAPRER ENN LAPRER 10/14/2019 COM 81041 39897 ERIN LAPRER ENN LAPRER 10/14/2019 COM 81045 59613 GERCONT MICHINESCO FUELD EDED CREDIT 10/14/2019 COM 81045 59613 GERCONT MICHINESCO FUELD ERIN LAPRER 10/14/2019 COM 81046 60174 HANS EICHEL JR ENS EICHEL JR ENS EICHEL JR 10/14/2019 COM 81046 60174 HANS EICHEL JR ENS EICHEL SR 10/14/2019 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						
10/14/2019 COM 81034 MISC DROBOT CUSTOM BUILDING I DURGET CUSTOM BUILDING I 10/14/2019 COM 81036 51385 DTE ENREGY DTE ENREGY DTE ENREGY 10/14/2019 COM 81036 60017 EASTERM MICHIGANU UNIVEREASTERN UNIVERSU 10/14/2019 COM 81041 36685 ERIC KOENIG ELICASTERN KINE 10/14/2019 COM 81042 59721 FEDEX OFFICE ENTURING NIVERON MICHIGANU SYSTEMS OF MI 10/14/2019 COM 81043 61030 FROM THE DESK OF LIZ LYC MICHIGANU SYSTEMS OF MI 10/14/2019 COM 81044 61130 FROM THE DESK OF LIZ LYC MICHIGANU SYSTEMS OF MICHIGANU SY						101.92
10/14/2019 COM 81035 50919 DTE ENERGY DTE ENERGY 10/14/2019 COM 81036 60017 EASTERN MICHIGAN UNIVERSESTENN MICHIGAN UNIVERS 10/14/2019 COM 81038 60017 EASTERN MICHIGAN UNIVERS 10/14/2019 COM 81039 60173 ELIZABETH KIME ELIZABETH KIME 10/14/2019 COM 81041 59897 FRIN LAPERE FDEX CONSIG 10/14/2019 COM 81043 MISC FOUNDATION SYSTEMS OF MICOUNDATION SYSTEMS OF MI 10/14/2019 COM 81044 60130 FRON THE DESK OF LIZ LYCERON THE DESK OF CHIZ 10/14/2019 COM 81046 50174 GRON FILE LINCERON THE DESK OF LIZ LYCERON THE DESK OF CONSTRESS 10/14/2019 COM 81047 31202 HONS DEPOT CREDIT SERVICHONE DE						154.71 300.00
10/14/2019 COM 91036 51385 DTE ENERGY DTE ENERGY 10/14/2019 COM 81033 60060 EDWARD POCOCK EDWARD POCOCK 10/14/2019 COM 81033 60060 EDWARD POCOCK EDWARD POCOCK 10/14/2019 COM 81040 36655 ERIC KORNIG ERIC KOENIG 10/14/2019 COM 81042 39721 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81042 39721 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81044 60130 FROM THE DESK OF LIC UCROM THE DESK OF LIC INCRIMENTEL 10/14/2019 COM 81046 60174 HANS ETCHEL JR HANS ETCHEL JR 10/14/2019 COM 81047 31202 HOW EDFOT CREDIT SERVICEME DEFOT CREDIT SERVIC 10/14/2019 COM 81049 99301 HUNT SIGN COMPANY 10/14/2019 COM 81043 39010 HUNT SIGN COMPANY 10/14/2019 COM 81053 59423 JGR SUPELY, INC JGR SUPELY, I						
10/14/2019 COM 81037 60017 EASTERN MICHIGAN UNIVERS 10/14/2019 COM 81039 60173 ELIZABETH KIME ELIZABETH KIME 10/14/2019 COM 81040 30685 ERIC KORNIG ERIC KORNIG ERIC KORNIG 10/14/2019 COM 81041 59897 ERIN LAPERE ERIN LAPERE 10/14/2019 COM 81042 59721 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81045 59613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81045 59613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81046 60174 HANS EICHEL JR HANS EICHEL JR 10/14/2019 COM 81049 59301 HUGH CONNOLLY HUGH CONNOLLY 10/14/2019 COM 81051 59930 JUNROCORP HYDROCORP 10/14/2019 COM 81053 59423 JARES HEALY JARES HEALY 10/14/2019 COM 81055 35521 <td></td> <td></td> <td></td> <td></td> <td></td> <td>2,417.39</td>						2,417.39
10/14/2019 COM 81038 60060 EDWARD POCOCK EDWARD POCOCK 10/14/2019 COM 81090 36655 ERIC KORNIG ERIC KORNIG 10/14/2019 COM 81091 59871 ERIC KORNIG ERIC KORNIG 10/14/2019 COM 810942 59721 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 810943 MISC FOUNDATION SYSTEMS OF MIDATION SYSTEMS OF MI 10/14/2019 COM 810944 60130 FROM THE DESK OF LIZ LOFFOM THE DESK OF LIZ LYCENOM THE DESK OF LIZ LYCE						3,437.79
10/14/2019 COM 81049 60173 ELIZABETH KIME ELIZABETH KIME 10/14/2019 COM 81041 59897 ERIN LAPERE ERIN LAPERE ERIN LAPERE 10/14/2019 COM 81042 59721 FEDEX OFFICE FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81043 MISC FOUNDATION SYSTEMS OF MICTON THE DESK OF LIZ 10/14/2019 COM 81045 59613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81046 60174 HANE EICHEL JR HANE SICHEL JR 10/14/2019 COM 81047 31202 HOME DEPOT CREDIT SERVICHOME DEPOT CREDIT SERVIC 10/14/2019 COM 81048 08500 HUBBELL ROTH & CLARK INCHBEELL RN 10/14/2019 COM 81051 58950 HYDROCORP HYDROCORP 10/14/2019 COM 81055 30521 JAMES HEALY JAMES HEALY 10/14/2019 COM 81056 60172 JOHN KILLERON JOHN KILLIKON KARENT CHIDINI 10/14/2019 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
10/14/2019 COM 81040 30685 ERIC KORNIG ERIC KORNIG 10/14/2019 COM 81042 59921 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81043 MISC FOUNDATION SYSTEMS OF MI FOUNDATION SYSTEMS OF MI 10/14/2019 COM 81044 60130 FROM THE DESK OF LIZ LYCFROM THE DESK OF LIZ LYCFROM THE DESK OF LIZ LYCTROM THE DESK OF LYCTROM THE DESK OF LIZ LYCTROM THE DESK OF LIZ LYCTROM THE DESK OF LYCTROM THE DESK						100.00
10/14/2019 COM 81041 59897 DENN LAPERE ENIN LAPERE 10/14/2019 COM 81043 MISC FOUNDATION SYSTEMS OF MICTUNINTON SYSTEMS OF MI 10/14/2019 COM 81043 MISC FOUNDATION SYSTEMS OF MISC OF MISC OF MISC OF MISCON THE DESK OF LIZ LYCKOM THE DESK OF LYCKOM TH						200.00
10/14/2019 COM 81042 S9721 FEDEX OFFICE FEDEX OFFICE 10/14/2019 COM 81044 60130 FROM THE DESK OF LIZ LYCPROM THE DESK OF LIZ LYC 10/14/2019 COM 81045 S9613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81046 60174 HANS EICHEL JR HANS EICHEL JR 10/14/2019 COM 81047 31202 HOME DEPCT CREDIT SERVIC COMPC ACENT SERVIC 10/14/2019 COM 81048 08500 HUBECLE ACHAR INCHUBELL ROTH & CLARK INCHUBELL R						1,050.00
10/14/2019 COM 81043 MISC FOUDATION SYSTEMS OF MITPOUNDATION SYSTEMS OF MI 10/14/2019 COM 81045 59613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81046 6017 HANS EICHEL JR 10/14/2019 COM 81046 6017 HANS EICHEL JR 10/14/2019 COM 81046 08100 HUBBELL ROTH & CLARK INCHUBBELL JR 10/14/2019 COM 81049 93301 HUBBELL ROTH & CLARK INCHUBBELL COMPANY 10/14/2019 COM 81051 59910 HUBRIC COMPANY HUBRIC COMPANY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81054 59324 JGCR SUPLY, INC. JCR SUPLY, INC. 10/14/2019 COM 81055 50321 JOHN MILLIEON JOHN MIRCARCH CHIONN 10/14/2019 COM 81055 51339 KERTON PUBLICATION GROUTERATON P	,					141.52
10/14/2019 COM 81044 60130 FROM THE DESK OF LIZ LYC FROM THE DESK OF LIZ LYC 10/14/2019 COM 81046 60174 HANS BICHEL JR HANS EICHEL JR 10/14/2019 COM 81047 31202 HOME DEFOC CREDIT SERVIC HOME DEFOT CREDIT SERVIC 10/14/2019 COM 81048 08500 HUBBELL ROTH & CLARK INC HUBBELL ROTH & CLARK INC 10/14/2019 COM 81051 59910 HUBT COMPANY HUBT COMOLIV 10/14/2019 COM 81052 39070 J, H. HART URBAN FORESTRY J. H. HART URBAN FORESTRY J. H. HART 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81055 39521 JOINN NILLIRON JORN NILLIRON 10/14/2019 COM 81055 39521 JOINN NILLIRON JOINN NILLIRON 10/14/2019 COM 81055 39521 JOINN NILLIRON JORN NILLIRON 10/14/2019 COM 81057 59920 KAREN MCCONALD KAREN MACCONALD 10/14/2019 COM 81						16.20
10/14/2019 COM 81045 59613 GREGORY MACKENZIE GREGORY MACKENZIE 10/14/2019 COM 81047 31202 HOME DEFOT CREDIT SERVICHOME DEFOT CREDIT SERVIC 10/14/2019 COM 81048 08500 HUBBELL POTH & CLARK INCHUBBELL POTH & CLARK INCHUBENTY 10/14/2019 COM 81050 59010 HUBRCLENTY HUGH CONNOLLY HUGH CONNOLLY 10/14/2019 COM 81052 39070 J.H. HART URBAN FORESTRYJ.H. HART URBAN FORESTRY 10/14/2019 COM 81055 30521 JOHN OR MARCDONALD JAMES HEALY 10/14/2019 COM 81056 60172 JOHN OR MARCDONALD KAREN MACCONALD 10/14/2019 COM 81057 59920 KARRN MACDONALD KAREN MACCONALD 10/14/2019 COM 81056 51939 KEATON PUBLICATION GROUE KARAN MACDONALD 10/14/2019 COM 81066 60077 KRISTIN RUTKONSKI KRIS						900.00
10/14/2019 COM 81046 60174 HANS EICHEL JR HANS EICHEL JR 10/14/2019 COM 81048 08500 HUBBELL FOTH 4 CLARK INC 10/14/2019 COM 81049 5301 HUGH CONNOLLY HUGH CONNOLLY 10/14/2019 COM 81049 53010 HURT SIGN COMPANY HURT SIGN COMPANY 10/14/2019 COM 81051 58950 HYDROCORP HYDROCORP 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81055 50172 JOHN ON MARCARET CHIONIJOH ON MARCARET CHIONI 10/14/2019 COM 81065 51938 KEATON PUBLICATION GROUFEKATON PUBLICATION GROUF 10/14/2019 COM 81066 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81066 51792 LE						276.75
10/14/2019 COM \$1047 31202 HOME DEPOT CREDIT SERVICHOME DEPOT CREDIT SERVIC 10/14/2019 COM \$1048 08500 HUBBELL ROTH & CLARK INCHUBELL ROTH & CLARK INC 10/14/2019 COM \$1050 \$9010 HUBE CONNOLLY HUGH CONNOLLY 10/14/2019 COM \$1051 \$8950 HYDROCORP HUT REGN COMPANY 10/14/2019 COM \$1052 39070 J.H. HART URBAN FORESTRYJ.H. HART URBAN FORESTRY 10/14/2019 COM \$1053 \$9423 JAMES HEALY JAMES HEALY 10/14/2019 COM \$1054 \$9324 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM \$1055 30521 JOHN OR MARGADRET CHOINIJOHN OR MARGARET CHOINI 10/14/2019 COM \$1056 60172 JOHN OR MARGADRET CHOINIJOHN OR MARGARET CHOINI 10/14/2019 COM \$1053 \$1939 KEATON YUELICATION GROUE KRATON NECONNEXT 10/14/2019 COM \$1066 60077 KRISTIN RUTKONSKI KELLER THOMA 10/14/2019 COM \$1066 <						100.00
10/14/2019 COM 81048 08500 HUBBELL ROTH & CLARK INCHUBBELL ROTH & CLARK INC 10/14/2019 COM 81050 59301 HUGH CONNOLLY HUGH CONNOLLY 10/14/2019 COM 81051 58950 HURNCORP HUDRCORP 10/14/2019 COM 81052 39070 J.H. HART URBAN FORESTRIJ.H. HART URBAN FORESTRY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81054 59324 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM 81055 61521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINI ON MARGARET CHIOINI 10/14/2019 COM 81058 51338 KEATON PUBLICATION ROUVELACTIN PUBLICATION ROUVELATINA 10/14/2019 COM 81061 MISC KURTIS KITCHEN 10/14/2019 COM 81061 MISC KURTIS KITCHEN 10/14/2019 COM 81065 59299 MARGARET HOLDER MONDELCENTON BECOMMUNITY COL						100.00
10/14/2019 COM 81049 59301 HUGH CONNOLLY HUGH CONNOLLY 10/14/2019 COM 81051 58950 HUDROCORP HUDROCORP 10/14/2019 COM 81052 39070 J.H. HART URBAN FORESTRYJ.H. HART URBAN FORESTRY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81055 30521 JOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOH/4/2019 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOH 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINJOHN OR MARGARET CHIOINJOH 10/14/2019 COM 81056 60172 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81061 MISC KURTIS KITCHEN KELLER THOMA 10/14/2019 COM 81062 51732 LEXISTENETIS RITS KUTCHEN KURTIS KITCHEN 10/14/2019 COM 81064 49491 MARCARET HOLDEN MARGARET HOLDEN						389.21
10/14/2019 COM 81050 59010 HURT SIGN COMPANY HURT SIGN COMPANY 10/14/2019 COM 81051 58950 HYDROCORP HYDROCORP 10/14/2019 COM 81052 39070 J.H. HART URBAN FORESTRYJ.H. HART URBAN FORESTRY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81055 30521 JOHN OR MARGARET CHIDINI ON OR MARGARET CHIDINI 10/14/2019 COM 81055 5920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81057 59320 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81066 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81063 53573 MACOME COMUNITY COLLEGE KURTIS KITCHEN 10/14/2019 COM 81064 <td></td> <td></td> <td></td> <td></td> <td></td> <td>22,330.51</td>						22,330.51
10/14/2019 COM 81051 58950 HYDROCORP HYDROCORP 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81054 59324 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81055 60172 JOHN OR MAGGARET CHIONIJOHN MARGARET CHIONNID 10/14/2019 COM 81055 51939 KEATON PUBLICATION GROUF KATON PUBLICATION GROUF 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTION COMMINITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPLY 10/14/2019 COM 81065 5299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066						100.00 180.00
10/14/2019 COM 81052 39070 J.H. HART URBAN FORESTRYJ.H. HART URBAN FORESTRY 10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81054 59324 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINI JOHN OR MARGARET CHIOINI 10/14/2019 COM 81057 59920 KAREN MACDONALD KAREAN MACDONALD 10/14/2019 COM 81058 51939 KEARTON PUBLICATION GROUKEATON UPBLICATION GROUP 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTION MONINITY COLLEGEMACONE COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARERE, CAROLYN 10/						284.00
10/14/2019 COM 81053 59423 JAMES HEALY JAMES HEALY 10/14/2019 COM 81055 30521 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MREARET CHIOINIJOHN OR MARGARET CHIOINI 10/14/2019 COM 81056 60172 JOHN MREARET CHIOINIJOHN OR MARGARET CHIOINI 10/14/2019 COM 81057 59920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81058 51939 KEATON PUBLICATION GROUFKEATON PUBLICATION GROUF 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTION LEXISNEXIS RISK SOLUTION 10/14/2019 COM 81064 49491 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81065 52299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019						3,840.25
10/14/2019 COM 81054 5324 JCR SUPPLY, INC. JCR SUPPLY, INC. 10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINIJOHN OR MARGARET CHIOINI 10/14/2019 COM 81056 59920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81058 51939 KEATON PUBLICATION GRUFHELLATION GRUPHELLATION GRUPHELLATION 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KIRTIN RUTKOWSKI 10/14/2019 COM 81062 51792 LEXISNELIS RISK SOLUTIONLECHACOM COMMUNITY COLLEGE 10/14/2019 COM 81065 5299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCAREN, CAROLYN MCCAREN, CAROLYN 10/14/2019 COM 81066 MISC MCCAREN, CAROLYN MCCAREN, CAROLYN 10/14/2019 COM 81066 MISC MCCAREN, CAROLYN MCCAREN, CAROLYN 10/14/2019 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>280.00</td></td<>						280.00
10/14/2019 COM 81055 30521 JOHN MILLIRON JOHN MILLIRON 10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINIJOHN OR MARGARET CHIOINI 10/14/2019 COM 81057 59920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81059 93300 KELLER THOMA KELLER THOMA 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KISTIN RUTKOWSKI 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMMUNITY COLLECE MANNIN LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCAREN, CAROLYN MCCAREN, CAROLYN MCCAREN, CAROLYN 10/14/2019 COM 81065 59299 MARGARET HOLDEN MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCAREN, CAROLYN MCCAREN, CAROLYN MCLAREN, CAROLYN 10/14/2019 COM 81067 51408 MICRO CENTER A/						576.75
10/14/2019 COM 81056 60172 JOHN OR MARGARET CHIOINIJOHN OR MARGARET CHIOINI 10/14/2019 COM 81057 59920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81058 51939 KEATON PUBLICATION GROUFKEATON PUBLICATION GROUF 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KEISTIN RUTKOWSKI 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTION ELAISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACMONINTY COLLEGRMCOMB COMMUNITY COLLEGRE 10/14/2019 COM 81064 49491 MAINSLANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CARDLY MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CARDLY MELISSA GRAY 10/14/2019 COM 81067 60175 MELISSA GRAY MELISSA RINGEY 10/14/2019 COM 81067 <td></td> <td></td> <td></td> <td></td> <td></td> <td>1,050.00</td>						1,050.00
10/14/2019 COM 81057 5920 KAREN MACDONALD KAREN MACDONALD 10/14/2019 COM 81058 51939 KEATON PUBLICATION GROUFKEATON PUBLICATION GROUF 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOMB COMMUNITY COLLEGEMACOMB COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81066 MISC MICARC CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM <						85.69
10/14/2019 COM 81058 51939 KEATON PUBLICATION GROUFKEATON PUBLICATION GROUF 10/14/2019 COM 81059 09300 KELLER THOMA KELLER THOMA 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMMUNITY COLLEGEMACOME COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MELISSA GRAY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MELISSA GRAY 10/14/2019 COM 81067 61175 MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM						200.00
10/14/2019 COM 81059 09300 KELLER THOMA KELLER THOMA 10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMMUNITY COLLEGE MACOME COMMUNITY COLLEGE 10/14/2019 COM 81065 59299 MARGARET HOLDEN MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCLARREY MELISSA GRAY 10/14/2019 COM 81067 60175 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 8						
10/14/2019 COM 81060 60077 KRISTIN RUTKOWSKI KRISTIN RUTKOWSKI 10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMUNITY COLLEGEMACOME COMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81067 60175 MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81068 49556 MELISSA GRAY MICRO CENTER A/R 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 810						43.75
10/14/2019 COM 81061 MISC KURTIS KITCHEN KURTIS KITCHEN 10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMMUNITY COLLEGEMACOME COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 9556 MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81067 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81075						199.93
10/14/2019 COM 81062 51792 LEXISNEXIS RISK SOLUTIONLEXISNEXIS RISK SOLUTION 10/14/2019 COM 81063 53573 MACOME COMMUNITY COLLEGE MACOME COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCLISSA GRAY MELISSA GRAY 10/14/2019 COM 81067 60175 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREPOAKLAND COUNTY TREASUREF 10/14						700.00
10/14/2019 COM 81063 53573 MACOMB COMMUNITY COLLEGEMACOMB COMMUNITY COLLEGE 10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81065 59299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81067 60175 MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COM \$1076 <						150.00
10/14/2019 COM 81064 49491 MAINS LANDSCAPE SUPPLY MAINS LANDSCAPE SUPPLY 10/14/2019 COM 81065 59299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81066 MISC MCLAREN, CAROLYN MELISSA GRAY 10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81070 51408 MICRO CENTER A/R MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFO 10/14/2019 COM 81077 49769 OFFICE EXPRESS O'FFICE EXPRESS 10/14/2019 <						175.00
10/14/2019 COM 81065 59299 MARGARET HOLDEN MARGARET HOLDEN 10/14/2019 COM 81066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM 81067 60175 MELISSA GRAY MELISSA RINGEY 10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREFOAKLAND 10/14/2019 COM 81077 49769						174.78
10/14/2019 COM \$1066 MISC MCCARREN, CAROLYN MCCARREN, CAROLYN 10/14/2019 COM \$1067 60175 MELISSA GRAY MELISSA GRAY 10/14/2019 COM \$1068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM \$1069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM \$1070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM \$1071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM \$1071 MISC MOLT NEXT 10/14/2019 COM \$1073 59112 NEXT NEXT 10/14/2019 COM \$1075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM \$1076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM \$1077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM \$1078 \$8894						100.00
10/14/2019 COM 81067 60175 MELISSA GRAY MELISSA GRAY 10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81076 50830 OKELLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078						500.00
10/14/2019 COM 81068 49556 MELISSA RINGEY MELISSA RINGEY 10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMMEOVERHEAD DOOR WEST COMME 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 <td></td> <td></td> <td></td> <td></td> <td></td> <td>300.00</td>						300.00
10/14/2019 COM 81069 31794 MICHAEL MILES MICHAEL MILES 10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81076 50830 OVERHEAD DOOR WEST COMMEOVERHEAD DOOR WEST COMME 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMMEOVERHEAD DOOR WEST COMME 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14						200.00
10/14/2019 COM 81070 51408 MICRO CENTER A/R MICRO CENTER A/R 10/14/2019 COM 81071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKIROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROM ACEMENT 10/14/20					MICHAEL MILES MICHAEL MILES	1,050.00
10/14/2019 COM 81071 MISC MODERN MILL SOLAR MODERN MILL SOLAR 10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 <t< td=""><td></td><td></td><td></td><td></td><td>MICRO CENTER A/R MICRO CENTER A/R</td><td>104.93</td></t<>					MICRO CENTER A/R MICRO CENTER A/R	104.93
10/14/2019 COM 81072 51182 NELSON BROTHERS SEWER & NELSON BROTHERS SEWER & 10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREPOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKI ROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084						200.00
10/14/2019 COM 81073 59112 NEXT NEXT 10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 <t< td=""><td></td><td></td><td></td><td></td><td></td><td>260.00</td></t<>						260.00
10/14/2019 COM 81074 51799 NYE UNIFORM EAST NYE UNIFORM EAST 10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREPOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKI ROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085						42,835.00
10/14/2019 COM 81075 51540 O'REILLY AUTO PARTS O'REILLY AUTO PARTS 10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREPOAKLAND COUNTY TREASUREP 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81082 16100 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						709.65
10/14/2019 COM 81076 50830 OAKLAND COUNTY TREASUREFOAKLAND COUNTY TREASUREF 10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMME OVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKI ROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						50.36
10/14/2019 COM 81077 49769 OFFICE EXPRESS OFFICE EXPRESS 10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMMEOVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKIROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROM ACEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						342,975.49
10/14/2019 COM 81078 58894 OVERHEAD DOOR WEST COMMEOVERHEAD DOOR WEST COMME 10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKIROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						97.40
10/14/2019 COM 81079 59933 PACK 1712 PACK 1712 10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKIROAD COMMISSION FOR OAKI 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						380.73
10/14/2019 COM 81080 50502 PITNEY BOWES CREDIT CORFPITNEY BOWES CREDIT CORF 10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKLROAD COMMISSION FOR OAKL 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						132.00
10/14/2019 COM 81081 15300 PRINTING SYSTEMS PRINTING SYSTEMS 10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKLROAD COMMISSION FOR OAKL 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						186.98
10/14/2019 COM 81082 16100 ROAD COMMISSION FOR OAKLROAD COMMISSION FOR OAKL 10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						728.90
10/14/2019 COM 81083 49784 ROMA CEMENT ROMA CEMENT 10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						4,283.67
10/14/2019 COM 81084 59212 RON BALLER RON BALLER 10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						7,845.00
10/14/2019 COM 81085 16500 S.O.C.R.R.A. S.O.C.R.R.A.						100.00
						33,660.00
						60,021.92
10/14/2019 COM 81087 MISC SMOLYANOV HOME IMPROVEME SMOLYANOV HOME IMPROVEME						200.00
10/14/2019 COM 81088 51356 SOUTHFIELD MUFFLER & BRASOUTHFIELD MUFFLER & BRA						1,080.94
10/14/2019 COM 81089 38145 SOUTHFIELD POSTAL SERVICSOUTHFIELD POSTAL SERVIC						383.60

CHECK REGISTER FOR VILLAGE OF BEVERLY HILLS CHECK DATE FROM 10/14/2019 - 10/14/2019

Page: 2/2

Check Date	Bank	Check	Vendor	Vendor Name	Invoice Vendor	Amount
10/14/2019	COM	81090	39048	SOUTHFIELD TOWNSHIP	SOUTHFIELD TOWNSHIP	191.50
10/14/2019	COM	81091	60161	STEVE ORTH	STEVE ORTH	60.00
10/14/2019	COM	81092	17700	SUNSET MAINTENANCE SER	RVISUNSET MAINTENANCE SERVI	1,000.00
10/14/2019	COM	81093	31043	THOMAS J RYAN PC.	THOMAS J RYAN PC.	8,125.00
10/14/2019	COM	81094	38205	VERIZON WIRELESS MESSA	AGIVERIZON WIRELESS MESSAGI	410.20
10/14/2019	COM	81095	MISC	VILLANOVA CONSTRUCTION	VILLANOVA CONSTRUCTION	200.00
10/14/2019	COM	81096	MISC	WALLSIDE WINDOWS	WALLSIDE WINDOWS	1,600.00
10/14/2019	COM	81097	MISC	WHITELAW, MARCUS	WHITELAW, MARCUS	200.00
10/14/2019	COM	81098	53572	WOW! BUSINESS	WOW! BUSINESS	636.27

COM TOTALS:

Total of 87 Checks:

Less 0 Void Checks:

Total of 87 Disbursements:

707,488.86

0.00

707,488.86

CHECK REGISTER FOR VILLAGE OF BEVERLY HILLS Page: 1/1 CHECK DATE FROM 10/02/2019 - 10/14/2019

Check Date	Bank	Check	Vendor	Vendor Name	Invoice Vendor	Amount
Bank IND INDE	PENDENT	BANK				
10/09/2019	IND	1110	30899	RENTAL WORLD		67.50
IND TOTALS:						
Total of 1 Ch Less 0 Void C						67.50 0.00
Total of 1 Di	sburseme	nts:				67.50



To: Honorable President Peddie; Village Council Chris Wilson, Village Manager

From: Erin LaPere, Planning & Zoning Administrator

Date: October 3, 2019

Re: Set Public Hearing for reprogramming of Community Development Block Grant (CDBG)

The Village allocated funds in Program Year (PY) 2017 for the CDBG project Remove Architectural Barriers in anticipation of renovations to Beverly Park to meet requirements of the Americans with Disabilities Act. We did replace the sidewalk at the park, however, due to numerous issues with the contractor that project did not expend the CDBG allocation.

We originally allocated funds in this project to be used for sidewalk and related infrastructure improvements to provide ADA accessible pedestrian paths at Beverly Park. The CDBG program requires contractors to comply with federal government mandates in order for CDBG funds to be used. In addition to the contractor being unable and unwilling to comply with those requirements, he was unable to complete the project per the contract. We are seeking relief for the expenses incurred through the surety bond that was provided with the project.

At this time, we are seeking to reprogram Community Development Block Grant Funds from Program Year 2017. The CDBG program has a number of project categories, however, Beverly Hills does not meet the low income criteria for expending funds on most of those types of projects. Therefore, I am proposing that we reprogram all of the funds from to the Minor Home Repair program which is administered by NEXT for Beverly Hills. The total amount of funds to be reprogrammed is \$13,801.00. The 2017 funds may become eligible to be recaptured by the federal government if they are not expended. Due to limits and restrictions on various projects, we do not have an alternate project to recommend reprogramming other than to transfer them into Minor Home Repair (MHR).

As part of the process required for reprogramming the funds, the Village must hold a public hearing on the matter with notification two weeks prior to the hearing date. The first available Council meeting date available that would provide sufficient time to meet notification deadlines is Tuesday, November 19, 2019.

Suggested Motion


Village Council sets a public hearing date of Tuesday, November 19, 2019 to hear comments on the reprogramming of CDBG allocation from Remove Architectural Barriers to Minor Home Repairs in the amount of \$13,801 for Program Year 2017.



Village of Beverly Hills Audit Presentation to the Village Council

For Year Ended June 30, 2019





* General Fund activity excludes Sick Pay Severance and Vacation Reserve funds




Village of Beverly Hills General Fund, Public Safety Fund, Library Fund - Revenue (in thousands) Years Ended June 30



* General Fund activity excludes Sick Pay Severance and Vacation Reserve funds


plante moran Audit. Tax. Consulting. Wealth Management.






plante moran | Audit. Tax. Consulting. Wealth Management.

Village of Beverly Hills Property Taxes Headlee Maximum Millage versus Actual Levy



plante moran | Audit. Tax. Consulting. Wealth Management.







Village of Beverly Hills General Fund, Public Safety Fund, and Library Fund —Expenditures (in thousands) Years Ended June 30




* General Fund activity excludes Sick Pay Severance and Vacation Reserve funds

plante moran | Audit. Tax. Consulting. Wealth Management.




Village of Beverly Hills General Fund and Public Safety Fund – Fund Balance^{*} Compared to Minimum Target Years Ended June 30



* General Fund activity excludes Sick Pay Severance and Vacation Reserve funds





Business-type Activities
 Governmental Activities

plante moran | Audit. Tax. Consulting. Wealth Management.


(Dollars in 000s)

8



(Dollars in 000s)

Village of Beverly Hills Pension and OPEB Funding Years Ended June 30



Total Plan Net Position Total Liability



THANK YOU

For more information contact:

Martin Olejnik, Partner (248) 223-3662

Rumzei Abdallah, Manager (313) 496-7232

plante moran | {

Audit. Tax. Consulting. Wealth Management.



- To: Honorable President Peddie; Village Council Chris Wilson, Village Manager
- From: Erin LaPere, Planning & Zoning Administrator
- Date: October 9, 2019
- Re: Site Plan and Special Land Use approval for proposed security structure at Detroit Country Day School Middle School parking lot

The Village has received plans to install a building at the Middle School parking lot at Detroit Country Day School for use by security personnel. As a private school in the R-1, Single Family Residential Zone District, any accessory buildings require site plan and special land use approval. Village Ordinance, Section 22.14.030 requires special land use approval for accessory structures at a private school in a Single Family Residential Zone District. Additionally, Section 22.08.300, j requires any modifications to the site after approval that are not in accordance with the approved site plan to obtain special land use approval.

The Planning Commission held a public hearing on August 28, 2019 for plans submitted by DCDS to install the building at the Middle School parking lot. Upon receiving public comments and reviewing the submittal, the Planning Commission made a recommendation that the Village Council approve the site plan and the special land use requests contingent on the Village receiving plans with compete title block, date, and location setbacks clearly marked, and the installation of "Do Not Block Driveway" signage in either direction before the private residence on Hillview Lane. Procedurally, a public hearing on the special land use request must be held by the Council prior to issuing a decision on the requests for special land use and site plan approval

The Village has received updated plans pursuant to the Planning Commission recommendation, see attached. Additionally, the review letter from the Village Planning Consultant and an excerpt from the minutes of the Planning Commission meeting held August 28, 2019 are attached.


Suggested Motions

Village Council approves request for special land use approval from Detroit Country Day School, 22305 W. 13 Mile Road, to install a guard house at the Middle School parking lot entrance off Hillview Lane.

Village Council approves request for modification to a site plan from Detroit Country Day School, 22305 W. 13 Mile Road, to install a guard house at the Middle School parking lot entrance off Hillview Lane.

eel

attachments





	•
•	
•	
•	
•	<u>.</u>
•	· ·
•	· · · · · · · · · · · · · · · · · · ·
•	· · · · · · · · · · · · · · · · · · ·
09/24/2019	DO NOT BLOCK DRIVEWAY SIGNS
08/29/2019	GUARDHOUSE
DATE:	ISSUED FOR:
ORAWN	MLW
CHECKED	TAC
PPROVED	TAC



Planning Commission Village of Beverly Hills 18500 W. 13 Mile Road Beverly Hills, MI 48025

Attention:	Erin LaPere, Planning and Zoning Administrator
Subject:	Detroit Country Day School – Special Use and Site Plan Review #1
Location:	22305 West 13 Mile Road – southwest corner of the 13 Mile and Lahser intersection
Zoning:	R-1 Single Family Residential District

Dear Commissioners:

At the Village's request, we have reviewed the submittal from Detroit Country Day School (DCDS) for a security guard office associated with the Middle School (plans most recently dated 4/8/19).

The proposed security office, which entails a relatively small building (approximately 30 square feet), is located on the north side of Hillview Lane, approximately 100 feet east of the parking lot.

Private schools and accessory elements are permitted with special land use approval in the R-1 District. In accordance with Section 22.08.300, modifications to the site after approval require a new special land use approval, as well as site plan review/approval.

Procedurally, following a public hearing, the Commission may make its recommendation to Village Council on both the special land use and site plan.

We offer the following comments for your consideration in accordance with the applicable standards of the Village Zoning Ordinance. Items in need of attention or additional discussion are <u>underlined</u> to ease navigation through this letter.

Special use review. Section 22.08.300(h) provides the following standards for consideration by the Commission in its review of uses permitted after special approval:

1. In location, size and intensity of the principal and/or accessory operations, be compatible with adjacent uses and zoning of land.

The overall use of the property as a private school is generally compatible with the primarily residential nature of the Village.

The proposed inclusion of a relatively small security office is not expected to alter the overall operations of the site or adversely impact adjacent/surrounding uses of land.

2. Be compatible with and promote the intent and purpose of this Ordinance.

The proposed building is a relatively common accessory element found on large, private school sites. We do not foresee any issues related to the intent and purpose of the Village Zoning Ordinance.

3. Be compatible with the natural environment and conserve natural resources and energy.

The proposed building will have no impact on the natural environment.



Aerial view of site and surroundings (looking north prior to Middle School expansion)

4. Be consistent with existing and future capabilities of public services and facilities affected by the proposed use.

Given the nature, design and location of the proposed security office, the project is not expected to impact public services and facilities. <u>With that being said, the applicant must address any comments provided by the Director of Public Services and/or Village Engineer.</u>

5. Protect the public health, safety, and welfare as well as the social and economic well-being of those who will use the land use, activity, residents, businesses and landowners immediately adjacent and the Village as the whole.

Given the size, nature and location of the proposed security office, we do not anticipate activities that would be contrary to the public health, safety and welfare.

6. Promote the use of land in a socially and economically desirable manner.

DCDS is a well-established institutional use in the community and, as previously mentioned, stand-alone security offices are relatively common components to large, private schools.

7. Not be in conflict with convenient, safe and normal neighborhood vehicular and pedestrian traffic routes, flows, intersections, and general character and intensity of neighborhood development.

The office is situated well away from the intersection and the site plan does not include a gated driveway, which could cause traffic to back-up at certain times of day. As such, the proposal is not expected to be in conflict with vehicular and pedestrian circulation.

8. Be of such design and impact that the location and height of buildings, the location, nature and height of walls, fences and the nature and extent of landscaping on the site shall not hinder or discourage the appropriate development and use of adjacent land and buildings or impair the value thereof.

Given its size, height and location, the proposed building is not expected to have any impact upon use or value of adjacent/surrounding properties.

Village of Beverly Hills Planning Commission **Detroit Country Day School - Special Use and Site Plan Review #2** Page 3

9. In the nature, location, size and site layout of the use, be a harmonious part of the district in which it is situated taking into account, among other things, prevailing shopping habits, convenience of access by prospective patrons, the physical and economic relationship of one type of use to another and characteristic groupings of uses of said district.

Similar to comments above, we do not anticipate off-site impacts of the proposal.

10. In the location, size, intensity and site layout be such that operations will not be objectionable to nearby dwellings, by reason of noise, fumes, glare or flash of lights.

Similar to comments above, we do not expect the project to create any of the nuisance-like activities described under this criterion.

11. Be consistent with the character, nature and type of residential districts surrounding the proposed special uses.

Given the nature of the request, the proposal is not expected to alter the character of the DCDS property or the surrounding area.

Site plan review. Section 22.08.290 identifies the process and review standards applicable to site plans. We have reviewed the proposal for compliance with the applicable Ordinance standards, as follows:

- **1. Dimensional Requirements**. The proposed security office is situated approximately 400 feet from Lahser Road and well outside of required setbacks.
- **2. Building Design.** Elevation drawings have been provided depicting a small metal building on a concrete pad. Notes on the elevation drawing indicate a tan and green color scheme.
- 3. Lighting. The building section detail notes use of an LED light fixture on the outside of the building. We request the applicant provide a fixture detail along with an indication of the number and location of such fixtures.
- **4.** Landscaping and Screening. The landscaping required by the 2016 site plan approval has been planted. Given the limited scope of the project, additional landscaping is not required at this time.
- 5. Additional Considerations. <u>The plan included with the submittal identifies a concrete patio along</u> with a sidewalk at the rear of the Middle School. This is the location of the basketball court that was recently removed. The plans must be revised to remove these structures.

The plan also depicts an additional length of screen fencing along the west side lot line. If proposed as part of this project, details must be provided. If this is an oversight, it must be removed from the plan.

Should you have any questions concerning this matter, please do not hesitate to contact our office. I can be reached by phone at (248) 586-0505, or via e-mail at <u>bborden@safebuilt.com</u>.

Respectfully, **SAFEBUILT STUDIO**

Brian V. Borden, AICP Planning Manager

EXCERPT OF REGULAR PLANNING COMMISSION MEETING MINUTES – AUGUST 28, 2019 – PAGE 1

- Present: Chairperson Drummond; Vice-Chairperson Westerlund; Members: Borowski, Copeland, Grinnan, Ostrowski, Ruprich, and Wilensky
- Absent: Member: Stempien
- Also Present: Planning and Zoning Administrator, LaPere Planning Consultant, Borden Council Liaison, Hrydziuszko

PUBLIC HEARING ON SPECIAL LAND USE REQUEST FOR INSTALLATION OF A GUARD HOUSE AT DETROIT COUNTRY DAY SCHOOL, MIDDLE SCHOOL PARKING LOT, 22305 W 13 MILE ROAD

Mary Sclabassi, Security Director, provided an overview of the request and explained that the guard house will give the school the ability to reroute traffic that attempts to cut through the property and allow for screening of any visitors to the campus during the school day. The guard building would only be staffed from 8:30 am to 2:45 pm, Monday through Friday. She noted that the location is on Hillview Lane.

Borowski asked why the cement pad had been poured prior to approval and Sclabassi explained there was concrete work being done at the property so it was more economical to pour the pad at the same time.

Copeland inquired about the impact to the resident located on Hillview Lane. She explained the guard house is not intended for slowing down traffic during pick up and drop off times.

Borden reviewed the submittal from Detroit Country Day School (DCDS) for a security guard house associated with the Middle School (plans most recently dated 4/8/19). The proposed security building, approximately 30 square feet, is to be located on the north side of Hillview Lane, approximately 100 feet east of the parking lot. Private schools and accessory elements are permitted with special land use approval in the R-1 District.

In accordance with Section 22.08.300, modifications to the site after approval require a new special land use approval, as well as site plan review and approval. Procedurally, following a public hearing, the Commission may make its recommendation to Village Council on both the special land use and site plan.

Section 22.08.300(h) provides the standards for consideration by the Commission in its review of uses permitted after special approval. Given the nature, design and location of the proposed security office, the project is not expected to impact public services and facilities. With that being said, the applicant must address any comments provided by the Director of Public Services and/or Village Engineer.

Drummond opened the public hearing at 8:05 p.m.

EXCERPT OF REGULAR PLANNING COMMISSION MEETING MINUTES – AUGUST 28, 2019 – PAGE 2

John Mooney, Devonshire, believes that the guard house is not a necessary addition and that DCDS intended to install it regardless of approval.

No one else wished to be heard; therefore the public hearing was closed at 8:08 p.m.

REVIEW AND CONSIDER RECOMMENDATION ON SPECIAL LAND USE AND SITE PLAN FOR THE INSTALLATION OF A GUARD HOUSE AT DETROIT COUNTRY DAY SCHOOL, MIDDLE SCHOOL PARKING LOT, 22305 W 13 MILE ROAD

Westerlund agrees that despite the requests by the Village that DCDS follow procedures, they continue to disregard those requests. Grinnan expressed her belief that without the Village taking legal action, this will continue to occur.

Motion by Ostrowski, second by Westerlund, that the Planning Commission recommends approval of special land use for the installation of a guard house at Detroit Country Day School, Middle School parking lot, 22305 W. 13 Mile Road.

Roll Call Vote:CopelandnoDrummondyesGrinnanyesOstrowskiyesRuprichyesWesterlundyesBorowskiyes

Motion passed (6-1)

Wilensky arrived to the meeting at 8:15 pm.

Section 22.08.290 identifies the process and review standards applicable to site plans. The proposed security building is well outside of required setbacks. Elevation drawings have been provided depicting a small metal building on a concrete pad. Notes on the elevation drawing indicate a tan and green color scheme. The landscaping required by the 2016 site plan approval has been planted. Given the limited scope of the project, additional landscaping is not required. Applicant confirmed there is no intention to install a gate or fencing as a part of this project and that there would be no lighting on the exterior of the building.

Commissioners discussed the need for the standard details typically found on the plans and installation of signage to clearly prohibit blockage of the existing resident's driveway.

Motion by Westerlund, second by Grinnan, that the Planning Commission recommends approval of site plan for the installation of a guard house at Detroit Country Day School, Middle School parking lot, 22305 W. 13 Mile Road, contingent upon the revised site plan submitted with title block, professional seal, date and any revision dates; the location of the guard house and slab be identified with dimensions from nearby property

EXCERPT OF REGULAR PLANNING COMMISSION MEETING MINUTES – AUGUST 28, 2019 – PAGE 3

lines; two "do not block driveway" signs are installed, one on the north side and one on the south side of Hillview Lane, east and west of the property line of the private homeowner.

Roll Call Vote: Grinnan yes Ostrowski yes Ruprich yes Westerlund yes Wilensky yes Borowski yes Copeland no Drummond yes

Motion passed (7-1)



- To: Honorable President Peddie; Village Council Chris Wilson, Village Manager
- From: Erin LaPere, Planning & Zoning Administrator
- Date: October 9, 2019

Re: Proposed renovations to existing tennis courts at Detroit Country Day School

Detroit Country Day School has submitted plans to perform renovations on the existing tennis courts at the upper school portion of their campus. Due to the scope of the project, Section 22.08.290 requires site plan approval prior to construction. Per Village Ordinance, Council must first refer the proposal to the Planning Commission for a recommendation after which Council will have the opportunity to review and consider approval of the proposal.

The plans submitted detail the proposed removal and reconstruction of the existing tennis courts, including excavation and removal of the courts and base materials (approximately 4,100 yds of material), installation of new base and surface, installation of edge drain, and removal and replacement of court fencing. The Planning Commission reviewed the plans at their meeting held September 25, 2019 at which time the school representative confirmed the fencing would be removed during the project and replaced upon completion and that no lighting is proposed to be installed. The project is slated to begin at the end of the school year, June 2020. The Village Engineer has reviewed the plans and does not anticipate any impacts given the limited scope of modifications to the existing facilities. Administration will monitor the progress and inspect upon completion to ensure site plan compliance. The Village Planning Consultant has also reviewed the plans, comments attached.

Minutes of the Planning Commission meeting at which the Commission recommended approval of the site plan and a copy of the plans and scope of work provided by DCDS are attached.

Suggested Motions

Village Council approves plans submitted by Detroit Country Day for renovations to existing tennis courts provided that no lights are added to the court and subject to review and approval by the Village Engineer for grading and drainage.

eel

attachment



Planning Commission Village of Beverly Hills 18500 W. 13 Mile Road Beverly Hills, MI 48025

Attention:	Erin LaPere, Planning and Zoning Administrator
Subject:	Detroit Country Day School tennis court reconstruction – Site Plan Review #1
Location:	22305 West 13 Mile Road – southwest corner of the 13 Mile and Lahser intersection
Zoning:	R-1 Single Family Residential District

Dear Commissioners:

At the Village's request, we have reviewed the submittal from Detroit Country Day School (DCDS) to reconstruct their existing tennis courts at the Upper School.

The proposal entails removal and reconstruction of the 10 existing tennis courts.

Since the project does not entail a new or expanded use, special land use review is not required by the Zoning Ordinance.

However, given the nature of the project, site plan review is necessary (more than 5 cubic yards of earth material being disturbed).

We offer the following comments for your consideration in accordance with the applicable standards of the Village Zoning Ordinance. Items in need of attention or additional discussion are <u>underlined</u> to ease navigation through this letter.

Site plan review. Section 22.08.290 identifies the process and review standards applicable to site plans. We have reviewed the proposal for compliance with the applicable Ordinance standards, as follows:

- 1. **Dimensional Requirements**. The tennis courts will be reconstructed in the same location as they currently exist. This area is central to the overall campus and well outside of minimum R-1 setback requirements.
- 2. Lighting. If the tennis courts are to be illuminated, the applicant needs to provide details of poles/fixtures for the Commission's review.

If no lighting is proposed, we request the applicant provide confirmation.

3. Fencing. The existing black vinyl coated chain link fencing around the courts will be replaced. The current height is noted as approximately 10 feet. The fencing includes fabric wind screens, which is typical for tennis courts.

Per Section 22.08.150(E), Planning Commission approval is required for fences above 7 feet tall that enclose an institutional athletic field.

4. Engineering. <u>The project is subject to review and approval by the Village Engineer for grading and drainage.</u>



Aerial view of site and surroundings (looking east)

Should you have any questions concerning this matter, please do not hesitate to contact our office. I can be reached by phone at (248) 586-0505, or via e-mail at <u>bborden@safebuilt.com</u>.

Respectfully, **SAFEBUILT STUDIO**

Brian V. Borden, AICP Planning Manager

EXCERPT OF REGULAR PLANNING COMMISSION MEETING MINUTES – SEPTEMBER 25, 2019 – PAGE 1

- Present: Chairperson Drummond; Vice-Chairperson Westerlund; Members: Copeland, Grinnan, Ostrowski, Stempien, and Wilensky
- Absent: Members: Borowski and Ruprich
- Also Present: Planning and Zoning Administrator, LaPere Council Liaison, Hrydziuszko

REVIEW AND CONSIDER RECOMMENDATION TO COUNCIL FOR PROPOSED MAINTENANCE AND UPGRADES TO THE EXISTING TENNIS COURTS AT DETROIT COUNTRY DAY SCHOOL, 22305 W 13 MILE ROAD

LaPere provided an overview of Planning Consultant Borden's review of the submittal from Detroit Country Day School (DCDS) to reconstruct their existing tennis courts at the Upper School. The proposal entails removal and reconstruction of the 10 existing tennis courts. Since the project does not entail a new or expanded use, special land use review is not required by the Zoning Ordinance. However, given the nature of the project, site plan review is necessary (more than 5 cubic yards of earth material being disturbed).

Site plan review. Section 22.08.290 identifies the process and review standards applicable to site plans.

1. Dimensional Requirements. The tennis courts will be reconstructed in the same location as they currently exist. This area is central to the overall campus and well outside of minimum R-1 setback requirements.

2. Lighting. If the tennis courts are to be illuminated, the applicant needs to provide details of poles/fixtures for the Commission's review. If no lighting is proposed, we request the applicant provide confirmation.

3. Fencing. The existing black vinyl coated chain link fencing around the courts will be replaced. The current height is noted as approximately 10 feet. The fencing includes fabric wind screens, which is typical for tennis courts. Per Section 22.08.150(E), Planning Commission approval is required for fences above 7 feet tall that enclose an institutional athletic field.

4. Engineering. The project is subject to review and approval by the Village Engineer for grading and drainage.

Bruce Israel, contractor for DCD, explained that this project would not add any new structures and they will be improving the base materials and drainage system. There will not be any lights on the courts and the intention is to replace the existing fence without any change to the height. The pavers located along the west side of the court will be removed and replaced, the pavers on the east and north side will not be touched. This project is expected to take place in June of 2020. He was cautioned to be conscientious and courteous to neighbors during this project.

Motion by Westerlund, second by Stempien, that the Planning Commission recommends approval of site plan for proposed maintenance and upgrades to the existing tennis courts at Detroit Country Day School, 22305 W 13 Mile Road, contingent that no lights are added to the court, allowing of the replacement of the

EXCERPT OF REGULAR PLANNING COMMISSION MEETING MINUTES – SEPTEMBER 25, 2019 – PAGE 2

existing approximately 10 foot high fencing, and is subject to review and approval by the Village Engineer for grading and drainage.

Roll Call Vote: Motion passed (7-0)

THESE MINUTES ARE NOT OFFICIAL. THEY HAVE NOT BEEN APPROVED.



Report of Geotechnical Investigation

Detroit Country Day School Tennis Courts 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025

Latitude 42.512887° N Longitude 83.266062° W

Prepared for: Detroit Country Day School 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025

> G2 Project No. 190234 April 18, 2019

g2consultinggroup.com

Headquarters 1866 Woodslee St Ann Arbor 1350 Eisenhower Pl Chicagoland 1186 Heather Dr

Troy, MI 48083 P 248.680.0400 F 248.680.9745 Ann Arbor, MI 48108 Lake Zurich, IL 60047 P 847.353.8740 F 847.353.8742

P 734.390.9330 F 734.390.9331



April 18, 2019

Mr. Scott Stanley **Director of Campus Operations Detroit Country Day School** 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025

RE: Report of Geotechnical Investigation Detroit Country Day School Tennis Courts 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025 G2 Project No. 190234

Greetings Mr. Stanley:

In accordance with your request, we have completed a pavement investigation for the proposed rehabilitation/reconstruction of the existing tennis courts at Detroit Country Day School in Beverly Hills, Michigan. This report presents the results of our observations and analyses and includes recommendations and construction considerations relative to the proposed tennis court rehabilitation/reconstruction.

As always, we appreciate the opportunity to be of service to Detroit Country Day School and look forward to discussing our findings. In the meantime, if you have any questions regarding this report or any other matter pertaining to the project, please call us.

Sincerely,

G2 Consulting Group, LLC

ant M. Beelle

Grant M. Beahlen, P.E. Project Engineer

Enclosures

Jason B. Stoops, P.E. Office Manager/Project Manager

Headquarters 1866 Woodslee St Ann Arbor 1350 Eisenhower Pl Chicagoland 1186 Heather Dr

Troy, MI 48083 Ann Arbor, MI 48108 Lake Zurich, IL 60047 P 847.353.8740 F 847.353.8742

P 248.680.0400 F 248.680.9745 P 734.390.9330 F 734.390.9331

EXECUTIVE SUMMARY

2

We understand the project consists of rehabilitation/reconstruction of the existing tennis courts at Detroit Country Day School in Beverly Hills, Michigan. Based on onsite observations, an existing drainage tile is located along the east portion of the courts and ponding water is present within the playing surface along the east end of the tennis courts.

Approximately 3 inches of bituminous concrete underlain by 7 to 19 inches of pulverized bituminous concrete and crushed concrete are present at soil borings B-1 through B-6. Approximately 3 inches of bituminous concrete underlain by at least 9 inches of 1 by 3 crushed concrete are present at soil borings B-7 and B-8. Concrete fragments underlie the pulverized bituminous concrete within soil boring B-2 and extends to an approximate depth of 1-1/2 feet. Stiff silty clay fill with an unidentified hydrocarbon odor underlies the pavement section within soil boring B-5 and extends to an approximate depth of 3 feet. Native stiff silty clay underlies the pavement section within boring B-2 and underlies the fill within boring B-5 and extend to the explored depth of 4 feet. Very loose to loose silty sand and sand underlie the pavement section within boring B-1 and underlies the fill within boring B-5 and extend to the explored depths of 4 feet. Soil borings B-3, B-4, B-6, B-7, and B-8 were terminated prior to the proposed drilling depth due to hand auger refusal on the existing pavement section materials. No measurable groundwater was encountered during or upon completion of drilling operations.

Option A – Mill and Overlay

Based on historical imagery, it appears the tennis courts were reconstructed/rehabilitated in 2005. The existing courts are experiencing moderate severity shrinkage cracking with several cracks open 1 to 2 inches wide. A few of the fence and net posts are experiencing heaving.

Therefore, given the thickness of the existing bituminous pavement and underlying pulverized bituminous concrete, we recommend milling the court surface 1-1/2 inches, perform any full depth patching as necessary, and construct a new 1-1/2 inch thick bituminous concrete overlay.

Prior to the overlay, any existing cracks or joints in the pavement surface wider than 1/8 inch should be filled with hot-applied bituminous crack filler. Any areas of the pavement that exhibit excessive fatigue cracking or deterioration should be replaced with a full depth patch prior to placement of the new bituminous concrete overlay. The bituminous concrete should be saw-cut a minimum 2 feet laterally from the distressed area to be removed. Prior to placing the full-depth patch a tack coat should be applied to the sides of the saw-cut pavement.

Option B – Full Depth Reconstruction

Alternatively, we recommend completely removing the bituminous concrete pavement surface and sufficient amount of underlying pulverized bituminous concrete to support a new tennis court pavement section. We do not recommend reusing the existing pulverized bituminous concrete due to the risk of the pulverized bituminous concrete becoming unstable. We recommend the exposed subgrade be thoroughly proof rolled with a heavy rubber tired vehicle such as a tandem axle dump truck and visually evaluated for instability and/or unsuitable soil conditions. Areas of instability during construction traffic loading and proof roll operations should be expected within at least the area of soil boring B-5. An allowance for undercuts due to the existing fill soils should be allotted. Upon completion of proof roll operations, the subgrade should be graded to promote effective surface drainage and prevent water from ponding and the new pavement section may be constructed. We recommend all earthwork operations be performed in accordance with comprehensive specifications and be properly monitored in the field by qualified personnel under the direction of a licensed engineer.

Do not consider this summary separate from the entire text of this report, with all the conclusions and qualifications mentioned herein. Details of our analysis and recommendations are discussed in the following sections and in the Appendix of this report.

PROJECT DESCRIPTION

We understand the project consists of rehabilitation/reconstruction of the existing tennis courts at Detroit Country Day School in Beverly Hills, Michigan. Based on onsite observations, an existing drainage tile is located along the east portion of the courts and ponding water is present within the playing surface along the east end of the tennis courts.

The purpose of our investigation is to determine and evaluate the general pavement and subsurface conditions within the pavements and develop general recommendations for rehabilitation/reconstruction of the existing pavements.

SCOPE OF SERVICES

The field operations, laboratory testing, and engineering report preparation were performed under the direction and supervision of a licensed professional engineer. Our services were performed according to generally accepted standards and procedures in the practice of geotechnical engineering in this area. Our scope of services for this project consists of the following specific items:

- 1. We performed a cursory visual identification of the types and relative magnitudes of observable pavement distress.
- 2. We drilled pavement cores/soil borings B-1 through B-8 extending to depths ranging from 6 inches and 4 feet. We measured the existing pavement section materials (bituminous concrete, Portland cement concrete, and bituminous millings) and identified the type and condition of subgrade soils. Soil borings B-3, B-4, B-6, B-7, and B-8 were terminated prior to the proposed drilling depth due to hand auger refusal on the existing pavement section materials.
- 3. We performed laboratory testing on samples obtained from the soil borings. Laboratory testing included visual engineering classification, moisture content, and unconfined compressive strength determinations.
- 4. We prepared this engineering report. Our report includes recommendations for existing court rehabilitation/reconstruction.

FIELD OPERATIONS

G2 Consulting Group, LLC, selected the number, depth, and location of the soil borings. The soil borings were located in the field by a G2 representative by measuring from existing site features and landmarks using conventional taping methods. The approximate soil boring locations are shown on the Soil Boring Location Plan, Plate No. 1. Ground surface elevations were not available at the time of the field investigation.

We used an electrically powered core rig, equipped with a 4-inch diameter diamond-tipped core barrel, to core the pavement locations. Pavement cores were drilled through the full depth of the existing pavement structure to obtain an accurate determination of the pavement thickness.

Hand auger soil borings were performed using a 3-inch diameter hand auger. Within each hand auger soil boring, soil samples were obtained at 2 feet and 4 feet and at transitions in soil types, as able. The soil samples were placed in sealed containers in the field and brought to the laboratory for testing and classification. A Dynamic Cone Penetrometer (DCP) test was performed within granular soil to evaluate the relative density of the in-situ soil. DCP testing involves driving a 1-1/2-inch diameter cone with a 45° vertex angle into the ground using a 15-pound weight dropped 20 inches after the cone is seated into the bottom of the hand auger borehole. The Dynamic Cone Penetrometer is driven 1-3/4 inches. The blow counts for the 1-3/4-inch drive are presented on the individual hand auger soil boring logs.

During drilling operations, a G2 engineer maintained logs of the encountered subsurface conditions, including changes in stratigraphy and observed groundwater levels to be used in conjunction with our

analysis of the subsurface conditions. The final hand auger soil boring logs are based on the field logs and laboratory soil classification and testing. After completion of boring operations, the boreholes were backfilled with excavated soil and capped with cold patch.

LABORATORY TESTING

Representative soil samples were subjected to laboratory testing to determine soil parameters pertinent to pavement design and site preparation. An experienced geotechnical engineer classified the samples in general conformance with the Unified Soil Classification System.

Laboratory testing included moisture content and unconfined compressive strength determination. The unconfined compressive strengths were determined by using a spring loaded hand penetrometer. The hand penetrometer estimates the unconfined compressive strength to a maximum of 4-1/2 tons per square foot (tsf) by measuring the resistance of the soil sample to the penetration of a calibrated spring loaded cylinder.

The results of the moisture content and unconfined compressive strengths are indicated on the soil boring logs at the depths the samples were obtained. We will hold the soil samples for 60 days from the date of this report. If you would like the samples, please let us know.

EXISTING PAVEMENT AND SUBSURFACE CONDITIONS

Approximately 3 inches of bituminous concrete underlain by 7 to 19 inches of pulverized bituminous concrete and crushed concrete are present at soil borings B-1 through B-6. Approximately 3 inches of bituminous concrete underlain by at least 9 inches of 1 by 3 crushed concrete are present at soil borings B-7 and B-8. Concrete fragments underlie the pulverized bituminous concrete within soil boring B-2 and extends to an approximate depth of 1-1/2 feet. Silty clay fill underlies the pavement section within soil boring B-5 and extends to an approximate depth of 3 feet. Native silty clay underlies the pavement section within boring B-2 and extends to the explored depth of 4 feet. Silty sand and sand underlie the pavement section within boring B-1 and underlies the fill within boring B-5 and extend to the explored depths of 4 feet.

The silty clay fill is stiff in consistency with a moisture content of 22 percent and an unconfined compressive strength of 4,000 pounds per square foot (psf). The native silty clay within boring B-2 is stiff in consistency with natural moisture contents of 21 and 24 percent and unconfined compressive strengths of 2,500 and 4,000 psf. The silty sand and sand within borings B-1 and B-5 are very loose to loose with Dynamic Cone Penetration Test N-values ranging from 4 and 8 blows per 1-3/4 inches driven. The silty clay fill within boring B-5 contained an unidentified hydrocarbon odor.

The stratification depths shown on the soil boring logs represent the soil conditions at the boring locations. Variations may occur between borings. Additionally, the stratigraphic lines represent the approximate boundaries between soil types. The transition may be more gradual than what is shown. We have prepared the boring logs on the basis of laboratory classification and testing as well as field logs of the soils encountered.

The Soil Boring Location Plan, Plate No. 1, Soil Boring Logs, Figure Nos. 1 through 8 and Photographic Documentation, Figure Nos. 9 through 12, are presented in the Appendix. General Notes defining the nomenclature used on the boring logs and elsewhere in this report are presented on Figure No. 13.

PAVEMENT ASSESSMENT AND RECOMMENDATIONS

Option A – Mill and Overlay

Based on historical imagery, it appears the tennis courts were reconstructed/rehabilitated in 2005. The existing courts are experiencing moderate severity shrinkage cracking with several cracks open 1 to 2 inches wide. A few of the fence and net posts are experiencing heaving.



Therefore, given the thickness of the existing bituminous pavement and underlying pulverized bituminous concrete, we recommend milling the court surface 1-1/2 inches, perform any full depth patching as necessary, and construct a new 1-1/2 inch thick bituminous concrete overlay.

Prior to the overlay, any existing cracks or joints in the pavement surface wider than 1/8 inch should be filled with hot-applied bituminous crack filler. Any areas of the pavement that exhibit excessive fatigue cracking or deterioration should be replaced with a full depth patch prior to placement of the new bituminous concrete overlay. The bituminous concrete should be saw-cut a minimum 2 feet laterally from the distressed area to be removed. Prior to placing the full-depth patch, a tack coat should be applied to the sides of the saw-cut pavement.

Within any potential full depth bituminous concrete replacement patches, the exposed subgrade should be evaluated for stability. We recommend the exposed subgrade be thoroughly proof rolled, and evaluated for instability and/or unsuitable soil conditions. Any unstable or unsuitable areas noted should be improved by compaction or removed and replaced with MDOT 21AA aggregate placed in an engineered manner.

Based on the results of our analyses, we recommend a bituminous concrete pavement design section for the mill and overlay consisting of 1-1/2 inches of MDOT 36A bituminous concrete wearing course, after any full depth patching, as required.

Option B – Full Depth Reconstruction

Alternatively, we recommend completely removing the bituminous concrete pavement surface and sufficient amount of underlying pulverized bituminous concrete to support a new tennis court pavement section. We do not recommend reusing the existing pulverized bituminous concrete due to the risk of the pulverized bituminous concrete becoming unstable. We recommend the exposed subgrade be thoroughly proof rolled with a heavy rubber tired vehicle such as a tandem axle dump truck and visually evaluated for instability and/or unsuitable soil conditions. Areas of instability during construction traffic loading and proof roll operations should be expected within at least the area of soil boring B-5. An allowance for undercuts due to the existing fill soils should be allotted. Upon completion of proof roll operations, the subgrade should be graded to promote effective surface drainage and prevent water from ponding and the new pavement section may be constructed. We recommend all earthwork operations be performed in accordance with comprehensive specifications and be properly monitored in the field by qualified personnel under the direction of a licensed engineer.

Subgrade undercuts, where required, should be evaluated by a qualified engineering technician to determine if subgrade stabilization is necessary. We recommend that undercut excavations, where required, be backfilled with MDOT 21AA dense-graded aggregate (limestone) and placed in uniform horizontal layers, not more than 9 inches in loose thickness. The engineered fill should be compacted to achieve a density of at least 95 percent of the maximum dry density as determined by the Modified Proctor compaction test (ASTM D 1557). All engineered fill material should be placed and compacted at approximately the optimum moisture content. Frozen material should not be used as fill, nor should fill be placed on a frozen subgrade.

Full Depth Reconstruction Pavement Design

Based on our analyses, we recommend a pavement design section consisting of 1-1/2 inches of 36A bituminous concrete wearing course, 2 inches of 13A bituminous concrete leveling course, supported on a minimum of 8 inches of MDOT 21AA dense-graded limestone aggregate. An acrylic latex coating should be applied to the finished bituminous pavement surface upon completion of pavement curing period. We recommend a minimum pavement curing period of two weeks prior to placing an acrylic coating. However, the acrylic coating manufactures recommendations should be followed and can be longer than two weeks.

All pavement materials are specified within the 2012 Standard Specifications for Construction from the Michigan Department of Transportation. The bituminous pavement materials are described in Section 501.

Pavement Drainage and Maintenance

The pavement should be properly sloped to promote effective surface drainage and prevent water from ponding. Regular timely maintenance should be performed on the bituminous pavement to reduce the potential deterioration associated with moisture infiltration through surface cracks. Detroit Country Day School should be prepared to seal the cracks with a hot-applied elastic crack filler as soon as possible after cracking develops and as often as necessary to block the passage of water to the subgrade soils.

GENERAL COMMENTS

We have formulated the evaluations and recommendations presented in this report relative to site preparation and pavement construction on the basis of data provided to us relating to the general location for the proposed pavement improvements. Any significant change in this data should be brought to our attention for review and evaluation with respect to the prevailing subsurface conditions.


The scope of the present investigation was limited to evaluation of subsurface conditions for the support of the pavements and other related aspects of the development. No chemical, environmental, or hydrogeological testing or analyses were included in the scope of this investigation. If changes occur in the design, location, or concept of the project, the conclusions and recommendations contained in this report are not valid unless G2 Consulting Group, LLC reviews the changes. G2 Consulting Group, LLC will then confirm the recommendations presented herein or make changes in writing.

We have based the analyses and recommendations submitted in this report upon the data from soil borings performed at the approximate locations shown on the Soil Boring Location Plan, Plate No. 1. This report does not reflect variations that may occur between the actual boring locations. The nature and extent of any such variations may not become clear until the time of construction. If significant variations then become evident, it may be necessary for us to re-evaluate our report recommendations.

Soil conditions at the site could vary from those generalized on the basis of soil borings made at specific locations. It is, therefore, recommended that G2 Consulting Group, LLC be retained to provide soil engineering services during the site preparation and pavement construction phases of the proposed project. This is to observe compliance with the design concepts, specifications, and recommendations. Also, this allows design changes to be made in the event that subsurface conditions differ from those anticipated prior to the start of construction.

APPENDIX

Soil Boring Location PlanPlate No. 1Soil Boring LogsFigure Nos. 1 through 8Photographic DocumentationFigure Nos. 9 through 12General Notes TerminologyFigure No. 13



Legend

Soil Borings performed by G2 Consulting Group, LLC on April 5, 2019

Soil Boring Location Plan

Detroit Country Day Tennis Courts 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025

	Project No. 1902	34
	Drawn by: GMB	
	Date: 4-16-19	Plate
_	Scale: NTS	No. 1

Pro	oject Name	: Detroit Country Day School Tennis Cou	ts			Soil B	oring	No. B -1
Pro	oject Locat	ion: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025		(2		NSULTI	NG GR	OUP
G2	Project No	p. 190234			7			001
Lat	itude: N/A	A Longitude: N/A						
		SUBSURFACE PROFILE			SO	IL SAMPL		
DEPTH (ft)	PRO- FILE	GROUND SURFACE ELEVATION: N/A	DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	UNCOF. COMP. ST. (PSF)
		Bituminous Concrete (3 inches)	.3					
-		Pulverized Bituminous Concrete (19 inches)	.8	-				
	-	L	<u>.</u>	S-1	8			
_		Loose Brown Silty Sand	.0					
	T	Loose Brown Sand with trace gravel	.0	S-2	6			
		End of Boring @ 4 ft						
5			5					
	-			-				
-			-	-				
6								
/16/1								
DT 4								
ATE.C								
TEMPI								
DATA								
LTING	-		+	-				
ONSU								
0 G2 C								
14082			10					
77 Tota Drill	l Depth: ing Date: ector:	4 ft April 5, 2019	3-		oservation: luring and u	pon compl	etion of d	lrilling
PAVEMENT CORE DCP 190234.GPJ 20140820 G2 CONSULTING DATA TEMPLATE.GDT 4/19/19 - C - D - D - D - D - D - D - D - D - D	tractor:	G2 Consulting Group, LLC GMB	Exca	vation Bac	kfilling Proc gs and cold	edure: patch		
Drill	ing Methoo inch diamo	eter diamond tipped core barrel and						
-6 -6	inch diame	eter hand auger						Figure No. 1

Project Location: 22.305 West Thirteen Mile Read Beverity Hills, Michigan 46025 C2 Project No. 190234 Latitude: N/A Longitude: N/A SUBSURFACE LEVATION: N/A DOT: <u>AMPLE DATA</u> <u>Provence Bournings Concrete</u> <u>Provence Bournings Concrete</u> <u>Concrete Concrete</u> <u>Provence Bournings Concrete</u> <u>Concrete Concrete</u> <u>Provence Concrete</u> <u>Concrete Concrete Concrete</u> <u>Concrete Concrete Concrete</u> <u>Concrete Concrete Concrete</u> <u>Concrete Concrete Concrete Concrete Concrete Concrete <u>Concrete Concrete Concrete</u> <u>Concrete Concrete Concrete</u></u>		Proje	ct Name:	Detroit Country Day School Tennis Co	ourts	5			Soil B	oring	No. B –2	2
G2 Project No. 190234 Latitude: N/A SUBSURFACE PROFILE SOIL SAMPLE DATA MOSTURE (To THE INCOME SUBSURFACE PROFILE BIUMINOUS CONCRETE (3) Inches) 0.3 Pulverized Bituminous Concrete (7) Inches) 0.3 Deptid (10, The Notices) MOSTURE (10, The Notices) Deptid (10, The Notices) MOSTURE (10, The Notices) Deptid (10, The Notices) Deptid (10, The Notices) MOSTURE (10, The Notices) Deptid (10, The		Proje	ct Locati	on: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025			(2		NSULTI		OUP	
SUBSURFACE PROFILE SOIL SAMPLE DATA DEPTH (th) PRO- FILE GROUND SURFACE ELEVATION: N/A DEPTH (th) Sample (th) DCP BLOWS (th) MOSTURE (DISTIVE (DISTIVE (T)) DBNTY (PCF) UNCOF. COMP.ST. (PSF) Bituminous Concrete (3 inches) 0.3 Pulverized Bituminous Concrete (7 inches) 0.3 0.8 5-1 5-1 Stiff Brown Silty Clay with trace sand and gravel 1.5 2.0 5-1 5-2 24.4 2500* Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel 4.0 5-3 21.3 4000=			-					7				
DEPTH (ft) PRO- FILE GROUND SURFACE ELEVATION: N/A DEPTH (ft) SAMPLE TYPE/NO. DCP BLOWS IT/SINCHES MOSTURE OWNTHY DRY (DEPT) UNCOF. COMP. 5T. (PCF) Bituminous Concrete (7 Inches) 0.8 0.8		Latitu	ude: N/A									
Origin Type://doi CONTENT Desire (C) Bituminous Concrete (3 inches) 0.3 Pulverized Bituminous Concrete (7 inches) 0.3 Fill: Portland Cement Concrete Fragments 0.4 Stiff Brown Silty Clay with trace sand and gravel 5 Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel 5 End of Boring @ 4 ft 5				SUBSURFACE PROFILE								
(3 inches) 0.3 Pulverized Bituminous Concrete 0.8 Fill: Portland Cement Concrete 0.8 Fragments 1.5 Stiff Brown Silty Clay with trace sand and gravel 2.0 Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel 5-2 Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel 5-3 End of Boring @ 4 ft 5 5 5		DEPTH (ft)	PRO- FILE			DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	CONTENT	DENSITY	COMP. ST.	
(7 inches) 0.8 Fill: Portland Cement Concrete 1.5 Stiff Brown Silty Clay with trace sand and gravel 2.0 Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel S-2 24.4 2500* Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel S-3 21.3 4000* End of Boring @ 4 ft 5 5 1.5 1.5				(3 inches)	0.3							
Fill: Portland Cement Concrete Fragments 1.5 S-1 S-1 Stiff Brown Silty Clay with trace sand and gravel 2.0 S-2 24.4 2500* Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel S-3 21.3 4000* End of Boring @ 4 ft 5 5 Image: Silty Clay is the same same same same same same same sam				Pulverized Bituminous Concrete (7 inches)	0.8							
1.5 S-1 - Stiff Brown Silty Clay with trace sand and gravel 2.0 S-2 24.4 2500* Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel - - - - - Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel - - - - - Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - - Find of Boring @ 4 ft - - - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - - - Stiff Mottled Brown and Gray Silty Clay - - - - - -				Fill: Portland Cement Concrete								
and gravel 2.0 S-2 24.4 2500* Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel - - - - 4.0 S-3 21.3 4000* 5 - - - -					1.5		S-1					
Stiff Mottled Brown and Gray Silty Clay with trace sand and gravel End of Boring @ 4 ft 5 5 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7				Stiff Brown Silty Clay with trace sand and gravel					24.4		2500*	
with trace sand and gravel 4.0 S-3 21.3 4000* 6 5 5 5 1 1 1		-			2.0		5-2		24.4		2500^	
with trace sand and gravel 4.0 S-3 21.3 4000* 6 5 5 5 1 1 1												
with trace sand and gravel 4.0 S-3 21.3 4000* 6 5 5 5 1 1 1				Stiff Mottled Brown and Gray Silty Clay								
End of Boring @ 4 ft				with trace sand and gravel								
End of Boring @ 4 ft												
		-			4.0		S-3		21.3		4000*	
				End of Boring @ 4 ft								
						_						
Image: Construction of the construc						5						
Image: Construction of diameter diamond tipped core barrel and 3-inch diameter hand auger Image: Construction of tipped core barrel and 3-inch diameter hand auger												
Image: constraint of the second se												
10												
10 -												
10 10 Total Depth: 4 ft Drilling Date: April 5, 2019 Inspector: Drilling Date: Contractor: G2 Consulting Group, LLC Drilling Method: * Calibrated Hand Penetrometer 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Figure No. 2	19											
10 10 <td< td=""><td>4/19/</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	4/19/											
10	.GDT											
10 10 10 10	IPLATE						-					
10 10 <td< td=""><td>LA TEN</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	LA TEN											
10 10 <td< td=""><td>NG DA</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	NG DA											
10 10 <td< td=""><td>SULTI</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	SULTI											
10 10 10 10 Total Depth: 4 ft Water Level Observation: Drilling Date: April 5, 2019 Dry during and upon completion of drilling operations Inspector: G2 Consulting Group, LLC Notes: Drilling Method: * Calibrated Hand Penetrometer 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Figure No. 2	Z CON											
Total Depth: 4 ft Water Level Observation: Drilling Date: April 5, 2019 Dry during and upon completion of drilling operations Inspector: G2 Consulting Group, LLC Notes: Driller: GMB * Calibrated Hand Penetrometer Drilling Method: 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Mater Level Observation: Drilling Method: * Calibrated Hand Penetrometer Excavation Backfilling Procedure: Auger cuttings and cold patch Figure No. 2 Figure No. 2)820 G	10				10						
Inspector. G2 Consulting Group, LLC Notes: Contractor: G2 Consulting Group, LLC * Calibrated Hand Penetrometer Driller: GMB * Calibrated Hand Penetrometer Drilling Method: Auger cuttings and cold patch 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Figure No. 2	GPJ 2014(Total D Drilling	j Date:						npletion o	f drilling o	perations	
Drilling Method: 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Figure No. 2	¹⁹⁰²³⁴ .	Contra Driller:	ctor:					Hand Penetr	rometer			
Of Drilling Method: Auger cuttings and cold patch 4-inch diameter diamond tipped core barrel and 3-inch diameter hand auger Figure No. 2	RE DC					Excav	ation Bac	kfilling Proc	edure:			
3-inch diameter hand auger Figure No. 2	ENT CO	Drilling 4–inc	ch diame	ter diamond tipped core barrel and		Aug	jer cuttin	ys anu colu	μαιτη			
	AVEME	3-inc	ch diame	ter hand auger							Figure No.	. 2

	Proj	ject Nan	ne: Detroit Country Day School Tennis Court	s			Soil B	oring	No. B-3
	Proj	ject Loc	ation: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025		(2		NSULTI	NG GRO	JUP
		Project				7			
	Lati	tude: N							
			SUBSURFACE PROFILE				IL SAMPL MOISTURE		UNCOF.
	DEPTH (ft)	PRO- FILE	GROUND SURFACE ELEVATION: N/A	DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	CONTENT (%)	DENSITY (PCF)	UNCOF. COMP. ST. (PSF)
		****	Bituminous Concrete (3 inches)	3					
			Fill: Pulverized Bituminous Concrete		-				
			with concrete fragments		S-1				
			2.						
			End of Boring @ 2 ft, Auger Refusal						
	5			5					
					-				
9/19									
7 4/19									
TE.GDT									
MPLAT					-				
TA TE									
NG D/									
ISULTI					-				
2 CON									
)820 G	10			10					
GPJ 2014(Total Drillin	Depth: ng Date	2 ft : April 5, 2019	Water Dry	Level Ob during a	oservation: nd upon cor	mpletion o	f drilling o	perations
PAVEMENT CORE DCP 190234.GPJ 20140820 G2 CONSULTING DATA TEMPLATE.GDT 4/19/19	Inspe Contr Drille	ractor:	G2 Consulting Group, LLC GMB	Excav Aug	ation Bac ger cuttin	kfilling Proc gs and cold	edure: patch		
NRE DC									
NT CO	Drilliı 4-i	ng Meth nch diai	meter diamond tipped core barrel and						
VEMEI	3-i	nch diar	meter hand auger						Figure No. 3
PA									rigure NO. 5

Project Nan	ne: Detroit Country Day School Tennis C	ourts	5			Soil B	oring	No. B-4
Project Loca	ation: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025			(2		NSULTI		OUP
G2 Project	No. 190234				7			
Latitude: N								
	SUBSURFACE PROFILE				SO	L SAMPL		
DEPTH PRO- (ft) FILE	GROUND SURFACE ELEVATION: N/A Bituminous Concrete		DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	UNCOF. COMP. ST. (PSF)
_	(3 inches)	0.3						
	Pulverized Bituminous Concrete	1.0						
	End of Boring @ 1 ft, Auger Refusal	1.0						
5			5					
10			10					
Total Depth: Drilling Date	1 ft April 5, 2019				oservation: nd upon coi	npletion o	f drilling o	operations
Inspector: Contractor: Driller:	G2 Consulting Group, LLC GMB		Excav Aug	ation Bac er cuttin	kfilling Proc gs and cold	edure: patch		
Drilling Meth 4-inch diar	neter diamond tipped core barrel and							
3-inch diar	neter hand auger							Figure No. 4

PAVEMENT CORE DCP 190234.CPJ 20140820 G2 CONSULTING DATA TEMPLATE.GDT 4/19/19

Pro	ject Nam	e: Detroit Country Day School Tennis Co	ourts				Soil B	oring	No.	B-5
Pro	ject Loca	ition: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025			(2		NSULTI	-		
G2	Project N	No. 190234				7				
Lat	itude: N/	A Longitude: N/A								
		SUBSURFACE PROFILE				SO	L SAMPL			
DEPTH (ft)	PRO- FILE	GROUND SURFACE ELEVATION: N/A		DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	COM	COF. IP. ST. SF)
		Bituminous Concrete (5 inches)	0.5							
	×××××	Pulverized Bituminous Concrete (7 inches)	1.0							
		Fill: Stiff Gray Silty Clay with metal fragments, lime, and hydrocarbon odor	3.0		S-1		21.6		40	00*
	⊥	- Very Loose Brown and Gray Silty Sand	4.0		S-2	4				
		End of Boring @ 4 ft								
				_						
5	$\frac{1}{2}$		-	5						
			ŀ							
0										
19/16										
DT 4,										
ATE.G										
TEMPL										
DATA										
DNIL -										
ONSUL										
62 00										
10 40820				10						
Total Drilli	Depth: ng Date:	4 ft April 5, 2019		3-1		oservation: uring and u	pon compl	etion of d	rilling	
	ractor:	G2 Consulting Group, LLC GMB		Notes	:	Hand Peneti	rometer			
Drilli 4-i	ng Metho nch dian	neter diamond tipped core barrel and		Excav Aug	ation Bac er cuttin	kfilling Proc gs and cold	edure: patch			
I-E BAVEM	nch dian	neter hand auger							Figu	re No. 5

	Project N			rts		6		Soil B	oring	No.	B-6
	G2 Project L		on: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025 . 190234			(2	7 ^{COI}	NSULTI	NG GR	OUP	
	Latitude:										
			SUBSURFACE PROFILE				SO	L SAMPL	E DATA		
DE (PTH PRO- ft) FILE		GROUND SURFACE ELEVATION: N/A	DEP (ft	TH t)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	UN CO (I	ICOF. MP. ST. PSF)
			(5 lifelies)	.3							
			End of Boring @ 0.5 ft, Auger Refusal								
					_						
_											
	5			5							
_					_						
6											
4/19/1											
ATE.GDT											
A TEMPL/					_						
NG DAT/											
					-						
820 G2 C	10			10)						
D 20140	otal Dept rilling Da	h: ite:	0.5 ft April 5, 2019	Wa	ter		oservation: nd upon cor	npletion o	f drilling o	operatio	ons
P 190234.	spector: ontractor riller:		G2 Consulting Group, LLC GMB	Exc A	av Nug	ation Bac er cuttin	kfilling Proc gs and cold	edure: patch			
CORE DC	rilling Me	thod	ŀ								
/EMENT	4-inch d	iame	 ter diamond tipped core barrel and ter hand auger							_ .	
PA										Figu	ire No. 6

Pro	ject Name	e: Detroit Country Day School Tenr	nis Courts	5			Soil B	oring	No. B-7
Pro <u></u>	ject Locat	ion: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025			(2		NSULTI	NG GRO	OUP
G2	Project N	o. 190234				7			
Lati	itude: N/A								
	, ,	SUBSURFACE PROFILE				SO	IL SAMPL		
DEPTH (ft)	PRO- FILE	GROUND SURFACE ELEVATION: N	N/A	DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	UNCOF. COMP. ST. (PSF)
	P 4 4 P	Bituminous Concrete (3 inches)	0.3						
		Crushed Concrete (3"–1")	1.0						
		End of Boring @ 1 ft, Auger Refusal							
5				5					
	-								
	_								
ИЕ.ЫЛ! 4/⊥ 1									
20140820 02 CONSULING DATA TEMPRATE.GUI 4/19/19 10 10 10 10									
10 10 10				10					
	Depth: ng Date:	1 ft April 5, 2019				oservation: nd upon coi	mpletion o	f drilling o	perations
ភិ Drille	ractor:	G2 Consulting Group, LLC GMB		Excav Aug	ation Bac Jer cuttin	kfilling Proc gs and cold	edure: patch		
z 4-i	ng Metho nch diam nch diam	d: eter diamond tipped core barrel and eter hand auger							Figure No. 7

Figure No. 7

Pro	ject Name	e: Detroit Country Day School Ten	nis Courts	5			Soil B	oring l	No. B-8
Pro <u></u>	ject Locat	ion: 22305 West Thirteen Mile Road Beverly Hills, Michigan 48025			(2		NSULTI	NG GRO	OUP
G2	Project N	o. 190234				7			
Lati	tude: N/A								
		SUBSURFACE PROFILE				SO	IL SAMPL		
DEPTH (ft)	PRO- FILE	GROUND SURFACE ELEVATION:	N/A	DEPTH (ft)	SAMPLE TYPE/NO.	DCP BLOWS/ 1.75-INCHES	MOISTURE CONTENT (%)	DRY DENSITY (PCF)	UNCOF. COMP. ST. (PSF)
	P 6 4 P	Bituminous Concrete (3 inches)	0.3						
		Crushed Concrete (3"-1")	1.0						
		End of Boring @ 1 ft, Auger Refusal							
5				5					
				10					
	Depth: ng Date:	1 ft April 5, 2019		Water		servation: nd upon coi	mpletion o	f drilling o	perations
최 Drille	ractor:	G2 Consulting Group, LLC GMB		Excav Aug	ation Bac Jer cuttin	kfilling Proc gs and cold	edure: patch		
z 4-i	ng Metho nch diam nch diam	d: eter diamond tipped core barrel and eter hand auger	ł						Figure No. 8

Figure No. 8

Photographic Documentation Detroit Country Day Tennis Courts Beverly Hills, Michigan 48025 G2 Project No. 190234



Photograph No. 1: Looking North from Soil Boring B-4



Photograph No. 2: Looking North at Soil Boring B-8

Photographic Documentation Detroit Country Day Tennis Courts Beverly Hills, Michigan 48025 G2 Project No. 190234



Photograph No. 3: Drain Tile Along East Side of Courts



Photograph No. 4: Looking North at Soil Boring B-2



Photograph No. 5: Looking West at Soil Boring B-1



Photograph No. 6: Looking North at Soil Boring B-7



Photograph No. 7: Looking South at Soil Boring B-2



GENERAL NOTES TERMINOLOGY

Unless otherwise noted, all terms herein refer to the Standard Definitions presented in ASTM 653.

PARTICLE SIZE

Boulders Cobbles Gravel - Coarse - Fine Sand - Coarse - Medium - Fine Silt

Clay

avector then 12 inches
- greater than 12 inches
- 3 inches to 12 inches
- 3/4 inches to 3 inches
- No. 4 to 3/4 inches
- No. 10 to No. 4
- No. 40 to No. 10
- No. 200 to No. 40
- 0.005mm to 0.074mm
- Less than 0.005mm

CLASSIFICATION

The major soil constituent is the principal noun, i.e. clay, silt, sand, gravel. The second major soil constituent and other minor constituents are reported as follows:

Second Major Constituent (percent by weight) Trace - 1 to 12% Adjective - 12 to 35% And - over 35% Minor Constituent (percent by weight) Trace - 1 to 12% Little - 12 to 23% Some - 23 to 33%

COHESIVE SOILS

If clay content is sufficient so that clay dominates soil properties, clay becomes the principal noun with the other major soil constituent as modifier, i.e. sandy clay. Other minor soil constituents may be included in accordance with the classification breakdown for cohesionless soils, i.e. silty clay, trace sand, little gravel.

	Unconfined Compressive	
Consistency	Strength (psf)	Approximate Range of (N)
Very Soft	Below 500	0 - 2
Soft	500 - 1,000	3 - 4
Medium	1,000 - 2,000	5 - 8
Stiff	2,000 - 4,000	9 - 15
Very Stiff	4,000 - 8,000	16 - 30
Hard	8,000 - 16,000	31 - 50
Very Hard	Over 16,000	Over 50

Consistency of cohesive soils is based upon an evaluation of the observed resistance to deformation under load and not upon the Standard Penetration Resistance (N).

	COHESIONLESS SOILS	
Density Classification	Relative Density %	Approximate Range of (N)
Very Loose	0 - 15	0 - 4
Loose	16 - 35	5 - 10
Medium Compact	36 - 65	11 - 30
Compact	66 - 85	31 - 50
Very Compact	86 - 100	Over 50

Relative Density of cohesionless soils is based upon the evaluation of the Standard Penetration Resistance (N), modified as required for depth effects, sampling effects, etc.

SAMPLE DESIGNATIONS

- AS Auger Sample Cuttings directly from auger flight
- BS Bottle or Bag Samples
- S Split Spoon Sample ASTM D 1586
- LS Liner Sample with liner insert 3 inches in length
- ST Shelby Tube sample 3 inch diameter unless otherwise noted
- PS Piston Sample 3 inch diameter unless otherwise noted
- RC Rock Core NX core unless otherwise noted

STANDARD PENETRATION TEST (ASTM D 1586) - A 2.0 inch outside-diameter, 1-3/8 inch inside-diameter split barrel sampler is driven into undisturbed soil by means of a 140-pound weight falling freely through a vertical distance of 30 inches. The sampler is normally driven three successive 6-inch increments. The total number of blows required for the final 12 inches of penetration is the Standard Penetration Resistance (N).

Asphalt Specialists, Inc.



May 2, 2019

Detroit Country Day School ATTN: Scott Stanley 22305 West Thirteen Mile Road Beverly Hills, MI 48025 248-514-8380 <u>sstanley@dcds.edu</u>

RE: Detroit Country Day School – Tennis Courts

Dear Scott:

We are pleased to offer you our budget estimate for the Detroit Country Day tennis court removal and replacement project. Our enclosed bid closely follows the G2 consulting report for both materials and thicknesses. When reviewing the report, there are a couple noteworthy points that I want to take a moment and highlight.

- The existing courts are paved over a pulverized base, which is really just ground up asphalt and then recycled to be used under the courts. They do not recommend using the existing pulverized asphalt, due to the risk of the pulverized base becoming unstable as it is now. This is clearly explained under Option B, full depth reconstruction.
- On page 4, full depth reconstruction, they are suggesting which I also concur with, using 8.0" of MDOT 21AA limestone aggregate followed by 2.0" of MDOT #13A leveling course asphalt, then a 1.5" of MDOT #36A asphalt wearing course. The one thing that they did not mention, which I feel strongly about, is that both the wearing course and the leveling course should be 100% virgin aggregate materials. I do not want to have any recycled products (rubber, brick block, slag, etc...) in the asphalt courses because that's what causes the pops in the acrylic and or that rust staining that you see on the courts currently. No matter what, you have to use virgin aggregates to ensure that we are using all natural sand and gravel in the paving process.

Attached is our budget for you review. If you or the board has any further questions, please feel free to call. We appreaciate the opportunity for ASI to be part of this project.

Thank you,

Bruce Israel

Page | 1

1780 E. Highwood, Pontiac, MI 48340 * 248-334-4570 phone * 248-334-0134 fax

Detroit Country Day – Tennis Courts Budget

We are pleased to quote on the asphalt removal and replacement and miscellaneous site work required at the above referenced project. Our base bid includes the following:

- Engineering, Surveying, Layout and Construction Testing......
- Miscellaneous Demolition and Removals.....

Tennis Court Removal and Replacement

- 1. Onsite excavation and demo
 - A. Excavate and remove from site the entire existing asphalt surface;
 - B. Excavate and remove existing pulverized materials to allow for the new 12.0" section;
 - C. Currently it calls for approximately 4,100 YD of material to be loaded and hauled off-site;
- 2. Grade and compact sub grade, proof roll as required;
- 3. Place 8.0" of MDOT 21AA limestone aggregate;
- 4. Place 2.0" of MDOT #13A asphalt leveling course with all Virgin aggregate and compact;
- 5. Place SS 1-H tack coat for adhesion;
- 6. Place 1.5" of MDOT #26A asphalt wearing course with all Virgin aggregate and compact;
- 7. Clean up all ASI related debris.

Tennis Court Removal and Replacement......

Edge Drain Installation (approx. 1,000 LF)

1. I want to take advantage of the trench drain at the end of the courts and run lateral fingers of edge drain throughout.


Edge Drain Installation.....

- 10 Courts of Color Coating......
- New net posts, nets and center strap......

Fence Removal and Replacement

- 1. Roll up and remove the fence fabric;
- 2. Excavate and haul from site the fence posts and footings;
- 3. Re-install new fence posts, footings and fabric, 10 FT taall with black vinyl and 8 FT center;

Fence	e Removal and Replacement		
•	Miscellaneous brick work, sidewalk along western edge for access Beverly Hills Permit and Review Site contingency/ Sub-grade undercut contingency		
OUR	LUMP SUM PRICE PER THE ABOVE IS	terraturities instants of the sec)



	•
	•
	•
	•
	_ <u>•</u>
/08/2019	DCD MIDDLE SCH. SECURITY OFFICE
/13/2018	REVISED PLAYGROUND/SECURITY OFFICE
/27/2018	REVIEW
ATE:	ISSUED FOR:
RAWN	MLW
HECKED	TAC
PROVED	TAC

VILLAGE MANAGER'S REPORT CHRIS D. WILSON OCTOBER 11, 2019

Senior Joint Services Commission – There was a meeting of the Senior Joint Services Commission on Thursday, October 10th at Birmingham City Hall. I was not able to attend the meeting. Beverly Hills representative Jim Delaney did attend and is keeping me updated on the progress of the commission. Jim will likely be present at the meeting to give the Council an update on the progress of the meeting.

Water Testing – The Village has received some calls regarding water testing due to reports of testing in the City of Birmingham. The Village conducted the same number of tests as did Birmingham during the same time period and met all testing standards. These tests were open to any resident who wished to be tested. Some residents have requested testing based upon the most recent stories. Although the required testing period has passed, the Village will still offer water testing to any resident who is interested at no charge. Samples taken from the home will be tested at the same laboratory and results shared with the homeowner. Any resident interested in receiving testing, or in being included in future rounds of mandatory testing, can contact the Village offices.

South Oakland County Mayors Association Dinner – The October South Oakland Mayors Association Dinner is on Wednesday, October 16th and Council is invited to attend. The Village is jointly hosting this event along with the cities of Birmingham, Berkley, Lathrup Village and Royal Oak Township. Newly appointed Oakland County Executive Dave Coulter has agreed to be the guest speaker at this event.

Halloween Hoot – The 24th Annual Halloween Hoot is Saturday, October 26, 2019 at Beverly Park. There are details on the Village's website and Facebook page. A special thanks to Trish Oen and all the volunteers who help organize this event.

Beverly Hills Public Safety Activity Report

September 26th- October 10th, 2019

- The Public Safety Department is currently looking for applicants for Public Safety Officer. Please visit our website, **www.beverlyhillspolice.com** to see if you qualify.
- Warm weather brings out motorcycles and bicyclist. Look twice and save a life.
- Remember to lock your car and house doors.
- Do not leave valuables inside your car. Do not leave your keys in your car.

10 Steps to Avoid Scams

There are thousands of new scams every year, and you can't keep up with all of them (we know, we try!). But if you can just remember these TEN THINGS, you can avoid most scams and help protect yourself and your family.

- 1. Never send money to someone you have never met face-to-face. Seriously, just don't ever do it. And really, really don't do it if they ask you to use wire transfer, a prepaid debit card, or a gift card (those cannot be traced and are as good as cash).
- 2. Don't click on links or open attachments in unsolicited email. Links can download malware onto your computer and/or steal your identity. Be cautious even with email that looks familiar; it could be fake.
- 3. **Don't believe everything you see.** Scammers are great at mimicking official seals, fonts, and other details. Just because a website or email looks official does not mean that it is. Even Caller ID can be faked.
- 4. Don't buy online unless the transaction is secure. Make sure the website has "https" in the URL (the extra s is for "secure") and a small lock icon on the address bar. Even then, the site could be shady. Check out the company first at bbb.org. Read reviews about the quality of the merchandise, and make sure you are not buying cheap and/or counterfeit goods.
- 5. Be extremely cautious when dealing with anyone you've met online. Scammers use dating websites, Craigslist, social media, and many other sites to reach potential targets. They can quickly feel like a friend or even a romantic partner, but that is part of the con to get you to trust them.
- 6. Never share personally identifiable information with someone who has contacted you unsolicited, whether it's over the phone, by email, on social media, even at your front door. This includes banking and credit card information, your birthdate, and Social Security/Social Insurance numbers.

- 7. Don't be pressured to act immediately. Scammers typically try to make you think something is scarce or a limited time offer. They want to push you into action before you have time to think or to discuss it with a family member, friend, or financial advisor. High-pressure sales tactics are also used by some legitimate businesses, but it's never a good idea to make an important decision quickly.
- 8. Use secure, traceable transactions when making payments for goods, services, taxes, and debts. Do not pay by wire transfer, prepaid money card, gift card, or other non-traditional payment method. Say no to cash-only deals, high pressure sales tactics, high upfront payments, overpayments, and handshake deals without a contract.
- 9. Whenever possible, work with local businesses that have proper identification, licensing, and insurance, especially contractors who will be coming into your home or anyone dealing with your money or sensitive information. Check them out at bbb.org to see what other consumers have experienced.
- 10. Be cautious about what you share on social media and consider only connecting with people you already know. Be sure to use privacy settings on all social media and online accounts. Imposters often get information about their targets from their online interactions, and can make themselves sound like a friend or family member because they know so much about you.

CALLS FOR SERVICE

- 228 Calls for Service.
- 15 Arrests.
- 113 Tickets issued.
- 2 Walk in PBT's.
- 8 Prescription pill drop offs.
- Vacation checks.
- Car Seat Checks.
- Gun Permit.
- Crossing Guard on Beverly.
- Motor Carrier enforcement.
- 9 Prisoner transports to and from the Birmingham Police Department.
- 4 Traffic Accidents on 13 Mile Rd.
- 3 Traffic Investigations on 13 Mile Rd.
- 2 Alarms on 13 Mile Rd.
- 7 Medicals on 13 Mile Rd.
- Parking complaint on 13 Mile Rd.
- Suspicious Circumstance complaints on 13 Mile Rd.
- 2 Suspicious Persons complaints on 13 Mile Rd.
- 3 Motorist Assists on 13 Mile Rd.
- Reckless Driving on 13 Mile Rd.

- Citizen Assist on 13 Mile Rd.
- 2 Animal complaints on 13 Mile Rd.
- 2 Traffic Accidents on Southfield.
- Animal complaint on Southfield.
- Officers responded to a commercial business on Southfield for a disturbance. Subsequent investigation revealed probable cause to arrest an individual on domestic assault.
- Traffic complaints on Southfield.
- Parking complaint on Southfield.
- Suspicious Person on Southfield.
- Missing Person on Southfield.
- Assist Oakland County with traffic light on Southfield.
- Suspicious Vehicle on 14 Mile Rd.
- Alarm on 14 Mile Rd.
- Welfare Check on 14 Mile Rd.
- Impounded Vehicle on 14 Mile Rd.
- Motorist Assist on 14 Mile Rd.
- Traffic Accident on 14 Mile Rd.
- Motorist Assist on 14 Mile Rd.
- Traffic Accident on Evergreen.
- Animal complaint on Evergreen.
- Medical on Evergreen.
- Traffic Accident on Lahser.
- Medical on Lahser.
- Parking complaint on Lahser.
- 2 Traffic Accidents on Greenfield.
- 2 Suspicious Persons complaints on Pierce.
- Alarm on Beverly Ct.
- Fire Alarm on Beverly.
- Assist DPW on Buckingham.
- Officers stopped a vehicle on Lahser for a traffic violation. The driver was suspected of operating while intoxicated. The driver was arrested without incident.
- Medical on Hillcrest.
- Citizen Assist on Hillcrest.
- Medical on Locherbie.
- Officers stopped a vehicle on 14 Mile. The driver was operating on a suspended license. The driver was arrested without incident.
- Alarm on Village Pines.
- Alarm on W. Chelton.
- Traffic Accident on W. Rutland.
- Alarm on Devonshire.
- Officers responded to 13 Mile for a traffic accident. The driver was suspected of operating while intoxicated. The driver was transported to the hospital. Criminal charges are pending.

- Medical on Fox Run.
- Medical on N. Nottingham.
- Lift Assist on Kirkshire.
- Suspicious Persons on Chelton.
- Officers met with Lathrup Village Police and arrested an individual held on a Beverly Hills Warrant. The arrest took place without incident.
- Traffic Accident on Buckingham.
- Medical on Birwood.
- Down Wire on Charrington.
- Medical on Westlady.
- Fraud on Reedmere.
- Officers responded to Redford Police Department to arrest an individual being held on a Beverly Hills Warrant. The individual was arrested without incident.
- Citizen Assist on Pickwick.
- Suspicious Persons on Madoline.
- Suspicious Circumstance on Long Bow Ct.
- Officers responded to Novi Police Department to arrest an individual being held on a Beverly Hills Warrant. The individual was arrested without incident.
- Medical on Madoline.
- Down Wire on Charrington Ct.
- Medical on W. Chelton.
- Lift Assist on Village Pines Dr.
- Officers stopped a vehicle on Evergreen for a traffic violation. The driver was operating on a suspended license. The driver was arrested without incident.
- Medical on Cline.
- Alarm on Orchard Way.
- Fire Alarm on Eastlady.
- Road Hazard on Kinross.
- Larceny on 13 Mile Rd.
- Suspicious Circumstance on E. Rutland.
- Damage to Property on Huntley Sq. E.
- Officers stopped a vehicle on Evergreen for a traffic violation. The driver was operating without a license. The driver was arrested without incident.
- Carbon Monoxide Alarm on Birwood.
- Noise complaint on Sheridan.
- Officers stopped a vehicle on 13 Mile for a traffic violation. The driver was operating on a suspended license and she had warrants for her arrest. The driver was arrested without incident.
- Parking complaint on Metamora.
- Traffic Accident on Sleepy Hollow.
- Lift Assist on McKenzie.
- Solicitor complaint on Corsaut.
- Officers responded to the Wayne County Jail to arrest an individual being held on a Beverly Hills Warrant. The arrest took place without incident.

- Noise complaint on Pierce.
- Medical on Locherbie.
- Officers stopped a vehicle on Lahser. The driver was suspected of operating while intoxicated. The driver was arrested without incident.
- 911 Hang Up Kirkshire.
- Suspicious Persons on Metamora.
- Officers stopped a vehicle on Sunnyslope for a traffic violation. The driver was operating without a license. The driver was arrested without incident.
- Suspicious Persons on Bedford.
- Alarm on Auburn.
- Larceny on Hillcrest.
- Alarm on Auburn.
- Lost Property on Chelton.
- Alarm on Chelton.
- Citizen Assist on Kinross.
- Traffic Accident on Thistle.
- Down Wire on Beechwood.
- Officers stopped a vehicle on Lahser for a traffic violation. The driver was operating on a suspended license. The driver was arrested without incident.
- Suspicious Persons on Eastlady.
- Officers stopped a vehicle on 13 Mile for a traffic violation. The driver was suspected of operating while intoxicated. The driver was arrested without incident.

INVESTIGATION

- CFS Closed and Reviewed 240.
- CFS Closed and Reviewed 215.
- Reviewed 38 case reports for a disposition.
- Followed up and reviewed cases; of which 27 were closed and 11 remain open.
- 11 Cases were assigned.
- 9 Reports written on current cases.
- 27 Current active investigations.
- 10 Current pending investigations.
- Domestic Investigation/warrant issued -Saturday Arraignment.
- Retail Fraud Interview. Restitution paid to business.
- Received Uttering & Publishing Warrant.
- OD Death Investigation-Sunday investigation/Interviews w/family.
- Attended autopsy at OCME.
- Assist Adult Protective Service with fraud case.
- Followed up on Home Invasion. Working with Franklin PD on related cases.
- Follow up on juvenile medical.
- Assist Groves High School with juvenile complaint.
- Arraigned OWI and FTD Warrant/ Arraigned OWI warrant-Saturday.
- Assist with cook fire response.

- Sent 2 blood kits to MSP.
- Issued 1 OWI Ticket.
- Groves HS Football game.
- Groves HS Home Coming Dance/Field Day.
- Provide presence during Walk to School Day Beverly Elementary.
- SLO Attended Alice training at Detroit County Day High School.
- Traffic Conference at 46th D.C.
- Assisted with 2 prisoner transports to 46th D.C.

FIRE PREVENTION

- 36 Fire/EMS Reports reviewed.
- 1 Fire Inspection Completed.
- 3 C/E Sponsorship Courses Administered.
- Mandated County Medical Training Course Administered.
- Uploaded NFIRS data to FEMA.
- Annual pump testing Ladder 34 completed.
- Attend South Oakland Fire Investigators Work Session.
- Annual pump testing for Squad 31 completed.
- Road Patrol Supervisor coverage.
- Update Electronic Fire Inspection forms.
- Finalize Multi-Agency mandated Recon RIT course.
- Coordinate Mandatory Medical Control EMS Training.
- Attend State Fire Marshal Town Hall Meeting.
- Equipment Mounting and Maintenance Ladder 34.
- Stephen Siller 9/11 Tunnel to Towers Foundation Run.
- Restock Medical Supplies.
- Archive 32 EMS Training Files.
- Follow up with Fire King Inc. regarding inspection deficiencies at Southfield Rd. business.

Enforcement Number	Address		Filed	Status	Closed			
E19016516994 KIRKSHIRE AVE09/05/19Resolved09/13/19TALKED WITH OWNERS WORKINGON TRAILERS CAMPERS-BLOCKING SIDEWALK. STATE IT WOULD BE REMOVED FROM AREA09/05/19Resolved								
Inspection Type	Status	Result	Scheduled	Completed	Inspector			
Enforcement Number	Address		Filed	Status	Closed			
E190169	30275 VERN	ON DR	09/03/1	9 Resolved	09/06/19			
1. AUTO'S CANNOT F 2. BOAT AND TRAILF HOUSE LINE					'EAR YARD, BEHIND			
Inspection Type	Status	Result	Scheduled	Completed	Inspector			
Enforcement Number	Address		Filed	Status	Closed			
Eligo170	31040 LAHSI		09/06/19		09/17/19			
BOAT AND TRAILER					, ,			
Inspection Type	Status	Result	Scheduled	Completed	Inspector			
Inspection Type	Status	Result	Scheduled	Completed	Inspector			
		Result		-				
Enforcement Number	Address		Filed	Status	Closed			
Enforcement Number E190171	Address 17501 DUNE	BLAINE AVE	Filed 09/06/1	Status 9 Resolved	Closed 09/13/19			
Enforcement Number E190171	Address 17501 DUNE EE BRANCH	BLAINE AVE ES, FROM ROA	Filed 09/06/11 D EDGE, COI	Status 9 Resolved	Closed			
Enforcement Number E190171 PLEASE REMOVE TR	Address 17501 DUNE EE BRANCH	BLAINE AVE ES, FROM ROA	Filed 09/06/11 D EDGE, COI	Status 9 Resolved	Closed 09/13/19			
Enforcement Number E190171 PLEASE REMOVE TR BE BUNDLED OR PL	Address 17501 DUNE EE BRANCH ACE IN PAPE	BLAINE AVE ES, FROM ROA CR BAGS COMP	Filed 09/06/19 D EDGE, COI LAINTS	Status 9 Resolved LLECTION W	Closed 09/13/19 VILL NOT PICK UP MUST			
Enforcement Number E190171 PLEASE REMOVE TR BE BUNDLED OR PL	Address 17501 DUNE EE BRANCH ACE IN PAPE	BLAINE AVE ES, FROM ROA CR BAGS COMP	Filed 09/06/19 D EDGE, COI LAINTS	Status 9 Resolved LLECTION W	Closed 09/13/19 VILL NOT PICK UP MUST			

PLEASE REMOVE TREE DEBRIS FROM ROAD EDGE, MUST BE BUNDLED OR PLACE IN PAPER BAGS FOR COLLECTION. MUST NOT BE OVER 40LBS

	Inspection Type	Status	Result	Scheduled	Completed	Inspector	
Enfor	cement Number	Address		Filed	Status	Closed	
E190	173	17341 KINR	.OSS AVE	09/11/19	9 Resolved	09/19/19	
PLEA	ASE CUT ADN TR	AIM FRONT A	AND REAR YAF	DS, COMPLA	ITNS 6-8" LI	MIT	
	Inspection Type	Status	Result	Scheduled	Completed	Inspector	
Enfor	cement Number	Address		Filed	Status	Closed	
E190	175	16270 BUCK	KINGHAM AVE	09/12/19	9 Resolved	09/17/19	
	ASE REMOVE BC VILLAGE CODE	OAT AND TR	AILER FROM D	RIVEWAY, CA	NOT BE STO	ORED ON PROEPRTY.	
	Inspection Type	Status	Result	Scheduled	Completed	Inspector	
Enfor	cement Number	Address		Filed	Status	Closed	
E190	176	18365 BEVE	ERLY RD	09/12/19	9 Resolved	09/17/19	
	WOOD PALLETS CANNOT BE STORED ON GROUND. TRASH CONTAINER SHOULD BE OUT OF SITE FROM PUBLIC. PLEASE REMOVE FROM AREA.						
	Inspection Type	Status	Result	Scheduled	Completed	Inspector	
_							
Enfor	cement Number	Address		Filed	Status	Closed	
E190	177	18105 BUCK	KINGHAM AVE	09/12/19	9 Resolved	09/25/19	
REM STOI	OVE UTILITY TH	RAILER FRO BE IN FRON	M DRIVEWAY A	LONG WITH	OTHER STO	DRED ITEMS. OUTSIDE E OFF PROPERTY MAY	
	Inspection Type	Status	Result	Scheduled	Completed	Inspector	

Enforcement Number	Address		Filed	Status	Closed			
E190178	30665 STELL	AMAR ST	09/17/19	TICKET	ISSUED			
COLLECTION WILL I BUNDLED IN 3FT LE					PAPER BAGS OR			
RED PONT. AUTO H. PLATE.	AS EXPIRED	PLATES CAN	NOT BE STORE C	ON DRIVE	WAY. NEEDS NEW			
Inspection Type	Status	Result	Scheduled C	Completed	Inspector			
Enforcement Number	Address		Filed	Status	Closed			
E190179	16276 KIRKS	SHIRE AVE	09/17/19	Repaired	09/26/19			
WATER FROM DRIV	WATER FROM DRIVEWAY DOWN SPOUTS NEEDS TO HAVE EXTENSIOSN TO DIVERT WATER TOWARDS STREET AWAY FROM OTHER PROPERTY.							
Inspection Type	Status	Result	Scheduled C	Completed	Inspector			
Enforcement Number	Address		Filed	Status	Closed			
E190180	20070 CORY	ELL DR	09/19/19	Resolved	09/26/19			
WORK TRAILER CAN	NOT BE STC	RED ON DR	IVEWAY. IT CAN	BE STORE	ED IN REAR OPEN YARD			
Inspection Type	Status	Result	Scheduled C	Completed	Inspector			
Enforcement Number	Address		Filed	Status	Closed			
E190181	20201 CORY	ELL DR	09/19/19	Notice Se	ent			
PLEASE REMOVE SM	20201 00111							
GARAGE OK 10 SIC	IALL BOATS A DRE ITEMS. PI			JF HOUSE	E. REAR OPEN YARD OR			
Inspection Type			CODE.	OF HOUSE	E. REAR OPEN YARD OR Inspector			

				0			
Enforcement Number	Address		Filed	Status	Closed		
E190182	31135 W RUT		09/19/19		-		
REMOVE RECREATI	ON TRAILER F	ROM PROP	ERTY CANNOT	BE STOREI	O ON PROPERTY.		
Inspection Type	Status	Result	Scheduled	Completed	Inspector		
Final	Scheduled	00	10/14/19		Dan Gosselin		
Enforcement Number	Address		Filed	Status	Closed		
E190183	16994 KIRKSI	HRE AVE	09/19/19	Closed	09/23/19		
REMOVE TRAILER F			, ,		, ,		
Inspection Type	Status	Result		Completed	Inspector		
Enforcement Number	Address		Filed	Status	Closed		
			09/20/19		09/23/19		
E190186	16932 REEDN				09/23/19		
REMOVE MOTOR HO	JME FROM DF	IVEWAY N	O STOKING ON	DRIVE			
Inspection Type	Status	Result	Scheduled	Completed	Inspector		
Enforcement Number	Address		Filed	Status	Closed		
E190187	31324 FOXBC	RO WAY	09/26/19	Resolved			
DRIVEWAY LOOKS MUCH BETTER, WE NEED TRASH CAN REMOVED FROM BEHIND BUSH.							
PLEASE FEEL FREE	TO CALL TO E	ISCUSS NE	IGHBORHOOD I	SSUES			
Inspection Type	Status	Result	Scheduled	Completed	Inspector		
Enforcement Number	Address		Filed	Status	Closed		
E190188	31505 KENN(09/30/19				
E120100	31303 KEININ	JWATCI	07/30/19	monce se	.111		

1. PLEASE BE ADVISED THAT THE LIGHTS FROM YOUR RESIDENCE IS CAUSING GLARE ONTO A NEIGHBORS PROPERTY. PLEASE SHIELD OR TURN OFF LIGHTS LATE AT NIGHT. EXTERIOR AND INTERIOR LIGHTS. SEC 22.09.050

2. PLEASE REMOVE TREE BRUSH PILIED ALONG WOODED RIVERBANK, BRUSH SHOULD BE BAGGED AND REMOVED FROM PROPERTY. NOT STORED IN PILES

	Inspection Type	Status	Result	Scheduled	Completed	Inspector
Enfor	cement Number	Address		Filed	Status	Closed
E190	189	19777 BEVER	LY RD	10/03/19	Notice Se	ent
PRO ARE WHI	PERTY. THE VILL A OF PROPERTY	LAGE CODE I . THERE INCL TH CONSTRU	DOES NOT UDE TWO	ALLOW FOR ST ORANGE SLIDE	RUCTURES S AND A MI	ONT AREA OF YOUR LCOATED IN FRONT ETAL STRUCTURE ON YAY PLEASE REMOVE
	Inspection Type	Status	Result	Scheduled	Completed	Inspector
Enfor	cement Number	Address		Filed	Status	Closed
E190	190	30400 E LINC	OLNSHIRE	ST 10/09/19	Notice Se	ent
REM COE		OM FIRE HYD	DRANT. ARI	EA. CANNOT BL	OCK FIRE H	IYDRANT. PER FIRE
	Inspection Type	Status	Result	Scheduled	Completed	Inspector
	Final	Scheduled	00	10/10/19		Dan Gosselin
Enfor	cement Number	Address		Filed	Status	Closed
E190	191	31175 DOWN	ING PL	10/09/19) Notice Se	ent
TRA MON	ILERS ARE ALLO	WED ON PRO DULD COMPLE	PERTY. TH ETE YOUR I	E VILLAGE HAS PROJECT. WE CA	ALLOWED	NAL VEHICLES OR THIS TRAILER FOR TEND THE TIEM ANY
	Inspection Type	Status	Result	Scheduled	Completed	Inspector

10/10/19

Dan Gosselin

Final Scheduled 00 10/14/19

Population: All Records

ation: All Records

Enforcement.DateFiled Between 9/1/2019 12:00:00 AM AND 10/10/2019 11:59:59 PM



CANDID COFFEE CHIT CHAT

Please join your state legislators to discuss important issues in our community.

Monday, October 28

6 to 7 p.m.

Beverly Hills Village Hall

18500 13 Mile Road, Beverly Hills, MI 48025





State Senator Rosemary Bayer

SenRBayer@senate.michigan.gov | SenatorBayer.com | (517) 373-2417



Community Office Hours

Community office hours are an opportunity for residents to speak with Senator Bayer and her staff without traveling to Lansing.

To ensure everyone the opportunity to speak privately with the Senator, appointments are strongly encouraged. For an appointment please call our office at (517) 373-2417.

> Monday, October 28 7:15 to 8:15 p.m.

Beverly Hills Village Hall

18500 13 Mile Road, Beverly Hills, MI 48025





State Senator Rosemary Bayer

SenRBayer@senate.michigan.gov | SenatorBayer.com | (517) 373-2417



October 2, 2019

Ms. Kristin Rutkowski, Clerk Village of Beverly Hills 18500 W. 13 Mile Road Beverly Hills, MI 48025

Re: Xfinity TV Channel Updates

Dear Ms. Rutkowski:

We are committed to keeping you and our customers informed with Xfinity TV changes and enhancements. Below we share details regarding new programming that we are launching and the drop of a channel from our line-up.

New Channel Effective October 29, 2019

For our customers who subscribe to the Xfinity Latino package, on October 29 we will begin offering a new Spanish-language channel, Kanal D Drama. Kanal D Drama is a Spanish-language network featuring telenovelas and series. We are communicating this change to our affected customers through a bill message.

Loss of Channel Effective December 5, 2019

We also wanted to inform you that MVStv will be dropped from Xfinity Latino on December 5. We are communicating this change to our affected customers through a bill message.

We are excited about the addition to our robust entertainment offerings and for the opportunity to continue enhancing our Xfinity TV product.

Please feel free to contact me at 734-359-2308 if you have any questions. Please note, this a new phone number for me, update your records accordingly.

Sincerely

Kyle V. Mazurek Manager of External Affairs Comcast, Heartland Region 41112 Concept Drive Plymouth, MI 48170