



Record ID: PR0000899

SWIMMING POOL/SPA Inspection Report

| | | | | | |
|---|--------------------------|---------------------------------------|-----------------------------------|------------------------------------|---|
| Facility Name MJUSD MARYSVILLE HIGH SCHOOL | | Total Violations | 9 | Date: 08/22/2018 | Total Time: 75 |
| Facility Address 2201 RAMIREZ ST | | Total Significant Violations | 1 | Start: 9:30 am | Finish: 10:45 am |
| City/State MARYSVILLE, CA | Zip Code 95901 | Phone (530) 749-6147 | Operator Name MATT HALL | | Operator Phone (530) 701-9625 |
| Program: 0860 - PUBLIC SWIMMING POOL-SPA PERMIT | | Service: ROUTINE INSPECTION | | Result: MINOR VIOLATIONS | |

Fill in the designated compliance status (IN, OUT, N/O, N/A) for each numbered item Fill in the appropriate box for COS and/or R
In = In compliance **OUT** = Not In compliance **N/O** = Not observed **N/A** = Not applicable **COS** = Corrected on-site during inspection **R** = Repeat violation

SWIMMING POOL & SPA

| | | | | | |
|---|-----------------------------|---|------------------------------|------------------------------|------------------------------|
| 1 | Disinfectant Residual (ppm) | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 2 | pH | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 3 | Cyanuric Acid (ppm) | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | <input type="checkbox"/> MAJ |

RECORD KEEPING

| | | | | | | |
|---|---------------------------|---|------------------------------|------------------------------|------------------------------|------------------------------|
| 4 | Inadequate Record Keeping | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 5 | DPD Test Kit | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |

CLARITY

| | | | | | | |
|---|--------------|---|------------------------------|--|------------------------------|------------------------------|
| 6 | Poor Clarity | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
|---|--------------|---|------------------------------|--|------------------------------|------------------------------|

ALGAE

| | | | | | | |
|---|--------------|------------------------------|---|--|--|------------------------------|
| 7 | Algae Growth | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | | | <input type="checkbox"/> MAJ |
|---|--------------|------------------------------|---|--|--|------------------------------|

RECIRCULATION EQUIPMENT

| | | | | | | |
|----|---------------------|---|------------------------------|------------------------------|------------------------------|------------------------------|
| 8 | Pressure Gauges | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 9 | Chlorinator | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 10 | Flowmeter | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 11 | Filter | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 12 | Water Leakage | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 13 | Cleanliness of Area | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 14 | AB1020 Compliant | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |

SKIMMERS

| | | | | | | | |
|----|---------------|---|---|------------------------------|----------------------------|------------------------------|----------------------------|
| 15 | Retarded Flow | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |
| 16 | Weir | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |
| 17 | Basket | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |
| 18 | Skimmer Cover | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |

RESCUE & SAFETY EQUIPMENT

| | | | | | | | |
|----|---------------------------------------|---|---|------------------------------|---|---|---|
| 19 | Rescue Pole with Crook | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 20 | Life Ring with Rope | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 21 | Artificial Respiration Procedure Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 22 | Warning-No Lifeguard on Duty Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 23 | Emergency Phone Number Sign | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input checked="" type="checkbox"/> MAJ |
| 24 | Keep Closed Sign on Gate | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 25 | "No Diving" Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |
| 26 | No Use After Dark Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | <input type="checkbox"/> N/A | <input type="checkbox"/> R | <input type="checkbox"/> COS | <input type="checkbox"/> M |
| 27 | First Aid Kit | <input type="checkbox"/> NVO | <input type="checkbox"/> OUT | | <input checked="" type="checkbox"/> N/O | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 28 | Maximum Occupancy Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 29 | Diarrhea Sign | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 30 | Grab Rail and/or Stair Rail Loose | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | <input type="checkbox"/> N/O | | <input checked="" type="checkbox"/> COS | <input type="checkbox"/> MAJ |

DECK

| | | | | | | | |
|----|----------------------|---|---|--|--|------------------------------|------------------------------|
| 31 | Cracks in decking | <input checked="" type="checkbox"/> NVO | <input type="checkbox"/> OUT | | | | <input type="checkbox"/> MAJ |
| 32 | Obstructions on deck | <input type="checkbox"/> NVO | <input checked="" type="checkbox"/> OUT | | | <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |

| Facility Name | | Date: | Page 2 of 3 |
|--------------------------------|----------------------------------|---|---|
| MJUSD MARYSVILLE HIGH SCHOOL | | 08/22/2018 | |
| SWIMMING POOL & SPA | | | |
| 33 | Inadequate drainage of pool area | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT | <input type="checkbox"/> MAJ |
| BOTTOM DRAIN | | | |
| 34 | Cover Plate VGBA Compliant | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT | <input type="checkbox"/> MAJ |
| 35 | Drain Visible from Deck | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> COS <input type="checkbox"/> M |
| POOL FINISH | | | |
| 36 | Cracks in pool shell | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O | <input type="checkbox"/> MAJ |
| 37 | Rough areas in pool shell | <input type="checkbox"/> NVO <input checked="" type="checkbox"/> OUT <input type="checkbox"/> N/O | <input type="checkbox"/> MAJ |
| DIVING BOARD | | | |
| 38 | Non-slip Surface | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> M |
| 39 | Condition | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> M |
| POOL LIGHT | | | |
| 40 | Non-functioning pool light | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| 41 | Pool Light Separating from Wall | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| TILE | | | |
| 42 | Cracked Tiles | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 43 | Dirty Tiles | <input type="checkbox"/> NVO <input checked="" type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 44 | Depth Markers | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> M |
| CLEANLINESS | | | |
| 45 | Pool Bottom Dirty | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 46 | Floating Debris in Pool | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT | <input type="checkbox"/> COS <input type="checkbox"/> MAJ |
| FENCING | | | |
| 47 | Adequacy of Fencing | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 48 | Gates Self-closing | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 49 | Gates are Self-latching | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/O <input type="checkbox"/> COS | <input type="checkbox"/> MAJ |
| 50 | One Means of Keyless Egress | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT | <input type="checkbox"/> MAJ |
| ANCILLARY FACILITY | | | |
| 51 | Adequacy of Bathrooms | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| 52 | Poor Sanitation of Bathrooms | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| 53 | Structural Defect in Bathrooms | <input type="checkbox"/> NVO <input checked="" type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| 54 | Hot Water Provided in Bathrooms | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| 55 | Poor Sanitation of Showers | <input checked="" type="checkbox"/> NVO <input type="checkbox"/> OUT <input type="checkbox"/> N/A <input type="checkbox"/> R <input type="checkbox"/> N/O | <input type="checkbox"/> M |
| SPA REQUIREMENTS | | | |
| 56 | Spa Temperature | <input type="checkbox"/> NVO <input type="checkbox"/> OUT <input checked="" type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> M |
| 57 | Spa Pool Warning Signs | <input type="checkbox"/> NVO <input type="checkbox"/> OUT <input checked="" type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> COS <input type="checkbox"/> M |
| 58 | Spa Thermometer | <input type="checkbox"/> NVO <input type="checkbox"/> OUT <input checked="" type="checkbox"/> N/A <input type="checkbox"/> R | <input type="checkbox"/> COS <input type="checkbox"/> M |

| Facility Name MJUSD MARYSVILLE HIGH SCHOOL | | Date: 08/22/2018 | Page 3 of 3 |
|--|---|---------------------|-------------|
| VIOLATIONS, OBSERVATIONS AND CORRECTIVE ACTIONS | | | |
| Item No | Remarks | | |
| 1 | Disinfectant Residual (ppm): 1.5 ppm | | |
| 2 | pH: 7.4 | | |
| 3 | Cyanuric Acid (ppm): 35 ppm | | |
| 7 | Algae Growth: Some black algae observed in the shallow end of the pool. | | |
| 16 | Weir: During the 2017 inspection of this pool, the weirs were not installed and we told you that we would waive the requirement for the weirs if you would send a written request for waiver. We have not received a request as of today's date. Please send YCEH a request for waiver of the requirement for emplacement of weirs in the skimmers at this pool. | | |
| 23 | <p>Emergency Phone Number Sign: The pool facility was observed without an EMERGENCY PHONE NUMBER sign. The facility must provide a clearly readable EMERGENCY PHONE NUMBER sign. Correct within 24 hours.</p> <p>SECTION 3120B REQUIRED SIGNS</p> <p>3120B.6 Emergency sign. The emergency telephone number 911, with numbers not less than 4 inches (102 mm), the number of the nearest emergency services and the name and street address of the pool facility, with numbers and text not less than 1inch (25 mm), shall be posted.</p> | | |
| 24 | Keep Closed Sign on Gate: There was a sign on one of the gates, but not the main gate. Matt will move the KEEP GATE CLOSED sign to the main gate. | | |
| 30 | Grab Rail and/or Stair Rail Loose: One of the stair rails was loose. CORRECTED DURING THE INSPECTION | | |
| 32 | Obstructions on deck: Skimmer pads need repair, they continue to deteriorate and are now posing trip hazards. Operator stated that there are plans to paint & reseal the pool this year. The skimmer pads must be repaired when the work to the pool is being done. | | |
| 37 | Rough areas in pool shell: A couple instances of chipping in the pool observed. Per operator, the pool will be repainted this year - make sure these chips do not worsen. If they continue to deteriorate, the pool will need to be resurfaced. | | |
| 43 | Dirty Tiles: Water line tiles at the deep end were dirty. | | |
| 53 | Structural Defect in Bathrooms: One of the toilets on the boys side was loose. | | |
| <p>Overall Inspection Comments:</p> <p><i>Pool and area were very clean & well-maintained. Violations noted were very minor. A re-inspection will be conducted within 30 days.</i></p> <p>**Handicap chair lift was not operational at the time of the inspection (battery was dead)**</p> | | | |
| Received By | | Title: | Date: |
| Inspector JODI BIRD | | EH Technician | 8/22/2018 |