



Yuba County Environmental Health
915 8th Street Suite 123
Marysville, CA 95901
(530) 749-5450

Record ID: PR0002825

Inspection Report

Facility Name Peach Tree Golf and Country Club		Total Violations	3	Date: 05/30/2018	Total Time: 20
Facility Address 2043 Simpson Dantoni RD		Total Significant Violations	2	Start: 11:00 am	Finish: 11:20 am
City/State Marysville, CA	Zip Code 95901	Phone (530) 743-1897	Operator Name MARK NIMRICK		Operator Phone (530) 743-1897
Program: 0860 - PUBLIC SWIMMING POOL-SPA PERMIT		Service: FOLLOW-UP		Result: FAILED TO MEET STANDARDS	

Fill in the designated compliance status (IN, OUT, N/O, N/A) for each numbered item

Fill in the appropriate box for COS and/or R

In = In compliance **OUT** = Not In compliance **N/O** = Not observed **N/A** = Not applicable **COS** = Corrected on-site during inspection **R** = Repeat violation

0 | Gates are Self-latching

VIOLATIONS, OBSERVATIONS AND CORRECTIVE ACTIONS

Item No	Remarks
	Life Ring with Rope: Life ring with rope provided.
	Obstructions on deck: One umbrella & stand is still too close to the pool. There must be 4 feet of unobstructed decking around the entire pool.
	Gates Self-closing: The gate next to the restrooms was standing open during the inspection today. Per pool operator, this gate is supposed to remain closed & locked at all times. Repeat occurrences of this violation will require immediate closure of the pool and possible enforcement.
	Gates are Self-latching: **See comment for "Gates Self-closing"***

Overall Inspection Comments:

A re-inspection will be conducted within 30 days.

Received By JODI BIRD	Title: EH Technician	Date: 5/30/2018
---------------------------------	--------------------------------	---------------------------